


SCE photo log book No. 4 (negatives 18491 - 26127),  
1934-1944  
(photCL SCE, Series 8, Box 2)

Southern California Edison Collection of Negatives and Photographs  
(photCL SCE)  
The Huntington Library



18491	Arden Dairy - Elec. chopper for Silage	10-3-34
18492	" " " " " "	" "
18493	Accident - Wade Walden of 10-17-34	10-24-34
18494	" " " " " "	" "
18495	" " " " " "	" "
18496	" " " " " "	" "
18497	" " " " " "	" "
18498	" " " " " "	" "
18499	" " " " " "	" "
18500	" " " " " "	" "
18501	Accident - Fatal to Cora B Tracy - Olive Ave - Compton	10-29-34
18502	" " " " " "	" "
18503	" " " " " "	" "
18502	" " " " " "	" "
18503	" " " " " "	" "
18504	" " " " " "	" "
18505	" " " " " "	" "
18506	" " " " " "	" "
18507	" " " " " "	" "
18508	" " " " " "	" "
18509	Illumination - Green's Hardware Store - L.B.	11-8-34
18510	" " " " " "	" "
18511	" " " Window	" "
18512	" " " " " "	" "
18513	" - Benjamin's Jewelry St. Windows L.B.	" "
18514	" - Lone Palm Service Station L.B.	" "
18515	Portrait (Copy) Mr. Buffum	12-6-34
18516	Accident - 2nd Pole E. of Avalon on Sepulveda	12-6-34
18517	" " " " " "	" "

18518	" " " " " "	12-6-34
18519	" " " " " "	" "
18520	" " " " " "	" "
18521	Newport Beach - High Tide Damage	12-8-34
18522	" " " " " "	" "
18523	" " " " " "	" "
18524	" " " " " "	" "
18525	" " " " " "	" "
18526	" " " " " "	" "
18527	" " " " " "	" "
18528	" " " " " "	" "
18529	" " " " " "	" "
18530	" " " " " "	" "
18529	" " " " " "	" "
18530	" " " " " "	" "
18531	" " " " " "	" "
18532	" " " " " "	" "
18533	" " " " " "	" "
18534	" " " " " "	" "
18535	" " " " " "	" "
18536	" " " " " "	" "
18537	Accident - Fatal - Roy Johnson - Olive Ave - Compton	12-16-34
18538	" " " " " "	" "
18539	" " " " " "	" "
18540	" Fatal to Roy A Eastman - Miranda - Tejonja Ave - N. Hollywood	12-21-34
18541	" " - Rear of " Car	" "
18542	" " " Car of Eastman	" "
18543	" " " " " "	" "
18544	" " " " " "	" "



18545	Accident - Roy Eastman - His Car	12-21-34
18546	" " - Other Car	"
18547	" " " "	"
18548	" of Harvey Gerber - Transformer	12-24-34
18549	" " " "	"
18550	" " " "	"
18551	Chart - Merchandise Income	12-27-34
18552	" - Power Light	"
18553	" - Total	"
18554	Window Display Setup	12-27-34
18555	" " " "	"
18556	Accident to G.H. Swinheart - Pole 103110M - Alhambra Blvd -	1-5-35
18557	" " " " " "	"
18556	Accident to G.H. Swinheart - Pole 103110M - Alhambra Blvd -	1-5-35
18557	" " " " " "	"
18558	" " " " " "	"
18559	Mill Creek #1 New Automatic Gen. Set up.	1-8-35
18560	" " " " " "	"
18561	" Old Generator	"
18562	" Break in Pressure Main (Collapsed Pipe)	"
18563	" " " " " "	"
18564	" " " " " (Break)	"
18565	" " " " " "	"
18566	Accident - fatal - Gilbert Quichada - Atlantic by Bandini	1-10-35
18567	" " " " " "	"
18568	" " " " " "	"
18569	" " " " " "	"
18570	" " " " " "	"
18571	" " " " " "	"

18572	Chart - KWH per Consumer 1926-34 incl.	1-10-35
18573	Accident - fatal - Clarence Bishop - Tele. Rd + S. Gab. Blvd	1-10-35
18574	" " " "	"
18575	" " " "	"
18576	" " " "	"
18577	" " " "	"
18578	" " " "	"
18579	Five Point Service Station - Night View - Ventura	
18580	Market at Ventura - Night View -	"
18581	Ladies Apparel Shop -	"
18582	Ned Souther Tire Shop -	"
18583	Pole at San Gabriel Blvd + Wells St.	11-16-34
18584	" " " " " "	"
18583	Pole at San Gabriel Blvd + Wells St.	11-16-34
18584	" " " " " "	"
18585	" " " " " "	"
18586	Christmas Tree in Lobby of Edison Bldg -	12-24-34
18587	Window display of DOLLS	12-17-34
18588	Chart of 1934 Advertising - New Business	12-4-34
18589	" " " " - Merchandise	"
18590	Copy of Rose Bowl	12-26-34
18591	Ladder Truck at Genl. Garage	1-20-35
18592	" " " "	"
18593	" " " "	"
18594	" " " "	"
18595	" " " "	"
18596	Test on Steel Tower proposed for Colo R. Transline	1-24-35
18597	" " " " " "	"
18598	" " Wood Poles -	"

18599	Test on Wood Poles proposed for Colo. R. Trans Line	1-24-35
18600	Lighting - Christy's Cafe - Torrance Int.	1-24-35
18601	" " " " " 4t.	"
18602	Accident - Spidler & Cicis - Prairie & Redondo Blvd	1-28-35
18603	" " " " " "	"
18604	" " " " " "	"
18605	" " " " " "	"
18606	" " " " " "	"
18607	" " " " " "	"
18608	Lighting - Hub Cleaners - <del>Before</del> - Inglewood	"
18609	Electric Range operated by Blind Woman	1-29-35
18610	" " " " " "	"
18611	Fire swept area on Mountain above Altadena - (Red Filter)	2-1-35
18610	" " " " " "	"
18611	Fire swept area on Mountain above Altadena - (Red Filter)	2-1-35
18612	" " " " " " - No "	"
18613	View from Top Turnbull Canon	2-1-35
18614	" " " " " "	"
18615	" " " " " "	"
18616	Lighting - Suffin's Store - Huntington Park	2-1-35
18617	Accident - Burrows-Kidder - Newport	2-8-35
18618	" " " " " "	"
18619	" " " " " "	"
18620	" " " " " "	"
18621	" " " " " "	"
18622	" " " " " "	"
18623	" " " " " "	"
18624	Copy of Check for Taxes 1,566.722	2-1-35
18625	" " Met. Water Dist. Float in Pas Parade	"

18626	Accident - Geo R Bisco - Downey Rd & Telegraph Rd.	2-8-35
18627	" " " " " "	"
18628	" " " " " "	"
18629	" " " " " "	"
18630	" " " " " "	"
18631	" " " " " "	"
18632	" " " " " "	"
18633	" " " " " "	"
18634	RANGE - Mrs. Art Smith - Blind Woman	2-12-35
18635	P.E. Steel structure on R. of W. at Bairdstown	2-14-35
18636	" " " " " "	"
18637	Accident - Geo. H. Baker - Altadena - Raymond & Winton	2-15-35
18638	" " " " " "	"
18637	Accident - Geo. H. Baker - Altadena - Raymond & Winton	2-15-35
18638	" " " " " "	"
18639	" " " " " "	"
18640	" " " " " "	"
18641	" " " " " "	"
18642	" " " " " "	"
18643	" " " " " "	"
18644	" " " " " "	"
18645	Accident - Harold Turk - H. Sch. - Compton	2-16-35
18646	" " " " " "	"
18647	" " " " " "	"
18648	" " " " " "	"
18649	Lighting - Lindsey Ripe Olive Co.	2-26-35
18650	" " Hub Cleaners - Inglewood	2-19-35
18651	Elec. Broiler - Rotary	2-25-35
18652	Baby Incubator at Torrance Hospital	2-27-35



18653	Furnace at D. & M. Machine Co. Torrance	2-27-35
18654	Brass Furnace at Hydral Co. Lomita	3-2-35
18655	Testing Machine .. ..	3-2-35
18656	Chart .. ..	3-2-35
18657	Electric Lunch Stand at Farmers Market	3-4-35
18658	" " " " " "	3-4-35
18659	Window Display at Torrance Office	3-4-35
18660	Lower 5 <sup>th</sup> St. Entrance to Edison Bldg.	3-11-35
18661	" " " Interior .. ..	3-11-35
18662	" " " " " "	3-11-35
18663	5 <sup>th</sup> Entrance to Public Library	3-11-35
18664	Hotel St. " " " "	3-11-35
18665	Edison Prop. from Roof - Looking S.E.	3-11-35
18666	note vt. " " " " S.	3-11-35
18665	Edison Prop. from Roof - Looking S.E.	3-11-35
18666	" " " " " S.	3-11-35
18667	View from Engstrom Hotel - Looking S.W.	3-12-35
18668	" " " " " S.E.	3-12-35
18669	L.B.S.P. - Intak damaged by steamship	3-11-35
18670	" " " " "	3-11-35
18671	" " " " "	3-11-35
18672	" " " " "	3-11-35
18673	" " " " "	3-11-35
18674	" " " " "	3-11-35
18675	Elec. Deep Fat Frier - Hunting Park	3-12-35
18676	" " " " " "	3-12-35
18677	Lighting - News Bulletin Florence	3-16-35
18678	" " " " "	3-16-35
18679	" " " " "	3-16-35

18680	Claim - Wires over house in Bellflower	4-2-35
18681	" " " " "	"
18682	" " " " "	"
18683	Lighting - Marisco Paint Co. Windows - H. Park	4-4-35
18684	" " " " "	"
18685	Oil Wells - Pump - at H. Beach	4-9-35
18686	" " " " "	"
18687	" " " " "	"
18688	" " at Seaclyff	4-10-35
18689	" " " " "	"
18690	" " " " "	"
18691	" " " " "	"
18692	" " " " "	"
18693	" " " " "	"
18694	" " " " "	"
18695	" " " " "	"
18696	" " " " "	"
18697	" " " " "	"
18698	" Cont. O. Co. L. Beach	4-15-35
18699	Accident - Todd - Below Culver City	4-18-35
18700	" " " " "	"
18701	" " " " "	"
18702	" " " " "	"
18703	" " " " "	"
18704	" " " " "	"
18705	" " " " "	"
18706	" " " " "	"

18707	Accident - Todd - S.W. of Culver City	4-18-35
18708	" " " "	"
18709	" " The car - "	"
18710	" " " " "	"
18711	" " Jeff. Blvd Looking S.W.	4-23-35
18712	" " " " Nly	4-23-35
18713	" - Jack Chambers - Prairie + Garden St. - Lennox	4-23-35
18714	" " " "	"
18715	" " " "	"
18716	" " " "	"
18717	Edison Bldg + from Grand Ave	5-29-35
18718	" " " " Edwards Library	"
18719	Poultry - Brooder - Visalia	"
18718	" " " " Edwards Library	"
18719	Poultry - Brooder - Visalia	"
18720	Dairy - Refrigeration Machine - Vanderhoan Ro.	4-30-35
18721	" - Milk cooler	"
18722	" - " sterilizer	"
18723	" - Vitamin D Dairy - Bldgs	"
18724	" " " " Ice Machine	"
18725	" " " " Milk Cooler + Bottler	"
18726	Night Photo - Copy - Weaver Jackson	4-25-35
18727	" " " " Oh a	"
18728	Letter - Copy of - Main Drug Store - Visalia	"
18729	" " " " Marisco Paint Co.	"
18730	Night Photo of Gilmore Sta - Fairfax + Beverly Sts	"
18731	" " " " " "	5-7-35
18732	" " Luminous Structures	5-1-35
18733	Interior Drug Store - Visalia	"

18734	Accident - Bennett Clark - Foothill + Baldwin	5-14-35
18735	" " " "	"
18736	" " " "	"
18737	" " " "	"
18738	" " " "	"
18739	" " " "	"
18740	Accident - Hiram Jacqua - Santa Anita + Duarte Rd	5-15-35
18741	" " " "	"
18742	" " " "	"
18743	" " " "	"
18744	Accident - Kenneth Clark - <sup>Car involved</sup> Foothill + Baldwin - 5-8-35	"
18745	" " " "	"
18746	Accident - <del>Hiram Jacqua</del> <sup>Horton + Vagle</sup> - Ocean Ave + Quincy L.B.	5-15-35
18745	" " " "	"
18746	Accident - <del>Hiram Jacqua</del> <sup>Horton + Vagle</sup> - Ocean Ave + Quincy L.B.	5-15-35
18747	" " " "	"
18748	" " " "	"
18749	" " " "	"
18750	Letter - Associated Tel. Co.	5-7-35
18751	Letter - Cal. First Natl. Bank of L.B.	"
18752	Ring Estate - Proposed location for Pole line	5-27-35
18753	" " " "	"
18754	" " " "	"
18755	" " " "	"
18756	Night Photo - Garry + Valley Blvd.	5-20-35
18757	" " " "	"
18758	" " - Ford Dealer - W. Pico	"
18759	" " " "	"
18760	Chart - Milk Cooling	5-25-35



18761	Wild Game Hatchery - Lynwood - 3822 Atlantic	5-24-35
18762	" " " " " "	"
18763	Refrigeration - Palmer Dairy - Compton Dist.	"
18764	" " " " " "	"
18765	" - Poole Dairy " " "	"
18766	" - " " " " "	"
18767	" - " " " " "	"
18768	Accident - W. H. Atkisson - Holt + Peck Aves - El Monte	6-3-35
18769	" " " " " "	"
18770	" " " " " "	"
18771	" " " " " "	"
18772	Bridge at Maywood	6-4-35
18773	" " " " " "	"
18774	Bridge at Maywood	6-4-35
18775	" " " " " "	"
18776	" " " " " "	"
18777	Venture Drug Store - Sign - Day	6-10-35
18778	" " " " " Night	6-10-35
18779	" Play Ground - Day	"
18780	" " " " " Night	"
18781	Santa Paula " " " Day	"
18782	" " " " " Night	"
18783	" " " " " "	"
18784	" " " " " "	"
18785	" " Billiniak Dairy - G. View	"
18786	" " " " " "	"
18787	" " " " " Sw. Bd.	"

18788	S. Paula - Billiniak Dairy - Motor at Pump Plant	6-4-35
18789	" " " " - Old Compressor " "	"
18790	" " " " - New Motor " "	"
18791	Accident - Otto Loeffler - Fuller - Ton	6-20-35
18792	" " " " " "	"
18793	" " " " " "	"
18794	" " " " " "	"
18795	" " " " " "	"
18796	Accident - H. M. Knight - Downey - Firestone -	6-20-35
18797	" " " " " "	"
18798	" " " " " "	"
18799	" " " " " "	7-16-35
18800	" " " " " "	"
18801	" " " " " "	"
18802	" " " " " "	"
18803	" " " " " "	"
18804	" " " " " "	"
18805	" " " " " "	"
18806	" " " " " "	"
18807	" " " " " "	"
18808	" " " " " "	"
18809	" " " " " "	"
18810	L. B. S. P. - Turbo	6-12-35
18811	" " " " " "	"
18812	" " " " " "	"
18813	Redondo " " "	"
18814	" " " " " "	"





18869	Coving Office Exterior (Air Cond)	8-9-35
18870	" " Interior "	"
18871	" " Fan in Attic "	"
18872	Air Conditioned Home of Geo Webb	8-7-35
18873	" " " (Fan) "	"
18874	" " " " "	"
18875	" " " in Hollywood "	"
18876	Copy of Ad gas eng. + pump.	"
18877	Night Photo - Parr Jewellery H. Park	8-5-35
18878	" " - Suffins Dept St. "	"
18879	" " - Wilshire Mart - Bev. Hills	8-8-35
18880	" " - Livingstones - "	"
18881	" " - Curries Ice Cream "	"
18882	L.B. S.P. - Interior Bailer 54	8-17-35
18883	" " - Curries Ice Cream "	"
18884	L.B. S.P. - Interior Bailer 54	8-17-35
18885	" " " " "	"
18886	" " " " "	"
18887	" " " " "	"
18888	" " " " "	"
18889	" " " " "	"
18890	" " " Auto "	"
18891	Lighting - Day - Peterson's Shoes - S. Flng	8-22-35
18892	" " - Night " " "	"
18893	Oil Pumps at Kobe Mfg Co.	7-4-35
18894	" " " " "	"
18895	" " " " "	"

18896	Poultry -	Ro. - H. Park	9-4-35
18897	" " " "	"	"
18898	" Mrs Smith's " - Hawthorne	"	"
18899	" " " " "	"	"
18900	" " " " "	"	"
18901	" " Webb " Bell	"	"
18902	Hot Beds at Orange	"	"
18903	P.R. at school at "	"	"
18904	" " Artesia	"	"
18905	Valley Water Co - Flintridge - Office	"	9-5-35
18906	" " " - 3 Plants	"	"
18907	" " " - Interior P.R.	"	"
18908	" " " " "	"	"
18909	" " " " "	"	"
18908	" " " " "	"	"
18909	" " " " "	"	"
18910	Accident - Gordon Lapasse - L.B.	"	"
18911	" " " " "	"	"
18912	" " " " "	"	"
18913	" " " " "	"	"
18914	Accident - Forrest F Booker - El Monte	"	10-2-35
18915	" " " " "	"	"
18916	" " " " "	"	"
18917	" " " " "	"	"
18918	Accident - Car of Donald Staff - Armandale	"	10-2-35
18919	" " " " "	"	"
18920	Store Front - N. Hollywood -	"	10-11-35
18921	Forest Fire above Altadena - Det. Towers	"	10-23-35
18922	" " " " "	"	"

18923	Altadena Forest Fire + Wind - Fruit on ground	10-22-35
18924	" " " - End of cable	"
18925	" " " Looking E.	"
18926	" " " " E.	"
18927	" " " Replacing x arm on tower	10-24-35
18928	" " " " " " "	"
18929	" " " " " " "	"
18930	" " " Looking E.	"
18931	" " " E. Toward E. side Rubio Canon	"
18932	" " " W " W " " "	"
18933	" " " Cable in burned area	"
18934	" " " " " " "	"
18935	" " " 2nd Trip - Water pipe burn	10-31-35
18936	" " " " " " "	"
18935	" " " 2nd Trip - Water pipe burn	10-31-35
18936	" " " - Cover over reservoir blown in	"
18937	" " " P.P. burned + shield bent on pipe	"
18938	" " " " - Close up	"
18939	Wind Damage in Orange Co. - Mulberry Tree	11-1-35
18940	" " " " - Orange Grove	"
18941	" " " " - Lemon	"
18942	" " " " - Cypress tree down	"
18943	" " " " "	"
18944	" " " " "	"
18945	" " " " "	"
18946	" " " " "	"
18947	" " " " "	"
18948	" " " " "	"
18949	" " " " "	"

18950	Wind Damage in Orange Co.	11-1-35
18951	" " " "	"
18952	" " " "	"
18953	" " " "	"
18954	" " " "	"
18955	Altadena - View from Home of	11-7-35
18956	" " " " Mrs Johnson	"
18957	" " " " Johnson	"
18958	" " " " "	"
18959	" " " " "	"
18960	" " " " "	"
18961	" " " " "	"
18962	" " " " Milkman	"
18961	Altadena - View from Home of	11-9-35
18962	" " " " Milkman	"
18963	Malibu Fire Damage - Where it started	11-9-35
18964	" " " " "	"
18965	" " " " "	"
18966	" " " " "	"
18967	Night Photo - Rubaloffs - N. Hollywood	11-8-35
18968	Altadena Fire Area - As seen from	11-13-35
18969	" " " " "	"
18970	" " " " "	"
18971	" " " " "	"
18972	" " " " "	"
18973	" " " " "	"
18974	" " " " "	"
18975	" " " " "	"
18976	" " " " "	"



18977	Altadena Fire Area - Seen from home of	11-13-35
18978	"	"
18979	"	"
18980	"	"
18981	"	"
18982	"	"
18983	"	"
18984	"	"
18985	"	"
18986	Altadena Fire Area -	11-19-35
18987	"	"
18988	"	"
18989	Malibu " - Along Hi-way	11-29-35
18990	"	"
18989	Malibu " - Along Hi-way	11-29-35
18990	"	"
18991	"	"
18992	"	"
18993	"	"
18994	"	"
18995	"	"
18996	"	"
18997	"	"
18998	"	"
18999	"	"
19000	"	"
19001	"	"
19002	"	"
19003	"	"

19004	Malibu Fire Area	Dec-6-35
19005	"	"
19006	"	"
19007	"	"
19008	"	"
19009	"	"
19010	"	"
19011	"	"
19012	"	"
19013	"	"
19014	Accident - Hole in sidewalk - Compton	Dec 10-35
19015	"	"
19016	Edison Office - Huntington Park	Dec 11-35
19015	"	"
19016	Edison Office - Huntington Park	Dec 11-35
19017	"	"
19018	Malibu Fire Area taken from a boat -	Dec-17-35
19019	"	"
19020	"	"
19021	"	"
19022	"	"
19023	"	"
19024	Kitchen - Portable - at Orange	12-12-35
19025	Home of Dr. A A Harwood Santa Ana - Ext.	12-12-35
19026	"	"
19027	"	"
19028	"	"
19029	"	"

19030	Home of Dr. Harwood - Santa Ana - Powder Room	12-12-35
19031	" " " " - Jun. Truck	
19032	Covina <del>Huntington</del> Post Office	
19033	H. Parker Electric Home - EXT. - Keyes	12-23-35
19034	" " " " - <del>Living Room</del>	"
19035	" " " " - Dining	"
19036	" " " " - Bath	"
19037	" " " " - Kitchen	"
19038	Santa Ana Cit Hall - Exterior	12-12-35
19039	" " " " " "	"
19040	" " " " - Council Chamber	"
19041	Nursery Montebello - Elec. Heating	12-14-35
19042	" " " " " "	"
19041	Nursery Montebello - Elec. Heating	12-14-35
19042	" " " " " "	"
19043	" " " " " "	"
19044	Trailer Repair Shop	12-12-35
19045	" " " " " "	"
19046	Heavy Duty Heating Display	
19047	Dolls -	
19048	Malibu fire Area. Along the coast E. of Latigo	1-14-36
19049	" " " " " "	"
19050	" " " " - Gate - Close up	"
19051	" " " " " "	"
19052	" " " " looking toward gate from up canon	"
19053	Accident - Saw at Gen. Garage (R.C. Finley)	1-16-36
19054	" " " " " "	"
19055	" " " " " "	"
19056	" " " " " "	"

19057	Altadena Fire Area - Copy of Aerial View	1-15-36
19058	" " " " " "	"
19059	" " " " " "	"
19060	" " " " " "	"
19061	Copy of Drawing - 519467	1-20-36
19062	" " " " 519468	"
19063	" " " " 519469	"
19064	" " " " 519495	"
19065	" " " " 519496	"
19066	" " " " 519497	"
19067	" " " " 520658	"
19068	Portrait (copy) F.B. Lewis	1-20-36
19069	Lancaster new office - Sign + Front	1-19-36
19068	Portrait (copy) F.B. Lewis	1-20-36
19069	Lancaster new office - Sign + Front	1-19-36
19070	" " " " - EXT.	"
19071	" " " " - Int.	"
19072	Accident at 38 <sup>th</sup> + Ross E.K. Wood Lumber Co.	1-20-36
19073	" " " " " "	"
19074	" " " " " "	"
19075	" " " " " "	"
19076	" " " " " "	"
19077	Studebaker Plant - Entrance - C.M. Dist.	1-27-36
19078	" " " " - From Roof	"
19079	" " " " " "	"
19080	Edison Trouble man's truck	"
19081	Mr. Reese gets her 25 year button	11-6-35
19082	Bandini Water Co - motor	"
19083	" " " " - Reservoir	"



19084	Altadena Fire Area	1-25-36
19085	" "	"
19086	" "	"
19087	" "	"
19088	" "	"
19089	" "	"
19090	" "	"
19091	Altadena " " Showing Flare on Ridge	1-31-36
19092	" " " " " "	"
19093	Accident at Compton (Boyle Cisco)	2-4-36
19094	" " " "	"
19095	" " " "	"
19094	" " " "	"
19095	" " " "	"
19096	" " " "	"
19097	" " " "	"
19098	" " " "	"
19099	" " " "	"
19100	" " " "	"
19101	" " " "	"
19102	" " " "	"
19103	" " " "	"
19104	" " " "	"
19105	Edison Bldg - from Library Grounds	"
19106	Copy of Letter (Carpenteria Mutual)	"
19107	" " (City & Co. of S.F.)	"
19108	" " F+H Market - Ventura	"
19109	" " U.S. Rubber	"
19110	Sign Bld. Night Light - Bld. 1	"

19111	Copy of Letter (Downtown News)	
19112	" " Ned Souther - Station	
19113	" " Mound Del Mar Schools	
19114	" " Benj. Irving Co.	
✓ 19115	" " Kern Co.	
19116	" " Lindsay Ripe Olives	
19117	" " H.L. J. Perkins Land Co	
19118	" " Horace W. Green + Sons	
19119	" " Christy's - Torrance	
19120	" " Jack Rose Smart Shop - Ventura	
19121	" " O Point Service Station	
19122	" " Morisco Paint Co. H.P.H.	
19121	" " O Point Service Station	
19122	" " Morisco Paint Co. H.P.H.	
19123	" " Suffins Stores "	
19124	" " Lone Palm Service Sta.	
19125	" " Compton Herald	
19126	" " Ventura Drug	
19127	□ Deal Used Car Lot - Night lighted	
19128	" " " " "	
19129	Night light - Al Levey's Tavern	
19130	" " Chapeaux	
19131	Lighting - Modern Tel. T.B.K.	
19132	" " " " + office	
19133	" - Interior Milnery Store	
19134	" - Lemons -	
* 19135	Edison Bldg -	
19136	Diagram - G.E. Elec. Ht. Hot Bed	

✗ 12-28-36

26

19138	Rubber Tire machine - lighted	
19139	" " " "	
19140	Emsco Drafting Room - Old Lighting	2-14-36
19141	" " " "	
19142	Scene of Accident (Aeroplane in line)	2-17-36
19143	" " " "	
19144	" " " "	
19145	" " " "	
19146	Accident - No Hollywood - Employees Car	2-20-36
19147	" " " "	
19148	" " " "	
19149	" " " "	
19148	" " " "	
19149	" " " "	
19150	" " " "	
19151	" " " "	
19152	" " " "	
19153	" " " "	
19154	" " " "	
19155	" " " "	
19156	" " " "	
19157	" " " "	
19158	" " " "	
19159	Roberts Chicken Ranch - Pomona	3-12-36
19160	Bldg. for rent (Bates Valve Bag Corp.)	3-13-36
19161	" " " "	
19162	Chart - Total income Sold 1936	3-11-36
19163	" - Gross Revenue 1935-6	

27

19165	Accident - Auto of E.G. Caverley - Linwood -	2-21-36
19166	" " " "	
19167	" " " "	
19168	" " " "	
19169	Nursery at Montebello	
19170	" " " "	
19171	" " " "	
19172	Malibu Fire Area (Osborne + Sandrager)	3-13-36
19173	" " " "	
19174	" " " "	
19175	" " " "	
19176	" " " "	
19175	" " " "	
19176	" " " "	
19177	" " " "	
19178	" " " "	
19179	" " " "	
19180	" " " "	
19181	Booth at Restaurant Mens Display at Biltmore Hotel	3-18-36
19182	Altadena Fire - Insulator Hanger Assembly -	3-19-36
19183	" " " "	
19184	" " " "	
19185	" " " " Pins	
19186	Malibu Fire Area -	3-25-36
19187	" " " "	
19188	" " " "	
19189	" " " "	
19190	" " " "	



19192	Malibu Fire Area		8-25-36
19193	Accident - of	Altadena	4-6-36
19194	"	"	"
19195	"	"	"
19196	"	"	"
19197	"	"	"
19198	"	"	"
19199	Electric Home of	Barkston - Pasadena Division	3-31-36
19200	"	Chas Washburn	"
19201	"	Douglas	"
19202	"	Jameson	"
19203	"	Nelson	"
19204	"	Nelson	"
19203	"	Nelson	"
19204	"	Nelson	"
19205	"	Mrs Emma Jameson, Sierra Madre	"
19206	"	Nelson	"
19207	"	Douglas Nelson, El Monte	"
19208	"	Miller Douglas	"
19209	"	Isid. O. Miller	4-6-36
19210	"	Jones	"
19211	"	Vallee	"
19212	"	Miller	"
19213	"	Billings	"
19214	"	Billings	"
19215	"	Smith	"
19216	"	Ng Cooper San Marino	"
19217	"	Bassett	"
19218	"	Bush	"

19219	Electric Home of	Schaub - Pasadena Div.	4-6-36 X
19220	"	Scheussler - S. Monica Div. Ber. Hills	4-1-36
19221	"	"	"
19222	"	"	"
19223	"	"	"
19224	"	"	" X
19225	"	Dreier	"
19226	"	"	"
19227	"	Krause	"
19228	"	Tappan	"
19229	"	Stanley Whitworth	"
19230	"	Stanley Whitworth	"
19231	"	"	"
19230	"	Stanley Whitworth	"
19231	"	"	"
19232	"	Lippi	"
19233	"	"	"
19234	"	"	"
19235	"	"	"
19236	"	"	"
19237	Electric Home of	Mrs Henry Bork Maywood	4-7-36
19238	"	"	"
19239	"	Ext. - Mrs Lamb	Montebello
19240	"	Kitchen	"
19241	"	Ext. Mashburn	Whittier
19242	"	Young Wilhoit	La Habra Hts
19243	"	"	"
19244	"	Louis Muchow	"
19245	"	J. B. Fenell	Laguna

19246	Electric Home of F.E. Reinhold	Costa Mesa	4-7-36
19247	All Electric Home of G.E. Co.	Newport	"
19248	Accident at 20 <sup>th</sup> + Olympic - Sawtelle		4-20-36
19249	"	"	"
19250	"	"	"
19251	Oil Wells - Petroleum Security Lease - Santa Paula		4-20-36
19252	"	"	"
19253	"	"	"
19254	"	"	"
19255	" Union Oil Lease	"	"
19256	"	"	"
19257	" Bank Line	"	"
19258	"	"	"
19257	" Bank Line	"	"
19258	"	"	"
19259	Wildcat	"	"
19260	"	"	"
19261	Accident - Venice + Lincoln Blvds - McDonald + Kahn Co		4-15-36
19262	"	"	"
19263	"	"	"
19264	"	"	"
19265	" Maple so. of Mines - Montebello - Frank Soto		4-16-36
19266	"	"	"
19267	"	"	"
19268	" South gate - 9645 Victoria Ave - Incinerator		"
19269	"	"	"
19270	Lighting - at El Rancho Packing House - Riviera		4-16-36
19271	"	"	4-22-36
19272	"	"	4-22-36

19273	Am. Legion - Officers of Edison Post 431		4-22-36
19274	ELECTRIC HOME of W.G. Johnson - Ext. Claremont		4-17-36
19275	"	Living R.	"
19276	"	Kitchen	"
19277	"	Bath R.	"
19278	" Mr. Hoffman - Bloomington - Ext.		"
19279	" Laird - Redlands		"
19280	"	"	"
19281	"	"	"
19282	" (Mr. Barry) San Bernardino		"
19283	" (Mr. Barry) Gift		"
19284	" John Scott (Ext.) Etiwanda		"
19285	" Living Room		"
19284	" John Scott (Ext.) Etiwanda		"
19285	" Living Room		"
19286	" Mrs. Preston Ex Claremont		"
19287	" Living Room		"
19288	" Kitchen		"
19289	" Clinic at San Fernando		4-23-36
19290	"	"	"
19291	"	"	"
19292	" Home of Dodson Redondo		4-14-36
19293	" Dr. P.H. Hawkins Palos Verdes		"
19294	" Mr. Craig		"
19295	"	"	"
19296	" Polhemus Torrance		"
19297	" Letter from C.F. Douglass Jr		4-29-36
19298	Heavy Duty Elec. Equip. Huntington Park H. Sch.		4-27-36
19299	"	"	"



19300	All Electric Bakery at San Bernardino	4-29-36
19301	" Window - <sup>Int.</sup> close up interior	"
19302	" EXT. "	"
19303	" EXT. "	"
19304	All Electric Home of C.E. Dailard - <sup>EXT.</sup> Carpentry	5-1-36
19305	" " " Hall	"
19306	" " " Living Room	"
19307	" " " Bedroom	"
19308	" " " Kitchen	"
19309	" " " Bath room	"
19310	" " " EXT. of W.C. Hohmann	"
19311	" " " Living Room	"
19310	" " " EXT. of W.C. Hohmann	"
19311	" " " Living Room	"
19312	" " " Kitchen	"
19313	" " " Bathroom	"
19314	" " " EXT. - Mr. Loetcher - Hope Ro. S. Barbara	"
19315	" " " Living R. "	"
19316	" " " " "	"
19317	" " " Kitchen	"
19318	" " " Bedroom	"
19319	" " " EXT. Van Rees - Montecito J. Bar.	"
19320	" " " Ed McCaffery - S. Barbara	"
19321	req. returned to Mr. Rivers <sup>1/2/37</sup> R.W. Rivers - Montecito	"
19322	" " " R.C. Robbins	"
19323	" " " Rudolf Fritch	"
19324	" " " Horton Carpentry	"
19325	1936 New Income Chart - Frost	4-36
19326	Re...	5-2-36

19327	Nursery at Montebello Tomato Plants	4-30-36
19328	" " "	"
19329	" " "	"
19330	" " "	"
19331	Scene in Rankin Drama - Stretcher	5-4-36
19332	" " " - Broken hand	"
19333	" " " - Passing out cigars	"
19334	All Electric Home of Ann Harding - S.M. Dist. - Hollywood	5-6-36
19335	" " " Mrs. Dannison - Bev. Hills	"
19336	" " " " "	"
19337	" " " Dr. J.J. Roberts - Pomona	5-12-36
19338	" " " H.V. Bright - La Verne	"
19337	" " " Dr. J.J. Roberts - Pomona	5-12-36
19338	" " " H.V. Bright - La Verne	"
19339	" " " Clarence Byer - Uplands	"
19340	" " " Milton Teague - EXT. Santa Paula	5-20-36
19341	" " " Liv. Rm	"
19342	" " " Din. "	"
19343	" " " Bath "	"
19344	" " " Dr. Mahan - EXT. Oxnard	"
19345	" " " Mr. Neilson - Port. Ht. - Lu. Rm Ventura	"
19346	Lighting - Mecca Cafe - EXT.	"
19347	" " " - Int.	"
19348	" " " - Oasis	"
19349	" " " of Garden of Mr. Arneill Camorilla	"
19350	" " " " "	"
19351	" " " " "	"
19352	" " " " "	"
19353	" " " " "	"

19354	Lighting - Santa Paula Super Market	5-20-36
19355	" " " "	"
19356	" " " "	"
19357	" P + H - Market at Ventura	"
19358	Elec. Shoe Repair Santa Paula	"
19359	Accident to Briggs & Koller - Covina - Spray Tower	5-24-36
19360	" " " "	"
19361	" " " "	"
19362	" " " "	"
19363	" " " "	"
19364	" " " "	"
19365	Lighting - Tunnel at Santa Monica	5-22-36
19366	" " Street " "	"
19365	Lighting - Tunnel at Santa Monica	5-22-36
19366	" " Street " " (Sodium Vapor)	"
19367	" - Home of Merle Norman - Liv. Rm - S. Monica	"
19368	" " " " " "	"
19369	" " " " Dining Rm. " "	"
19370	" " " " Bed Rm. " "	"
19371	" " " " Den " "	"
19372	Oil Wells - Motor & Pump - Edison 27 - Ventura -	5-25-36
19373	" " " " " "	"
19374	" - Portable control at. " "	"
19375	All Electric Home - G. E. Newport - Kitchen	5-27-36
19376	" " " " " "	"
19377	" " " " Bath " "	"
19378	Elec. Hot-bed - El Monte	6-1-36
19379	" " " " " "	"
19380	Elec. Kitchen - Home of N. R. Munger	6-3-36

19381	Elec. Kitchen - Home of D. A. Munger	6-3-36
19382	Copy of letter - of Anderson Boarding & Supply Co. -	6-22-36
✓ 19383	Pumping Plant - Page 1 of Laws Book	6-10-36
✓ 19384	" 2 " "	"
✓ 19385	" 3 " "	"
✓ 19386	" 4 " "	"
✓ 19387	" 5 " "	"
✓ 19388	" 6 " "	"
✓ 19389	" 7 " "	"
✓ 19390	" 8 " "	"
✓ 19391	" 9 " "	"
✓ 19392	" 10 " "	"
✓ 19391	" 9 " "	"
✓ 19392	" 10 " "	"
✓ 19393	" 11 " "	"
✓ 19394	" 12 " "	"
✓ 19395	" 13 " "	"
✓ 19396	" 14 " "	"
✓ 19397	" 15 " "	"
✓ 19398	" 16 " "	"
✓ 19399	" 17 " "	"
✓ 19400	" 18 " "	"
✓ 19401	" 19 " "	"
✓ 19402	" 20 " "	"
19403	" 21 " "	"
19404	" 22 " "	"
19405	" 23 " "	"
19406	" 24 " "	"
19407	" " " "	"



19408	Pumping Plants - Page 26 of "Law's Book"	6-10-36
19409	"	27
19410	"	28
19411	"	29
19412	"	30
19413	"	31
19414	"	32
19415	"	33
19416	"	34
19417	"	35
19418	"	36
19419	"	37
19418	"	36
19419	"	37
19420	"	38
19421	"	39
19422	"	40
19423	"	41
19424	"	42
19425	"	43
19426	"	44
19427	"	45
19428	"	46
19429	"	47
19430	"	48
19431	"	49
19432	"	50
19433	Vernon Brown Residence - EXT.	
19434	E. A. ...	

19435	Accident - Mrs. D. B. Hull - Altadena - Fracker St. 6 - 7-8-36	
19436	"	"
19437	"	"
19438	"	"
19439	Accident - on Aqueduct at Etawanda	7-10-36
19440	"	"
19441	"	"
19442	"	"
19443	"	"
19444	"	"
19445	Auto Accident at San Fernando - Tos. Daws Auto	8-10-36
✓ 19446	"	"
19445	Auto Accident at San Fernando - Tos. Daws Auto	8-10-36
✓ 19446	"	"
19447	"	"
19448	Night Lighting - <sup>Optometrist's</sup> Dentist's office at Downey	8-14-36
19449	"	"
19450	" - Wilshire Oil Co - Norwalk Ext.	"
19451	" Int.	"
19452	" Lab.	"
19453	Com. Dept. Service Trailer + Car	8-26-36
19454	" + Crew	"
19455	" Int.	"
19456	"	"
19457	" Man at bench	"
19458	Vera Ennis gets her 25 year button	8-29-36
19459	Criswell's Cafe - Covina Hi Way	8-28-36
19460	" Interior	"
19461	"	"

19462	Sw. Garden at L.B.S.P.	9-1-36
19463	" " "	"
19464	" " "	"
19465	Pomona Fair Edison Corn Booth	9-19-36
19466	" " "	"
19467	" " "	"
19468	" " Pump display	"
19469	" " "	"
19470	" " "	"
19471	" " Starters	"
19472	" " Poultry Equipment	"
19471	" " Starters	"
19472	" " Poultry Equipment	"
19473	Ward Monument - Enlg'd Copy	9-15-36
19474	Rate Schedule D-1A-Zone C Limited <small>Dulles Exeter Hamford Lindsay Porterville Tulare Visalia</small>	9-29-36
19475	" " " Pg. 2	"
19476	" " " Zone C -	"
19477	" " " "	"
19478	" " L-1 - " C Limited	"
19479	" " " Pg 2	"
19480	" " " 3	"
19481	" " " 4	"
19482	" " " 5	"
19483	" " " 6	"
19484	" " " 7	"
19485	" " " 8	"
19486	" D1-B1 - Zone C " 1	9-29-36
19487	" " 2	"

19489	Rate Schedule - D1-B1 - Zone C - Page 4	9-29-36
19490	" " " " " 5	"
19491	" " D1-B1-C - " C " 1	"
19492	" " " " " " 2	"
19493	" " " " " " 3	"
19494	" " " " " " 4	"
19495	" " " " " " 5	"
19496	" " " " " " 6	"
19497	" " - D1A - Zone A " 1	10-13-36
19498	" " " " " " 2	"
19499	" " " " " Prorate	"
19498	" " " " " " 2	"
19499	" " " " " Prorate	"
19500	" " " " " B 1	"
19501	" " " " " " 2	"
19502	" " " " " Residence	"
19503	Lighting - Pomona School Room	10-12-36
19504	" " " " " "	"
19505	Accident - To Harry Fairweather - E. Mission Rd.	10-13-36
19506	" " " " " "	"
19507	" " " " " "	"
19508	" " " " " "	"
19509	" " " " " "	"
19510	" <del>Mr. Shakaran</del> - Firestone Blvd. Downey	"
19511	" Mrs Shakaran " " "	"
19512	" " " " " "	"
19513	" " " " " "	"
19514	" " " " " "	"



19516	Group of Employees at Visalia Office	10-7-36
19517	Accident - Truck burned at Visalia	"
19518	" " " " " "	"
19519	Air Conditioned - Mirvis Dress Shop Hanford -	10-8-36
19520	" " " " " "	"
19521	" " - Robt. Rice -	"
19522	Peden's Cafe - Ext	"
19523	" " - Int.	"
19524	" " - Machine	"
19525	Cousin's Tractor Co - Ext	"
19526	" " Int	"
19527	Angelo Bank Bldg - Ext.	"
19528	Fox Theater " - "	"
19527	Angelo Bank Bldg - Ext.	"
19528	Fox Theater " - "	"
19529	Clinic - Ext.	"
19530	" - Int.	"
19531	Hospital - Ext	Woodlake 10-6-36
19532	" - Int.	"
19533	E.R. Nash Ext.	Tulare
19534	" Ext + Mach. housing	"
19535	Fox Theater - Ext	"
19536	Edison Bldg - Int	Visalia 10-7-36
19537	" " - Mach.	"
19538	Hyde Theater - Ext.	"
19539	Fox " " "	"
19540	" " - Machine	"
19541	Steel - Architect's Office	"
19542	Petersen's Men's Shop	"

19543	Air Conditioning - Model Dress Shop - Visalia	10-7-36
19544	" " - Dr. Carpenter - Dentist - Porterville	10-8-36
19545	All Electric Home of H. F. Silveria - Hanford	10-5-36
19546	" " " " Living Room -	"
19547	" " " " Kitchen	"
19548	" " " " Harold Schutt - Ext Lindsay	10-8-36
19549	" " " " - Int.	"
19550	" " New City Hall Ext.	"
19551	" " " " Int.	"
19552	" " Home - Geo. G. Cole - Ext Strathmore	"
19553	" " " " Int.	"
19554	" " " Mrs. Kasparian - Ext. Exeter	10-7-36
19555	" " " " - Living Room	"
19554	" " " Mrs. Kasparian - Ext. Exeter	10-7-36
19555	" " " " - Living Room	"
19556	" " " " - Bed	"
19557	" " " " - Kitchen	"
19558	" " " L. L. Dungan - Ext.	"
19559	" " " " Liv. Rm	"
19560	" " " Frank Pinkham - Ext	"
19561	" " " " Int.	"
19562	" " " E. H. Wilson - Ext Woodlake	"
19563	" " " " - <del>KITCHEN</del>	"
19564	" " " E. J. Bodine - Ext Tulare	"
19565	" " " " - Living Room	"
19566	" " " Richard Shannon - Ext	"
19567	" " " " - Living Room	"
19568	" " " " - Kitchen	"
19569	" " " Dr. Mathias - Ext.	"

19570	All Electric Home of Dr. Parkinson - Ext. Tulare 10-7-36
19571	" " " " Marcus Jones - Ext. Porterville "
19572	" " " " Mayor Hammer - Visalia "
19573	" " " " Kitchen " "
19574	" " " " <sup>Dr. W. L.</sup> Mr. Edwards - Ext. " "
19575	" " " " " " Den " "
19576	" " " " " " Bath " "
19577	" " " " " " Strawbridge - Ext. " "
19578	" " " " " " - Living R. " "
19579	" " " " " " - Kitchen " "
19580	" " " " " " Ryder - " " "
19581	" " " " " " Dr. Zeller - Ext. " "
19580	" " " " " " Ryder - " " "
19581	" " " " " " Dr. Zeller - Ext. " "
19582	" " " " " " - Liv. Room " "
19583	LIGHTING - Petersens - Ext - Day " "
19584	" " " " " " Night " "
19585	" " Justesen's Market - Day Porterville 10-6-36
19586	" " " " " " Night " "
19587	" " " " School Athletic Field - Terra Bella " "
19588	" " School Room - Pomona - Elec. Ext. - 10-21-36
19589	" " State Traffic Dept. San Bernardino " "
19590	" " Home of Mrs. " " Kitchen " "
19591	" " " " " " Hall " "
19592	" " Tower Market - Ext. " "
19593	" " " " " " Int. " "
19594	" " The "Cave" " " " "
19595	" " Wilson's Service Station - Redlands " "
19596	" " Shell " " " "

19597	Accident to <del>Willy's</del> Auto* at S. Monica - copy - 10-27-36
19598	" " " " " " " " " "
19599	" " " " Willy's " " 3P-1554 " 10-27-36
19600	" " " " " " " " " "
19601	" " " " " " " " " "
19602	" " " " Ford " " 3P-1444 " "
19603	" " " " " " " " " "
19604	" " " " " " " " " "
19605	Air Conditioning - Copy of letter from Hal's So. Kitchen - 11-20-36
19606	" " " " Sontag's - Wilshire Blvd - Ext - 10-1-36
19607	" " " " " " Int - " "
19608	" " " " Sheets' - " " EX " "
19607	" " " " " " Int - " "
19608	" " " " Sheets' - " " EX " "
19609	" " " " " " Int " "
19610	" " " " Eaton's Steak House " " EXT " "
19611	" " " " " " Int. " "
19612	Oil Well at Vent. Elec. Equipment (Copy @) Driller 5-25-36
19613	" " " " " " Motors " "
19614	" " " " " " Resistance " "
19615	" " " " " " Portable sub " "
19616	" " " " " " C.V. " "
19617	Oil Well Equip. at Long Beach - 11-30-36
19618	" " " " " " " "
19619	" " " " " " " "
19620	" " " " " " " "
19621	" " " " " " " "
19622	" " " " " " " "
19623	" " " " " " " "



19624	Oil Well Equipment at L. Beach	11-30-36
19625	" " " "	"
19626	Wepper Nursery - Inglewood C.U.	11-27-36
19627	" " " "	"
19628	<del>M.G. Set</del> Gas Eng. at Miss. Glass Wks. - Fullerton	12-2-36
19629	Night Janitors of Edison Bldg	12-3-36
19630	Accident - Fatal To Ross Swords - San Bernardino	12-18-36
19631	" " " "	"
19632	" " " "	"
19633	" " " "	"
19634	" " " "	"
19635	" " " "	"
19636	" " " "	"
19637	" " " "	"
19638	Accident - Watkins - 190 <sup>th</sup> St. & Vermont -	12-16-36
19639	" " " "	"
19640	" " " "	"
19641	" " " "	"
19642	Lighting for Schoolroom - demonstration - <sup>L.A. Teachers Inst.</sup>	12-17-36
19643	" " " "	"
19644	" " " "	"
19645	Dolls - in Club Room	12-16-36
19646	" " Window	12-17-36
19647	Night View (Before) Consolidated Rock Co. - office	12-16-36
19648	Chart - Consumers, KWH per - per year	"
19649	Nursery of Toshio Yamabe	10-30-36

19651	Chart - Ind. Power & Lighting (Rates)	12-30-36
19652	" - General Power Rates	"
19653	" Mfg. "	"
19654	" Oil Field "	"
19655	Letter from James Peden - Hanford	"
19656	Copy of Ice Cream Parlor - Visalia	"
19657	" " Stage Setting - Kitchen - old	"
19658	" " " " " new	"
19659	Fit Conditioned - Emerson Mortuary Ext - Redlands	12-30-36
19660	" " " " Int.	"
19661	" " " " Machine "	"
19662	" " " " Int.	"
19661	" " " " Machine "	"
19662	" " + Lighting - Girls Gym - Redlands	"
19663	" " - M.O.D. office	"
19664	" " " " Brooks - San Bernardino	"
19665	" " " " Int.	"
19666	" " Cocktail Room - Cal. Hotel	"
19667	" " Machine " " "	"
19668	Lighting - S. Monica - Jack Posner's Jewellery Store - Ext.	1-4-37
19669	" " " " Int.	"
19670	" " Noonan Hardware - Window	"
19671	" " " " Int.	"
19672	" " Hensley's Dept. Store	"
19673	" " Thrifty Drug "	"
19674	Chart - 220 K.V. Lines - B.C. Plants	"
19675	Ceramic Decorating Co. Kila	1-11-37
19676	" " " "	"

19678	Accident - Santa Barbara - Kimball Ave. Warren Peterson - 1-12-37
19679	" " " " " "
19680	" " " " " "
19681	" " " " " "
19682	" " " " " "
19683	" " " " " "
19684	Oil Well Equipment at Ventura - 1-11-37
19685	" " " " " "
19686	" " " " " "
19687	" " " " " "
19688	" " " " " "
19687	" " " " " "
19688	" " " " " "
19689	" " " " " "
19690	" " " " " "
19691	" " " " " "
19692	Night Lighting - Windows - Farmers Hardware - Whittier 1-14-37
19693	" " Int. " " " "
19694	" " " " " "
19695	" " Sign on door of Architect's Office " "
19696	Accident To Car # 3053 1-15-37
19697	" " " " " "
19698	" " " " " "
19699	" " " " " "
19700	Accident - Edith M. Lightsey - 190 <sup>th</sup> + Western Ave 1-19-37
19701	" " " " " "
19702	" " " " " "
19703	" " " " " "

19705	Accident - Continued - Lightsey 1-19-37
19706	" " " " " "
19707	" " " " " "
19708	Accident - Harold E. Davidson - at 190 St. + Vermont 1-25-37
19709	" " " " " "
19710	" " " " " "
19711	" " " " " "
19712	" " " " " "
19713	" " " " " "
19714	Lighting - East. Out. Co. H. Park - Ext. 1-26-37
19715	" " " " Int 1-28-37
19714	Lighting - East. Out. Co. H. Park - Ext. 1-26-37
19715	" " " " Int 1-28-37
19716	" " " " " "
19717	" " " " " "
19718	" - Consolidated Rock Co. (After alteration) "
19719	" " " " " "
19720	Heat - at Hatch Hatchery - Arcadia (proofer) 2-1-37
19721	" " " " " "
19722	Oil Well - Diagram of Derrick showing method of lighting 2-3-37
19723	Load Chart - 11 KV - Venida Sub - 2-4-37
19724	" " " " " "
19725	" " " " Strathmore " "
19726	" " " " " "
19727	" " " " Terra Bella " "
19728	" " " " " "
19729	" " " " Venice Hill " "
19730	" " " " " "



19732	Load Chart - 11 KV - Lindsay Sub	2-4-37
19733	" " " Porterville "	"
19734	" " " " "	"
19735	Heat - Elec. Melting Pots + Sw. Bd. Compton	2-8-37
19736	" " " " "	"
19737	Edison Elec. Restaurant Exhibit - Int.	"
19738	" " " " "	"
19739	" " " " "	"
19740	" " " " "	"
19741	" " " " EXT	"
19742	" " " " "	"
19743	" " " " "	"
19744	Accident - Darlington - Crystal Cove - Laguna	2-15-37
19743	" " " " "	"
19744	Accident - Darlington - Crystal Cove - Laguna	2-15-37
19745	" " " " "	"
19746	" " " " "	"
19747	" " " " "	"
19748	" " " " "	"
19749	" " " " "	"
19750	" " " " "	"
19751	" " " " "	"
19752	" " " " "	"
19753	" " " " "	"
19754	" " " " "	"
19755	" " " " "	"
19756	" " " " "	"
19757	" " " " "	"
19758	Chart - Annual Sales to Domestic Consumers to 1937	

19759	Electric Kitchen - Mrs Dr Hazwood at Range S. Ana	2-11-37
19760	" " " " " Refrig. "	"
19761	" " of " " " - Lighting only - "	"
19762	" " " " Mrs Merritt - Whittier	2-16-37
19763	" " " " " " "	"
19764	" " Dom. Sci. Dept. Whittier College	"
19765	Sodium Vapor Lighting - S. Monica	2-15-37
19766	Orange Show - Edison Booth	2-18-37
19767	" " " " "	"
19768	" " " " "	"
19769	" " " " "	"
19770	" " " " "	"
19771	" " " " "	"
19772	" " " " "	"
19773	Accident - Tree in yard of Frank Barrow - Inglewood	2-24-37
19774	" " " " "	"
19775	" " " " "	"
19776	" " " " "	"
19777	HEAT - Broiler Cafe - Ontario	3-1-37
19778	Wilshire Oil Co Refinery - Norwalk	3-2-37
19779	Elec. Kitchen - Dom. Sci. Dept - Whittier College	3-1-37
19780	" " " " " " "	"
19781	Lighting - Lane-Wells Co Shop	3-4-37
19782	" " - Curtis Laboratories - H. Park	"
✓ 19783	" " " " " " "	"
19784	" " - Baker Oil Tool Co. (Before) "	"
19785	" " - Woolworth 10 <sup>th</sup> Store - Whittier	3-5-37

19786	Lighting - Woolworth's 10 <sup>th</sup> Store - Whittier	3-3-37
19787	Redondo St. Pl. Boilers being dismantled	3-5-37
19788	" " " " " "	"
19789	Table of wt. of Pipe (Douglas)	3-1-37
19790	" " Loss of Heat in Pipe	"
19791	Newspaper Notice on Shortage of Gas	"
19792	" " prohibiting Diesel Engines	"
19793	Nursery - Soil Heating - Katagawa - S. Monica	3-8-37
19794	" " " " " " 105 <sup>th</sup> + Avalon Blvd	"
19795	" " " " " "	"
19796	Night Lighting - Sodium Vapor - Saugus	"
19797	Office Bldg - New - Alhambra	3-9-37
19798	" " " " " " Saugus	"
19797	Office Bldg - New - Alhambra	3-9-37
19798	" " " " " "	"
19799	RATE Schedule - L-1 - Zone C - S.J. Valley - Outside Car. Areas	3-11-37
19800	" " " " " "	"
19801	" " " " " "	"
19802	" " " " " "	"
19803	" " " " " "	"
19804	" " " " " "	"
19805	" " " " " "	"
19806	" " " " " "	"
19807	" " " " " "	"
19808	" " " " " "	"
19809	" " " " " "	"
19810	" " " " " "	"
19811	" " " " " "	"
19812	" " " " " "	"

19813	Accident - Isabel Bowser - Fatal - Atlantic Firestone	3-11-37
19814	" " " " " "	"
19815	" " " " " "	"
19816	" " " " " "	"
19817	" " " " " "	"
19818	Accident - Arden Rd	3-22-37
19819	" " " " " "	"
19820	Scenic - Trans. Line in Antelope Valley Vincent	3-26-37
19821	" " " " " "	"
19822	" " " " " "	"
19823	" " " " " "	"
19824	" " " " " "	"
19825	" " " " " "	"
19824	" " " " " "	"
19825	Heavy Duty - Mojave - Drive Im <sup>o</sup> Ext.	"
19826	" " " " " " Int	"
19827	" " " " " "	"
19828	" " " " " "	"
19829	Night Lighting - Service Station at Whittier (before)	3-31-37
19830	" " " " " " (After)	"
19831	" " " " " " Street - Garvey - Garfield	4-2-37
19832	" " " " " " - Hunt. Dr + Atlantic	"
19833	Whittier Office - Ext	4-4-37
19834	" " " " " "	"
19835	" " " " " " Int.	"
19836	Steam Table - Heat Regulated	4-5-37
19837	" " " " " "	"
19838	Night Photo - Wisteria Vine at Sierra Madre	4-6-37
19839	" " " " " "	"



19840	Night Fighting - Gertman Market - Monrovia	4-6-37
19841	" " " " " " " "	"
19842	" " " " " " " "	"
19843	" " " " " " " "	"
19844	" " " " " " " "	"
19845	" " " " " " " "	"
19846	Transformers for Magunden. - Loaded, at Vestal	4-8-37
19847	" " " " " " " "	"
19848	" " " " " " " "	"
19849	" " " " " " " "	"
19850	" " " " " " " "	"
19851	" " " " " " " "	"
19850	" " " " " " " "	"
19851	" " " " " " " "	"
19852	" " " " " " " "	"
19853	" " " " " " " "	"
19854	" " " " " " " "	"
19855	" " " " " " " "	"
19856	" " " " " " " "	"
19857	" " " " " " " "	"
19858	" " " " " " " "	"
19859	" " " " " " " "	"
19860	" " " " " " " "	"
19861	" " " " " " " "	"
19862	" " " " " " " "	"
19863	" " " " " " " "	"
19864	" " " " " " " "	"
19865	" " " " " " " "	"

19867	Ambulance for Trans Line (Boulder to Chino)	Ext. 4-7-37
19868	" " " " " " " "	Int. "
19869	" " " " " " " "	"
19870	All Electric Home (Living Room) of Mr Hammer Visalia - Apr-1937	
19871	" " " " " " " "	"
19872	Diesel Eng. Replaced by Motors - Market - Staussen + H. Park	4-12-37
19873	TRANSMISSION Line - Boulder to Chino - clam shovel on Crane	4-14-37
19874	" " " " " " " "	"
19875	" " " " " " " "	"
19876	" " " " " " " "	"
19877	" " " " " " " "	"
19876	" " " " " " " "	"
19877	" " " " " " " "	"
19878	" " " " " " " "	"
19879	" " " " " " " "	"
19880	" " " " " " " "	"
19881	" " " " " " " "	"
19882	" " " " " " " "	"
19883	" " " " " " " "	"
19884	" " " " " " " "	"
19885	" " " " " " " "	"
19886	" " " " " " " "	"
19887	" " " " " " " "	"
19888	" " " " " " " "	"
19889	" " " " " " " "	"
19890	" " " " " " " "	"
19891	" " " " " " " "	"
19892	" " " " " " " "	"

19894	Transmission Line - Boulder to Chino	4-14-37
19895	" " "	"
19896	" " "	"
19897	" " "	"
19898	" " 70 Cat.	4-16-37
19899	" " " "	"
19900	" " Camp quarters at Ludlow	"
19901	" " " " Kelso	"
19902	" " at Boulder Dam - Location for Sw. Garden	"
19903	" " " " - Dam & P.H.	"
19904	" " " " " "	"
19905	" " " From Arizona Side	"
19904	" " " " " "	"
19905	" " " From Arizona Side	"
19906	" " " " " C.V. of Towers	"
19907	" " " The Lake	"
19908	" " " " " "	"
19909	" " Control Room - of Bureau	"
19910	" " " " " "	"
19911	" " " " Edison	"
19912	Core # U1 - from Dam #1 H. Lake	4-29-37
19913	" " " " " "	"
19914	" " " " " "	"
19915	All electric home of L.W. Crosby - Ext.	"
19916	" " " - Liv. Rm	"
19917	" " " - Din. "	"
19918	" " " - Kitchen	"
19919	" " " " Mrs Crosby	"

19921	Core U2 From Dam 1 H.L.	5-3-37
19922	" " " Cl. Up. "	"
19923	" " U3-U4-U5-U6 - Dam 1 - H.L.	"
19924	" " U6-U7-U8- <del>U9</del> - H.L.	"
19925	All Electric Home of Mrs Brooks - Pomona - Ext.	5-5-37
19926	" " " " " Patio	"
19927	" " " " " Living Room	"
19928	" " " " " in Kitchen	"
19929	" " " " " "	"
19930	Broiler Cufe - Ontario - Air Conditioned	"
19931	Elec. Range - Class at Chaffey J.C. - Ontario	"
19932	<del>Broiler Cufe - Ontario - Air Conditioned</del>	"
19931	Elec. Range - Class at Chaffey J.C. - Ontario	"
19932	" " " " " "	"
19933	Night Lighting - <sup>Plenum</sup> Market at S. Monica -	5-6-37
19934	" " " " " "	"
19935	" " " " " Dentist's Office Cecil A. Dickinson	"
19936	" " " " " " " "	"
19937	Accident of Walter Williams on Tower at L.B.S.P.	5-7-37
19938	" " " " " "	"
19939	" " " " " "	"
19940	" " " " " "	"
19941	" " " " " "	"
19942	" " " " " "	"
19943	Accident - J.S. Showers - Fullerton HiWay -	5-16-37
19944	" " " " " "	"
19945	" " " " " "	"
19946	" " " " " "	"





20001	Oil Well - Pump & motor - Associated - Olinda	6-4-37
20002	" - Shell Co - Drilling Rig	"
20003	" " " "	"
20004	" " " " Mud Pumps	"
20005	Heavy Duty - All Elec. Grill - Balboa Herbert Hood	"
20006	" " " " Kitchen	"
20007	" Elec. Ice Cuber	"
20008	" " " "	"
20009	" " " "	"
20010	Elec. Ranges in Inglewood H. School	6-14-37
20011	Group - Salesmen for Pump & Agri. Sup.	6-15-37
20012	Elec. Ranges in Inglewood H. School	6-14-37
20011	Group - Salesmen for Pump & Agri. Sup.	6-15-37
20012	Katella Hatchery - EXT.	"
20013	" " Int	"
20014	" " " "	"
20015	" " Incubators open	"
20016	" " " " closed	"
20017	Albert Osterkamp Dairy - Santa Ana - EXT.	"
20018	" " " " Air Conditioner	"
20019	" " " " P.P.	"
20020	Smith " " - EXT.	"
20021	" " " " Sterilizer	"
20022	Red Day - " " - EXT.	"
20023	H.B. Ro - Huntington Beach - Entrance Gate Sign	"
20024	" " " " New Office Bldg	"
20025	" " " " Feed Mill - Separator	"
20026	" " " " Chopper	"

20028	H.B. Ro - Machine Shop	6-15-37
20029	Oil Well Pump at loading station	"
20030	Seal Beach W.W.S. - Bldg.	"
20031	" " " " Motors & Pumps	"
20032	" " " " - Mayor of Seal B. & Builder	"
20033	Elec. Kitchen with Mrs Hodges Arcadia	6-16-37
20034	" " of " "	"
20035	NIGHT LIGHT of Hiway at - Katella	"
20036	" " " " S. Bldg	6-17-37
20037	" " " " Uplands	"
20038	" " " " Azusa	"
20037	" " " " Uplands	"
20038	" " " " Azusa	"
20039	Accident - Tree Trimmed - Ro. of Pete Poda - Rosemond	6-22-37
20040	" " " " " "	"
20041	" " " " " "	"
20042	" " " " " "	"
20043	Window Light - Hearts Sh. Store - So. Pa. - Before - July-37	"
20044	" " " " " "	"
20045	Accident - Betty McDonald - Guy stub - Parmelee St -	14-37
20046	" " " " " "	"
20047	" " " " " "	"
20048	Copy of Report on Condition of DAMS at H.L.	July-1937
20049	" " " " " "	"
20050	" " " " " "	"
20051	" " " " " "	"
20052	" " " " " "	"
20053	" " " " " "	"



20055	Copy of Report on Condition of DAMS at H.L.	July '37
20056	" " "	"
20057	" " "	"
20058	" " "	"
20059	" " "	"
20060	" " "	"
20061	" " "	"
20062	" " "	"
20063	" " "	"
20064	" " "	"
20065	" " "	"
20066	" " "	"
20065	" " "	"
20066	" " "	"
20067	" " "	"
20068	" " "	"
20069	Den in Home of the Mayor of Visalia	"
20070	Night Photo of "Ford" Store - H. Park	7-14-37
20071	" " " Parr Jewellery Store "	"
20072	" " " " " "	"
20073	Accident - Lillian Waitman - Highgate -	6-21-37
20074	" " " " " "	"
20075	" " " " " "	"
20076	" " " The Transformer	"
20077	Telephone Circuits (3 charts)	7-22-37
20078	All Electric Home <sup>Ext.</sup> - Mrs Cooper - Oak Knoll - San Marino	7.23-37
20079	" " " Liv. Rm	"
20080	" " " Ent. Hall	"
20081	" " " Dining P.	"

20082	All Electric Home - Bed Room - Cooper - San Marino - 7-23-37
20083	" " " Bath Room " " "
20084	" " " Kitchen " " "
20085	" " " " " " "
20086	" " " Demonstration - Santa Ana - 7-26-37
20087	" " " Ext. - Ben W. Baker " " "
20088	" " " Kitchen with Mrs. " " "
20089	" " " Max Elliott - Ext. " " "
20090	" " " " " Kit. " " "
20091	" " " Donald Woodington " " "
20092	" " " Mrs Keys in Kitchen " " "
20093	Accident - Escamilla - Arrowhead 7-28-37
20092	" " " Mrs Keys in Kitchen " " "
20093	Accident - Escamilla - Arrowhead 7-28-37
20094	" " " " " " "
20095	" " " " " " "
20096	" " " " " " "
20097	School Lighting - Before - Torrance 7-22-37
20098	Leave this space
20099	Ramona Sub-Station - Front 8.3.37
20100	" " " " " Side "
20101	
20102	1. Upstream Core Drill Hole Dam 1. U-8 S
20103	- This hole is in column of concrete ne
20104	mix than surrounding concrete on upst
20105	2. Upstream Core drill hole Dam #2. 2-4
20106	3. Upstream face Dam #1 showing conditic
20107	prior to drilling. Taken April 27, 1937
20108	4. Upstream core drill hole Dam #1. U-1.
	5. Core drill hole upstream face Dam 1.
	elevation of any of the 16 holes dri
	Elevation 6930.5. Taken May 14, 1937
	6. Upstream core drill hole Dam #1. U-5
	7. Upstream core drill hole Dam 1. U-14
	between old and new work. Taken May

Small Films

20109

20110

20111

20112

20113

20114

20115

20116

20117

20118

20119

20118

20119

20120

20121

20122

20123

20124

20125

20126

20127

20128

20129

20130

20131

20132

20133

9. Upstream Core Drill Hole Dam #2 2-3 Station 4+60.3 Elev. 6918.0 Taken May 14, 1937.
10. Upstream Core Drill hole Dam #1 U-2 Sta. 11+39.4 Elev. 6898.9. Taken April 29, 1937.
11. Upstream Core Drill Hole Dam 1. U-4 Sta 10+10.5 Elev. 6898.1. Taken April 30, 1937
12. 4" iron pipe drain from tile weeper near east end of 11th. step. Dam 1. Approx. elev. weeper 6900.0 Taken May 30, 1937.
13. Photo showing outlet of 4" drain from the two weepers in rock chimney built up under weeper at easterly end of 11th step. Also shows drain connected directly to weep hole on 11th step. Taken June 3, 1937.
14. 4" iron pipe drain from tile weep hole near east end of 11th step Dam 1. Approx. elev. 6900.0 taken May 30th, 1937.
15. Showing method of connecting intermediate drain into pipe from westerly weeper. 4" pipe drain from two tile weepers into rock chimney. Taken June 3, 1937.
16. 4" pipe drain connecting two tile weepers to West and above tile weeper near east end of 11th step. Dam #1 Taken June 3, 1937.
17. Backfill Dam #3 taken from North end of dam. Taken June 26, 1937.
18. View of backfill dam #3 from south end of dam. Taken June 26, 1937.
19. Backfill Dam #3 taken from North end of dam. Taken June 26, 1937.
20. Dumping backfill material Dam #3 shortly after start of work at that dam. Taken June 4, 1937.
17. Backfill Dam #3 taken from North end of dam. Taken May 29, 1937.
18. View of backfill dam #3 from south end of dam. Taken June 26, 1937.
19. Backfill Dam #3 taken from North end of dam. Taken June 26, 1937.
20. Dumping backfill material Dam #3 shortly after start of work at that dam. Taken June 4, 1937.
21. Sheepsfoot roller in operation Backfill Dam 1 East end. Taken May 29, 1937.
22. View of Backfill East end dam 1. Taken June 4, 1937.
23. Carryall and sheepsfoot working on backfill at east end dam 1. Taken May 29, 1937.
24. Progress of Backfill Dam #1 east end. Taken May 29, 1937.
25. View of Backfill East end Dam 1 also showing work on 4" pipe drain. Taken June 3, 1937
26. Dam 1. View #1 showing exc at upper end of center pipe adjacent to concrete block below former location of valves. Taken June 12, 1937.
27. Dam 1. View #2 showing excavation at upper end of center 42" pipe extension. Taken June 12, 1937
28. Dam 1. View showing excavation for 42" pipes at upper end above wye. Taken June 12, 1937
29. Dam 1. Photo #1 showing cribbing discovered during excavation for west 42" pipe at upper end adjacent to existing concrete. Taken June 13, 1937.
30. Dam 1. Photo #2. Cutting away cribbing found in excavating for foundation under west 42" sluice pipe. At upper end adjacent to existing concrete. Taken June 13, 1937.
31. Dam 1. Exc. for east pipe. at upper end adjacent to existing concrete block below former location of valves. Hole was filled with concrete before forming 12" bearing walls under pipe extension. Taken June 17, 1937.
32. Dam 1. Photo #4. Close-up view of double row of cribbing cut through while excavating for foundation under west 42" sluice pipe extension. Taken June 15, 1937.
33. Dam 1. Showing cribbing cut through while excavating for foundation under upper end west sluice pipe extension. Taken June 15, 1937. Photo #3
34. Dam 1. View of 42" sluice valves showing removal of side concrete walls around valve enclosure prior to removing valves for relocation. Taken June 1, 1937.
35. Dam 1. View showing preliminary excavation with bull dozer at upper end of sluice pipe extension. Taken June 6, 1937.

20136

## LEGEND CONTINUED.

of 42" pipe from west side of canyon. Taken June 25, 1937.

. View of east and west pipe lines of sluice pipe. Taken June 25, 1937

of East and West 42" pipe lines at taken June 29, 1937.

of east 42" pipe in place at upper above wye. Taken June 22, 1937.

of 42" sluice pipe above wye after g east 42" valve into place. Taken June 22, 1937.

g concrete in 12" bearing wall (e View of east 42" pipe in place g foundation mat steel in foreground June 18, 1937.

of excavation for 42" sluice pipe of 12" bearing wall. Taken June 18, 1937.

g foundation for 42" pipe extension June 18, 1937.

of excavation for 42" sluice pipe of 12" bearing wall. Taken June 18, 1937.

g foundation for 42" pipe extension projecting above concrete, Taken g reinforcing steel in foundation June 16, 1937.

g upstream core drill hole 2-1. Station 6+21.4 Elevation 6905.4 Drilling set-up on D7 and D8 - Dam ne set up for drilling core hole May 8, 1937.

machine set-up Hole d-1 Dam #1. er view of drilling 2-2, upstream S. conduit. Taken May 10, 1937.

machine set-up on hole D-13 Dam drilling machine set-up on D-1 D of Keyways between 2nd. and 3rd p two sections of middle pipe in p er view of keyway between 2nd. and - Dam 1. Prior to placing middle .1- View of middle 42" sluice pipe

Murray Co. Conduit - 4" Diameter  
Backfills of P.C. Dams by Stone Webster Co.



20109  
20110  
20111  
20112  
20113  
20114  
20115  
20116  
20117  
20118  
20119  
20120  
20120  
20121  
20122  
20123  
20124  
20125  
20126  
20127  
20128  
20129  
20130  
20131  
20132  
20133  
20134  
20135

9. Upstr
10. Upstr
11. Upstr
12. 4" in
13. Phot
14. 4" in
15. Shot
16. 4" in
17. Bac
18. Vie
19. Bac
20. Dur
21. Sho
22. Vie
23. Cam
24. Pr
25. Vie
26. De
27. De
28. D
29. D
30. D
31. I
32. I
- 33.
- 34.
- 35.

20136  
20137  
20138  
20139  
20140  
20141  
20142  
20143  
20144  
20145  
20146  
20147  
20148  
20149  
20150  
20151  
20152  
20153  
20154  
20155  
20156  
20157  
20158  
20159  
20160  
20161  
20162

## LEGEND CONTINUED.

36. View of 42" pipe from west side of canyon. East and west lines in place. Taken June 24, 1937.
37. Dam 1. View of east and west pipe lines in place. Taken from top pf dam at center line of middle sluice pipe. Taken June 25, 1937.
38. View of East and West 42" pipe lines at lower end after 2nd. pour. Note 6"x3' keyways every 6'. Taken June 29, 1937.
39. View of east 42" pipe in place at upper end and forms for bearing walls center and west lines above wye. Taken June 22, 1937.
40. View of 42" sluice pipe above wye after first section of west pipe was in place. Taken 6/23/37.
41. Moving east 42" valve into place. Taken June 25, 1937.
42. Pouring concrete in 12" bearing wall (east) forms above wye. Taken June 20, 1937.
43. Dam 1. View of east 42" pipe in place above wye. Taken June 22, 1937.
44. Showing foundation mat steel in foreground and portion of mat concrete in background. Taken June 18, 1937.
45. View of excavation for 42" sluice pipe upper end after concrete foundation was poured up to base of 12" bearing wall. Taken June 19, 1937.
46. Showing foundation for 42" pipe extension after pouring 18" mat. Note rock shear keys projecting above concrete, Taken June 19, 1937.
47. Placing reinforcing steel in foundation mat for 42" pipe extension prior to pouring concrete. Taken June 16, 1937.
46. Showing foundation for 42" pipe extension after pouring 18" mat. Note rock shear keys projecting above concrete, Taken June 19, 1937.
47. Placing reinforcing steel in foundation mat for 42" pipe extension prior to pouring concrete. Taken June 16, 1937.
48. Showing upstream core drill hole 2-1. Dam 2. and drilling scaffold on hole 2-2. 2-1 Station 6+21.4 Elevation 6905.4 2-2. Station 6+16.7 Elevation 6909.6. Taken 5/10/37
49. Core drilling set-up on D7 and D8 - Dam 1
50. Machine set up for drilling core hole d-1 downstream face Dam 1. Sta. 9+73.5 Elev. 6812.4 Taken May 8, 1937.
51. Core machine set-up Hole d-1 Dam #1. Taken May 8, 1937.
52. Another view of drilling 2-2, upstream core hole at Dam #2 immediately east of intake to H.P.S. conduit. Taken May 10, 1937.
53. Core machine set-up on hole D-13 Dam #1. Taken June 16, 1937.
54. Core drilling machine set-up on D-1 Dam 1. Taken May 8, 1937. (from above & left of machine)
55. View of Keyways between 2nd. and 3rd pours. Envelope around 42" sluice pipes - Dam 1 First two sections of middle pipe in place - Taken July 1, 1937.
56. Another view of keyway between 2nd. and 3rd. pours, concrete envelope around 42" sluice pipes - Dam 1. Prior to placing middle pipe. Taken July 1, 1937.
57. Dam No. 1- View of middle 42" sluice pipe in place. Camera at upper end. Taken July 1, 1937.

Murray Co. Conduit - 4' Diameter

Progress in backfills of B.C. Dams by Stone Webster Co.



## Back Fills on Dams at H.L. - S+W.

20163	<del>Storm Damage S.H.P. Headworks -</del>	4-
20164	" "	"
20165	" "	"
20166	" "	"
20167	" "	"
20168	" "	"
20169	" "	"
20170	" "	"
20171	" "	"
20172	" "	"
20173	" "	"
20174	" "	"
20175	" "	"
20176	" "	"
20177	" "	"
20178	" "	"
20179	" "	"
20180	" "	"
20181	" "	"
20182	" "	"
20183	" "	"
20184	" "	"
20185	" "	"
20186	" "	"
20187	" "	"
20188	" "	"
20189	" "	"

Small Wall Film

See Page 136 Small Film

20190	Back Fills on Dams at H.L. - S+W.	
20191	" "	"
20192	" "	"
20193	" "	"
20194	" "	"
20195	Guniting Fresno side - Dam 6	9-25-38
20196	" "	"
20197	" "	"
20198	" "	"
20199	Dam 3 - Completed Rock Fill	11-3-35
20200	" "	"
20201	Amalia Sub-Station	8-3-37
20202	" "	"
20201	Amalia Sub-Station	8-3-37
20202	" " Background Blocked Out	"
20203	Office - Huntington Park - Ext. - Night	8-2-37
20204	Poultry Ranch at Redondo - Wagon Wheels	8-11-37
20205	" "	"
20206	" "	"
20207	" "	"
20208	" "	"
20209	" "	"
20210	" " 2 Men	"
20211	All Electric Home of Mr. Uplands - Ext.	8-12-37
20212	" " Ent. Hall	"
20213	" " Liv. Rm	"
20214	" " Kitchen + B.Rm	"
20215	" " " "	"
20216	" " " "	"



20217	Roasting Chickens on Rastisery at Prod. Market.	9-10-37
20218	Home Economist at Citrus Union High School	9-14-37
20219	Boulder Canon Line - 70 Cat. in Lucerne Valley -	8-8-37
20220	" Winding Road - Mile 155-4 To SScl Range "	"
20221	" " " " " "	"
20222	" Compressor MFS - Mi. 148-2	"
20223	" Jackhammer " "	"
20224	" Road looking toward Lucerne "	"
20225	" Sharp's Crew - Mi 147-2	"
20226	" Lava beds + beyond	"
20227	" Dust bowl	"
20228	" Shovel loading Trucks	"
20229	" R5 Spreading dirt	"
20228	" Shovel loading Trucks	"
20229	" R5 Spreading dirt	"
20230	" Lava at Mile 135-2	"
20231	" Tower at 130-1	"
20232	" Adams Grader at Mi. 83-4	"
20233	" Sharp turn in winding road Mi 83	"
20234	" Road from Marl Springs Toward Cima	"
20235	" Gas truck at Boulder City	8-9-37
20236	" Steel yard at " "	"
20237	" Excavation at mi 8-2	"
20238	" Stark Crew at Mi 15-2 Setting Stubs	"
20239	" Setting Footings at Mi 9-2	"
20240	" Byers Clamshell	"
20241	" F.W.D. Boom at Mi 33-1	"
20242	" Back fill at mi - 37	"
20243	" Mechanics Truck # 103	"

20244	Boulder Canon Line - Nipton Camp	8-9-37
20245	" " " F.W.D - Steel Truck "	"
20246	" " " Steel yd. at Cima	9-2-37
20247	" " Erection of tower at 89-4	"
20248	" " " " " "	"
20249	" " Excavation at Mi-0-4	9-3-37
20250	" " " " " 0-3	"
20251	" " Byers Excavating at 180-2	"
20252	" " Excavating at Mi. 172-2	"
20253	Boulder Canon Trans Line - 75 Diesel Cat. - 10-5-37	10-5-37
20254	" Road Bldg - Mile 205-1	"
20255	" Pouring Concrete in Stubs - mi. 176-3	"
20254	" Road Bldg - Mile 205-1	"
20255	" Pouring Concrete in Stubs - mi. 176-3	"
20256	" Byers erecting panel on tower 73+1	"
20257	" Topping off. Tower 74+1	"
20258	" Gin-pole erecting top section	"
20259	" Looking E. along line from 81-3	"
20260	Boulder Line - Pouring concrete for Warehouse - Cima X Road	11-5-37
20261	" " - Cat. pulling 3 cables -	"
20262	" " " 3 "	"
20263	" Splicing Cable	"
20264	" Clamping cable to insulators of Tower	"
20265	" 70' Boom	"
20266	" Road Bldg - Mile 209	"
20267	" Footings in Vineyard 2. of Ontario	11-6-37
20268	Boulder Line - New Footings in Lucerne Valley -	12-6-37
20269	" " - New Warehouse at Pisgah	"
20270	" " - Mine Station 11-1-37	"

- |       |   |         |
|-------|---|---------|
| 20271 | Boulder Line - Camp at Mile 31                      | 12-6-37 |
| 20272 | " " - Test on ground wire                           | 4-7-37  |
| 20273 | " " - Test machine for " "                          | 12 " 37 |
| 20274 | " " - Trimmed trees at Bonview & Schaeffer Chino    | " "     |
| 20275 | " " - Hauling steel up mountain on cable - Mile     | 1-4-38  |
| 20276 | " " - Erecting Tower at Mi. - inaccessible location | " "     |
| 20277 | " " - Transposition Tower - Mile                    | " "     |
| 20278 | " " " " " "   | " "     |
| 20279 | " " " " " "   | " "     |
| 20280 | " " " " " "   | " "     |
| 20281 | " " Eng. on tower checking sag in line              | " "     |
| 20282 | " " " " " " (at " " "                               | " "     |
| 20281 | " " Eng. on tower checking sag in line              | " "     |
| 20282 | " " " " " " (close up)                              | " "     |
| 20283 | " " - Stringing cable - 3 tractors pulling - Mile 3 | " "     |
| 20284 | " " - Unreeling Cable - 3 Reels                     | " "     |
| 20285 | " " " " " " - Close up of reel                      | " "     |
| 20286 | " " Crossing of So. Sierras Line at Mi 21           | " "     |
| 20287 | " " " " " " " "                                     | " "     |
| 20288 | " " " " Bureau                                      | " "     |
| 20289 | " " " " " " " "                                     | " "     |
| 20290 | " " Dead end Tower - Pulling up insulators          | 2-2-38  |
| 20291 | " " " " <sup>270</sup> Showing Jumpers              | " "     |
| 20292 | " " Camp at Sands                                   | " "     |
| 20293 | " " Erecting Tower #141-2 with 70' Boom             | " "     |
| 20294 | " " " " " " " "                                     | " "     |
| 20295 | " " " " " " in vineyard - NE of Ontario             | 2-17-38 |
| 20296 | " " " " " " " "                                     | " "     |

- |       |   |         |
|-------|---|---------|
| 20297 | Boulder Line - Storm Damage at Cajon Steel Yard     | 8-16-37 |
| 20298 | " " " " " "   | 8-16-37 |
| 20299 | " " " " " Rd. To Horse Thief Canon                  | "       |
| 20300 | " " " " " " " "                                     | "       |
| 20301 | Milking machine at G. Van Hummick Dairy, Cypress    | 8-12-37 |
| 20302 | " " " " " "   | "       |
| 20303 | " " " " " "   | "       |
| 20304 | Wagner Trans. That failed                           | 8-16-37 |
| 20305 | " " " " " "   | "       |
| 20306 | " " " " " "   | "       |
| 20307 | NIGHT Photo - Arthur's Jewellery Store - H. Park    | 8-30-37 |
| 20308 | " " " " " "   | "       |
| 20309 | NIGHT Photo - Arthur's Jewellery Store - H. Park    | 8-30-37 |
| 20308 | " " " " " "   | "       |
| 20309 | " " " " " "   | "       |
| 20310 | Night - St. Lt. Sodium Vapor - S. Bar.              | 8-31-37 |
| 20311 | " " " " " "   | "       |
| 20312 | Broaden <sup>G. Brown</sup> on Pickett's Turkey Ro. | "       |
| 20313 | " " " " " "   | "       |
| 20314 | All Elec. Home - Ext. Mrs Loren G. Spivey, S. Paula | "       |
| 20315 | " " " " Kitchen " "                                 | "       |
| 20316 | " " " " - Ext. " " " " " " " "                      | "       |
| 20317 | " " " " Liv. Rm. " " " "                            | "       |
| 20318 | " " " " Kitchen " " " "                             | "       |
| 20319 | " " " " Bath " " " "                                | "       |
| 20320 | " " " " Fly Trap - Mr " " "                         | "       |
| 20321 | " " " " Ext - Mrs - Bairland Jr Carpenteria         | 9-1-37  |
| 20322 | " " " " " Front Ent. " " " "                        | "       |
| 20323 | " " " " " " " " " "                                 | "       |



- 20324 <sup>Post Office</sup> All Electric Home - Mrs Baird - Kitchen - Carpenteria - 9-1-37
- 20325 " " " " " " " " " " " "
- 20326 " " Mrs. <sup>Wm</sup> Archer Ext. S. Barbara " " " "
- 20327 " " Wm Archer in Kitchen " " " "
- 20328 Gas Engine for Sale - at G. Store - Alhambra 9-22-37
- 20329 Portrait (Copy) of Mr Campbell " " " "
- 20330 Pomona Fair - 1937 - Edison Exhibit - Light 9-23-37
- 20331 " " " " - E. End " " " "
- 20332 " " " " Elec. Kitchen " " " "
- 20333 " " " " " " " " " "
- 20334 " " " " Min. Auditorium " " " "
- 20335 " " " " Elec. Eye in Sch. Room - " " " "
- 20336 " " " " Model School Room " " " "
- 20335 " " " " Elec. Eye in Sch. Room - " " " "
- 20336 " " " " Model School Room " " " "
- 20337 " " " " " " " " " "
- 20338 " " " " Genl. Lighting of Main Exhibit Bldg " " " "
- 20339 " " " " Pump Exhibit - " " " "
- 20340 " " " " " " " " " "
- 20341 " " " " " " " " " "
- 20342 " " " " " " " " " "
- 20343 " " " " " " " " " "
- 20344 " " " " " " " " " "
- 20345 " " " " " " " " " "
- 20346 Fairfax Sub 8-6-37
- 20347 Chicken Ro - Smith - S. of Rosecrans Prairie - 8-11-37
- 20348 " " " " " " " " " "
- 20349 " " " " " " " " " "
- 20350 Soil Sterilizer - <sup>Blakesley</sup> Bot. Gardens - S. Bar. 8-24-37

- 20351 Soil Sterilizer <sup>Blakesley</sup> Botanical Gar. S. Bar. - 8-24-37
- 20352 " " " " " " " " " "
- 20353 H.H. Garman Hatchery - Inc. Room - Sat. Coy " " " "
- 20354 " " " " Brooders. " " " "
- 20355 " " " " " " " " " "
- 20356 Prickett Turkeys - Moorpark " " " "
- 20357 " " " " " " " " " "
- 20358 " " " " " " " " " "
- 20359 Copy of Photos of Refill on H. Lake Dams 8-25-37
- 20360 " " " " " " " " " "
- 20361 " " " " " " " " " "
- 20362 Copy of Hydraulic Test Cards Information " " " "
- 20361 " " " " " " " " " "
- 20362 Copy of Hydraulic Test Cards Information 8-25-37
- 20363 " " " " " " " " " "
- 20364 " " " " " " " " " "
- 20365 " " " " " " " " " "
- 20366 " " " " " " " " " "
- 20367 " " " " " " " " " "
- 20368 Copy of old photo of San Antonio P.H. " " " "
- 20369 Clean up Campaign - Back Alley in Santa Paula 8-37
- 20370 " " " " " " " " " "
- 20371 Night Photo - "Before" - Front of Myers Store - Whittier 7-27-37
- 20372 Copy - News P. Clipping re Playground Light that failed 8-10-37
- 20373 " - Proposed xmas Dec. for Pomona Lt. Standards 9-22-37
- 20374 " " Seasons Greetings " " " "
- 20375 Tehachapi Prison - Cooking School - 9-29-37
- 20376 " " " " " " " " " "
- 20377 " " " " " " " " " "

20378	Night photo - Greenwood St. & Whittier - Ext.	10-11-37
20379	" " " " Int.	"
20380	" " " " " "	"
20381	" - Laundry Office " Int from Ex	"
20382	Boulder Trans Line.	10-5-37
20383	" " " "	"
20384	" " " "	"
20385	" " " "	"
20386	" " " "	"
20387	" " " "	"
20388	" " " "	"
20389	" " " "	"
20388	" " " "	"
20389	" " " "	"
20390	" " " "	"
20391	" " " "	"
20392	" " " "	"
20393	" " " "	"
20394	" " " "	"
20395	" " " "	"
20396	" " " "	"
20397	" " " "	"
20398	" " " "	"
20399	" " " "	"
20400	" " " "	"
20401	" " " "	"
20402	" " " "	"
20403	" " " "	"

20405	Boulder Trans. Line	10-5-37
20406	" " " "	10-6-37
20407	" " " - Road - Mile 209	11-4-37
20408	" " " - Splicing cable - Mi-80	11-5-37
20409	Winch on Cat -	11-5-37
20410	" " " "	"
20411	" " " "	"
20412	" " " "	"
20413	All Electric Home of Mrs McDonald - Whittier - Ext.	11-10-37
20414	" " " Liv. Room	"
20415	" " " Bath "	"
20416	" " " Liv. Room	"
20417	" " " Bath "	"
20418	" " " Kitchen	"
20419	" " " at Range	"
20420	" " " Mrs Hansen Pico - Ext. Bath Room	"
20421	" " " Liv. Rm	"
20422	" " " " "	"
20423	" " " Den	"
20424	" " " Bath	"
20425	" " " Brown " EXT.	"
20426	" " " Liv. Rm.	"
20427	" " " at Range	"
20428	Accident to E. Auto #3358 - Menrovia -	11-11-37
20429	" " " " "	"
20430	" " " " "	"
20431	All Electric Home - Hansen - Dining Room - Pico	"



20432	Lighting - Termino Market L.B. - Before	11-10-37
20433	" " " " " "	"
20434	" " " " " After	"
20435	" " " " " "	"
20436	Lamps - OLD <sup>and</sup> NEW (G.E. Collection)	11-17-37
20437	" " " " " "	"
20438	" " " " " "	"
20439	" " " " " "	"
20440	" " " " " "	"
20441	" " " " " "	"
20442	Elec. Furnaces at Aluminum Alloy Casting Co. - H. Park	11-19-37
20443	" " " " " "	"
20444	" " " " " "	"
20445	" " " " " "	"
20444	" " " " " "	"
20445	CHINO Sub - Condenser	11-22-37
20446	" " " " " Control	"
20447	Elec. Range in home of Mrs. Howard Whitties	11-32-37
20448	" " " " " Reynolds	"
20449	" " " " " C.F. Woods	"
20450	" " " " " Kirkwood	"
20451	" " " " " Pickett	"
20452	" " " " " Crum	"
20453	" " " " " Schierman	"
20454	" " " " " Ardis	"
20455	" " " " " Ardis	"
20456	Boulder Line - about mile 45	12-6-37
20457	" " " " " Footings in Lucerne Valley	"
20458	" " " " " Wire Stripping Hitch Mi 36	"

20459	Boulder Line - Trimmed Trees near Chino	12-7-37
20460	Accident - at Pump House - Katella	12-8-37
20461	" " " " " "	"
20462	" " " " " "	"
20463	" " " " " "	"
20464	" " " " " "	"
20465	Heavy Duty - Restaurant - Bev. Hills	12-10-37
20466	" " " " " "	"
20467	" " " " " "	"
20468	Window in Edison Bldg - Santa Claus	12-13-37
20469	Christmas Tree in " -	"
20470	Lighting of Market in Santa Ana	12-16-37
20471	" " Florist Shop " "	"
20473	Lighting of Market in Santa Ana Monrovia	12-16-37
20471	" " Florist Shop " "	"
20472	" " Elec. Fountain - ORANGE	"
20473	BEFORE lighting in Drafting Room of Ad. Boer Co	12-17-37
20474	Lighting in Composing Room - Alhambra Post Office	12-15-37
20475	" " " " " "	"
20476	" " " " " "	"
20477	" " Proof Reading " "	"
20478	Jones Pure Food Store - Ext. Bev. Hills	12-27-37
20479	" " " " " "	"
20480	Xmas Lighting - Bev. Hills - Park on S.M. Blvd.	12-27-37
20481	" " " " " "	"
20482	" " " " " "	"
20483	" " " " " "	"
20484	" " " " " Reindeer in yd.	"
20485	" " " " " Front yard	"

20486	Xmas Lighting - Bev. Hills -	12-27-37
20487	" " " Tree	"
20488	" " " 2 Trees (Helms)	"
20489	" " " Church	"
20490	" " " " "	"
20491	" " " Front Door Way	"
20492	COPIES of County Maps - Key To Index	12-28-37
20493	" " Page A1	"
20494	" " " 1	"
20495	" " " 2	"
20496	" " " 3	"
20497	" " " 4	"
20498	" " " 5	"
20497	" " " 4	"
20498	" " " 5	"
20499	" " " 6	"
20500	" " " 7	"
20501	" " " 8	"
20502	" " " 9	"
20503	" " " 10	"
20504	" " " 11	"
20505	" " " 12	"
20506	" " " 13	"
20507	" " " 14+15	"
20508	" " " Div. VII Road Map	"
20509	P. of W. - Prop. of <sup>En Archibald</sup> Riv. Dr. on Chino Ro. - Boulder Line - 12-37	
20510	" " " Warramaker N.	
20511	" " " So.	
20512	" " " Baumunk -	

20513	P. of W. for Boulder Line - Chino Ro. - Prop. of - Baumunk	12-37
20514	" " " Mantle - near Turner	"
20515	" " " Gemmil - So.	"
20516	" " " - No.	"
20517	" " " Wannamaker Hdqrs	"
20518	" " " Reicher	12-30-37
20519	" " " " "	"
20520	" " " Person	"
20521	" " " " "	"
20522	" " " " "	"
20523	" " " Smith	"
20524	" " " " "	"
20525	" " " " "	"
20524	" " " " "	"
20525	" " " " "	"
20526	" " " " "	"
20527	" " " " "	"
20528	" " " " "	"
20529	" " " Clark	"
20530	" " " " "	"
20531	" " " " "	"
20532	" " " " "	"
20533	" " " " "	"
20534	" " " " "	"
20535	" " " Lewis + Woods	"
20536	" " " " "	"
20537	" " " " "	"
20538	" " " " "	"
20539	" " " So. Side Chino River	"



20540	Night Lighting - Home Xmas Dec. - S. Berdoo	12-30-37
20541	Store " - Newberry's 10 <sup>th</sup> Store -	"
20542	" " " " - Fountain -	"
20543	Dodge Truck on Boulder Line	1-4-38
20544	" " " " " "	1-4-38
20545	Soil Heating - Ventura J.C. - Ext.	1-10-38
20546	" " " " - Int.	"
20547	" " - Dicmer Nursery - Ornard - Int.	"
20548	" " - Tyng " - Ojai - Int.	"
20549	" " " " " "	"
20550	" " " " " Ext.	"
20551	" " - Brown - The Lily man - " "	"
20552	" " - Flaitz - Begonias " Int.	"
20553	" " - Baker Hatchery man - Ornard - " "	"
20552	" " - Flaitz - Begonias " Int.	"
20553	" " - Baker Hatchery - Ornard - Brooder	"
20554	" " " " - Chickens	"
20555	Elec. Kitchen - Mrs - Range - Carpenteria	1-11-38
20556	Diesel Eng. Mira Mar Hotel - S. Bar. - Shut down	1-11-38
20557	" " in Pacific Laundry - S. Bar. -	1-11-38
20558	Home of Mrs - Carpenteria	1-11-38
20559	Accident - J.W. Skidmore - Laguna Canon	1-17-38
20560	" " " " " "	"
20561	" " " " " "	"
20562	" " " " " "	"
20563	" " " " " "	"
20564	" " " " " "	"
20565	RATE Reduction Chart for 1937	1-17-38
20566		

20567	Santa Monica Cam. Office - Interior	1-18-38
20568	" " " " " "	"
20569	" " " " " "	"
20570	" " " " " 2 <sup>nd</sup> Floor	"
20571	Whittier " Ext.	1-20-38
20572	" " Int	"
20573	" " " " " "	"
20574	" Bakery in Whittier - Schmoth	"
20575	" " " " " "	"
20576	" " " " " "	"
20577	" Paving House Murphy Ranch, Whittier	1-25-38
20578	" " " " " "	"
20579	Poultry - Ro. of Mr. <sup>and R.</sup> Richardson - Temple	1-25-38
20578	" " " " " "	"
20579	Poultry - Ro. of Mr. <sup>and R.</sup> Richardson - Temple	1-25-38
20580	" " " " " "	"
20581	" " " " " Incubator Room	"
20582	" " " " " New chicks	"
20583	" " " " " Brooders	"
20584	" " " " " Mixer	"
20585	" " Mr. Calvin Smith - Arcadia - Incub. Room	"
20586	" " " " " Brooder	"
20587	" " " " " Feeding Chickens	"
20588	" " " " " Bringing in the eggs	"
20589	" " " " " " "	"
20590	Lighting - Arthur's Jewelry Store - San Bernardino - Ext.	1-24-38
20591	" " " " " "	"
20592	" " " " " Int.	"
20593	" " " " " "	"



20594	Lighting - Arthur's Jewelry Store - San Bernardino - Int.	1-28-38
20595	" - Leeds Shoe Store " Ext.	"
20596	" " " " " "	"
20597	" " " " " Int.	"
20598	" Library - San Bernardino - Before - 1st Floor	"
20599	" " " " " Basement	"
20600	" " " " " 1903 - Copy	"
20601	Lighting - Used Car Lot - H. Park	1-27-38
20602	" " " " " "	"
20603	" " " " " "	"
20604	" " " " " "	"
20605	" " " " " "	"
20606	Boulder Line - 70' Boom at Tower 141.2	2-3-38
20605	" " " " " "	"
20606	Boulder Line - 70' Boom at Tower 141.2	2-3-38
20607	" " " - Jumpers " Tower 70+	2-2-38
20608	" " " - Dead end Tower - Raising Insulators	"
20609	Lighting in Orange Packing House - Redlands	2-7-38
20610	" " " " " " "	"
20611	Map of L.A. Harbor - Copy for R. of W. Dept	2-8-38
20612	" " " " " " "	"
20613	Accident - Wassell - Myetta - Pole #51720 - Avalon 165 <sup>th</sup> St.	2-8-38
20614	" " " " " " "	"
20615	" " " " " " "	"
20616	" " " " " " "	"
20617	" " " " " " "	"
20618	Poultry Ro. - Copy of Aerial View - Arcadia	Jan-38
20619	" " " " " " "	"
20620	Supt. + Assistants of Trans. Dept.	2-25-38

20621	Poultry - Brooders at Hatch Hatchery - Arcadia	2-2-38
20622	" - Pike-Krenz Hatchery " "	"
20623	" - Mr. Krenz at " "	"
20624	" " " at Temple	"
20625	" " " " " "	"
20626	" <del>Mr. Krenz</del> - Richardson Hatchery - Temple - Inc.	"
20627	" " " " " - Chicks	"
20628	" " " " " - Sorting	"
20629	" " " " " " "	"
20630	" " " " Cocksells in Tree	"
20631	Condenser at Santa Barbara	3-1-38
20632	Lighting - Lemon Packinghouse - Ormand	5-1-38
20633	" " " " " "	"
20632	Lighting - Lemon Packinghouse - Ormand	5-1-38
20633	" " " " " "	"
20634	Heavy Duty - Betty's Icecream Parlor - Ventura	"
20635	" " " " " "	"
20636	Storm Damage of Mar. 2 <sup>nd</sup> - Line burned down at Saugus - Gas Main Break	3-4-38
20637	" " " " " "	"
20638	" " " " " "	"
20639	" " " " " "	"
20640	" Tower " Leaning - Castaic	"
20641	" " " " " "	"
20642	" Tower on K.R. Line in Land Slide	"
20643	" " " " " "	"
20644	" H Frame on Rio Bravo	3-7-38
20645	" H " at H. Drive - San Gabriel	"
20646	" " " " " "	"
20647	" Tower on McNeil to Sherman Line + River	"



20648	Storm Damage of Mar. 2 <sup>nd</sup> - N. Hollywood	3-7-38
20649	" " " "	"
20650	" " Kern Line down N. of McNeil	"
20651	" " " "	"
20652	" " " "	"
20653	Storm Damage - San Antonio Canon - <sup>Cent #2 PH</sup> Sierra #3 - Hawks	3-10-38
20654	" " " " - W. W. Gen.	"
20655	" " " " " "	"
20656	" " " " " "	"
20657	" " " " <sup>Sierra PH River Ditch</sup> Remains of Dam	"
20658	" " " " Sierra #2 - P.H.	"
20659	" " " " " "	"
20660	" " " " " Interior	"
20661	" " " " " "	"
20660	" " " " " Interior	"
20661	" " " " " <del>Roof</del> Interior	"
20662	" " " " " Roof	"
20663	" " " " Operators Cottage	"
20664	" " " " " "	"
20665	" " " " " <sup>5013 Club</sup> Girls Dormitory	"
20666	" " " " " <sup>5013 Club</sup> Married folks Cabin	"
20667	" " " " Relief Operators	"
20668	" " Fontana - Pressure Line	3-11-38
20669	" " Lytle Creek Wash + P.H.	"
20670	" " " " Crossing -	"
20671	" " Mill Creek #1 P.H. Evt.	"
20672	" " " " Int.	"
20673	" " " " " "	"
20674	" " " " " "	"

20675	Storm Damage - Mill Creek #1 - <sup>Showing new channel</sup> G. V. <sup>Antenna PH</sup>	3-11-38
20676	" " " " Penstock washed out	"
20677	" " " " " "	"
20678	" " " " " seen from M.C. 3	"
20679	" " " " " "	"
20680	" " S. P. R. #3	3-12-38
20681	" " " "	"
20682	" " " "	"
20683	" " " "	"
20684	" " " "	"
20685	" " " "	"
20686	" " " "	"
20687	" " " "	"
20686	" " " "	"
20687	" " " "	"
20688	" " Cotton Sub	3-12-38
20689	" " Cotton Sub	"
20690	" " Stringing Wires in San Antonio Canon	"
20691	" " Mill Creek Hawks - Looking down canon	3-26-38
20692	" " " " " Nly. across	"
20693	" " " " " Pipeline on S. side of canon	"
20694	" " " " " Below sand box looking Ely.	"
20695	" " " " " So. of " " "	"
20696	" " " " " Up canon - site of Hawks	"
20697	" " " " " Looking Sly. across site of bridge	"
20698	" " " " " at front gate of cottages	"
20699	" " " " " Remains of gates + screen	"
20700	" " " " " Where it was	"
20701	Boulder Line - Stringing Ground Wire near Old Dad	3-15-38

Boulder Line

20702	Boulder Line - Clipping in Ground Wire on top of Tower	3-15-38
20703	" " " " " " " "	"
20704	" " - Lakes + Line in Lucerne Valley (East)	"
20705	" " " " " " (West)	"
20706	" " " " " " " "	"
20707	" " Footing washed out at Lytle Creek	3-11-38
20708	" " Bird Guards on Tower	3-15-38
20709	Boulder Line - Horsethief Canon - Main hi-way washed out	4-7-38
20710	" " - Lytle Creek - Looking Ely	"
20711	" " - Crossing Foot Hill Blvd	"
20712	" " " S. Fe. RR at Etowanda	"
20713	" " Snubbed on snubs	"
20714	" " Tie-in To Chino Sub	"
20715	" " Snubbed on snubs	"
20716	" " Tie-in To Chino Sub	"
20717	Boulder Line - Hardware	5-3-38
20718	" " " " " " " "	"
20719	Boulder Line - Reeling in discarded ground wire	6-2-38
20720	" " " " " " " "	"
20721	" " - C.V. of reeling mechanism (side)	"
20722	" " " " " (Top)	"
20723	" " Road Sign at intersection	"
20724	" " Gates at RR Crossing	"
20725	" " Danger sign on Tower	"
20726	" " Crossing S.F. at Blue Cut Cajon Pass	6-3-38
20727	" " " " " " " "	"
20728	" " Connections at Chino	8-10-38

20729	Boulder Line - Vibration Test on Tower	8-10-38
20730	" " - Footings of Tower in Dry Lake - Lucerne Valley	"
20731	" " - Transposition Tower	"
20732	" " " " " " " "	"
20733	" " " " " " " "	"
20734	Florence Lake Dam Arch #6, after intrados inspection	Mar. 1940
20735	" " " #7 " " " "	"
20736	" " " #8 " " " "	"
20737	" " " #9 " " " "	"
20738	" " " #10 " " " "	"
20739	" " " #11 " " " "	"
20740	" " " #12 " " " "	"
20741	" " " #13 " " " "	"
20742	" " " #12 " " " "	"
20743	" " " #13 " " " "	"
20744	" " " #12 " " " "	"
20745	" " " #13 " " " "	"
20746	" " " "Base of" #12 & 13 " " " "	"
20747	" " " #14 " " " "	"
20748	" " " #15 " " " "	"
20749	" " " #16 " " " "	"
20750	" " " #17 " " " "	"
20751	" " " #19 " " " "	"
20752	" " " #20 " " " "	"
20753	" " " #24 " " " "	"
20754	" " " #25 " " " "	"
20755	" " " #26 " " " "	"
	" " " #27 " " " "	"
	" " " #28 " " " "	"
	" " " #29 " " " "	"
	" " " #30 " " " "	"



20756	Florence Lake Dam - Arch #31, after estrados inspection	Mar. 1940
20757	" " " #32 " " "	"
20758	" " " #33 " " "	"
20759	" " " #34 " " "	"
20760	" " " #35 " " "	"
20761	" " " #36 " " "	"
20762	" " " #37 " " "	"
20763	" " " #38 " " "	"
20764	" " " #39 " " "	"
20765	" " " #40 " " "	"
20766	" " " #41 " " "	"
20767	" " " #42 " " "	"
20768	" " " #43 " " "	"
20767	" " " #42 " " "	"
20768	" " " #43 " " "	"
20769	" " " #44 " " "	"
20770	" " " #45 " " "	"
20771	" " " #46 " " "	"
20772	" " " #47 " " "	"
20773	" " " #48 " " "	"
20774	" " " #49 " " "	"
20775	" " " #50 " " "	"
20776	" " " #52 " " "	Lower part
20777	" " " #53 " " "	"
20778	" " " #54 " " "	"
20779	" " " #55 " " "	"
20780	" " " #56 " " "	"
20781	" " " #57 " " "	"
20782	" " " #58 " " "	"

20783	Florence Lake Dam - View of 1 <sup>st</sup> & 2 <sup>d</sup> tangents, after estrados inspec.	Mar. 1940
20784	" " " Frog Pond section, Arch. 11 to 21, after estr. insp.	"
20785	" " " River Tangent after estrados inspection	"
20786	" " " Inspecting estrados surface of Arch #9	"
20787	" " " Close up of Arch 12	"
20788	" " " " " " 13	"
20789	" " " " " " 14	"
20790	" " " " " " #15	"
20791	" " " " " " #16	"
20792	" " " " " " #17	"
20793	" " " 6" cores drilled from estrados surface of Arch #12	"
20794	" " " 6" " " " " " #13	"
20795	" " " 6" " " " " " #14	"
20794	" " " 6" " " " " " #13	"
20795	" " " 6" " " " " " #14	"
20796	" " " 6" " " " " " #15	"
20797	" " " 6" " " " " " #16	"
20798	" " " 6" " " " " " #17	"
20799	" " " Drilling 6" core from staging estrados " #16	"
20800	" " " Close up of drilling 6" cores on estrados surf. #15	"

P. 92

- 20801 Chapman's Chinchilla Farm, Inglewood - Fluoroscope use 11/37  
 20802 " " " " - Gen. View " "  
 20803 " " " " - Building pen " "  
 20804 Tank Farming - Electric cable heat. Inspecting roots 11/37  
 20805 " " " " " " " " " "  
 20806 " " " " " " - Picking fruit " "  
 ✓20807 Electric metal melting pot, Lancaster Gazette 12/37  
 20808 Edison doll dressing contest - winners 12/37  
 20809 " " " " " " " " " "  
 20810 " " " " " " Inspecting dolls " "  
 20811 " " " " " " " " " "  
 20812 Christmas Lighting, Deodar Lane, Altadena 12/37  
 20817 " " " " " " " " " "  
 20812 Christmas Lighting, Deodar Lane, Altadena 12/37  
 ✓20813 " " Lehman home, San Marino " "  
 ✓20814 " " Forsythe home, " " " "  
 ✓20815 " " Ivey home " " " "  
 20816 " " Ramp home, Alhambra " "  
 20817 " " Shennadoh Road, San Marino " "  
 20818 " " Perry home, Alhambra " "  
 ✓20819 " " Corser home, Altadena " "  
 ✓20820 " " Shubaker home, Alhambra " "  
 20821 " " Case home, Alhambra " "  
 ✓20822 " " Fleming home, San Marino " "  
 20823 (Staub's Exotic Hall) Pump testers at Firsick Bros. Lancaster - Arrive on scene 12/37  
 20824 " " " " - Drilling " "  
 20825 " " " " - Flowmeter test " "  
 20826 " " " " - Airline test " "  
 ✓20827 " " " " - Pressure test " "

- 20828 " " " " Pump speed test " "  
 ✓20829 " " " " Power test " "  
 ✓20830 " " " " Computations in office " "  
 ✓20831 Two-for-one specials. Waffle iron + servers 1/38  
 20832 " " " " Proctor iron " "  
 ✓20833 " " " " Hewitt heat pad " "  
 20834 Lineman Woods & bag Kite flyers 2/38  
 20835 " " " " " " " "  
 20836 " " " " " " " "  
 20837 " Carl " " " "  
 20838 " " " " " " " "  
 20839 Neil Schroth & electric bakery proof box 2/38  
 20838 " " " " " " " "  
 20839 Neil Schroth & electric bakery proof box 2/38  
 20840 " " " " " " " "  
 20841 " " " " " " " "  
 20842 " " " " " " " "  
 20843 Viz-o-Lite house number on porch 2/38  
 20844 R. G. Kenyon at desk 2/38  
 20845 " " " " " " " "  
 20846 " " " " " " " "  
 20847 Model, Lyons frost warmer 2/38  
 20848 Messrs. Frost & German, Achievement award 2/38  
 20849 " " " " " " " "  
 ✓20850 Clyde Alling - Drying room, Venetian Blind Co. Colver City 2/38  
 ✓20851 Loading " " " " " " " "  
 ✓20852 Mr. Trandly - Rinsing Tank, T-P Metal Products - Colver City 2/38  
 20853 " - Sandust Box " " " " " "  
 ✓20854 " " " " " " " "







20901	Air Conditioning - Pines Coffee Shop (Sign) Arcadia	3-18-38
20902	" " " " Int. "	"
20903	" " - Abbott's " Ext. - Monrovia	"
20904	" " " " Int. "	"
20905	" " " " Bar "	"
20906	" " - Pat's " Ext. "	"
20907	" " " " Int. "	"
20908	" " - Flynn's Grill - Ext. San Fernando	"
20909	" " " " Int. "	"
20910	" " " " Bar "	"
20911	" " " " " "	"
20912	" " - Ronnie's Theater - "	"
20911	" " " " " "	"
20912	" " - Rennie's Theater - "	"
20913	" " Home Builders Loan Co Pomona	24
20914	" " " " " "	"
20915	" " Owl Drug Store Ext. "	"
20916	" " " " Int. "	"
20917	" " Co. Fair Ad. Bldg. Ext. "	"
20918	" " " " Int. "	"
20919	" " Swing Bldg Ext. S. Berdoo	"
20920	" " Am. Nat'l. Bank Ext. "	"
20921	" " " " Int. "	"
20922	" " Bank " "	"
20923	" " Mapes Cafeteria " "	"
20924	" " " " Banquet Room "	"
20925	" " George's Cafe Ext. "	"
20926	" " Bankers Club Ext. "	"

20928	Heavy Duty - Elco Cafeteria - Long Beach	
20929	" " " " " "	
20930	" " " " " "	
20931	" " " " " "	
20932	Storm Damage of Mar 2 <sup>nd</sup> MC # 3 Hdws	3-26-38
20933	" " Mt. Home Cr. intake for MC 2	3-27-38
20934	" " " " " "	
20935	" " MC # 2 Hdws	
20936	" " " " " "	
20937	" " " " " "	
20938	" " " " " "	
20939	" " Looking down on MC Wash -	
20938	" " " " " "	3-28-38
20939	" " Looking down on MC Wash -	
20940	Storm Damage of Mar. 2 - Lytle Creek Hdws. G.V. from SE	3-30-38
20941	" " " " Sand-box	
20942	" " " " Cottages	
20943	" " " " " "	
20944	" " " " Intake	
20945	" " " " " "	
20946	" " " " Looking E. from intake	
20947	Storm Damage of Mar. 2 <sup>nd</sup> at S.H.R. 2 - G.V. from hill	
20948	" " " " " So.	
20949	" " " " " W.	
20950	" " " " " S.W.	
20951	" " " " Leaf screen + tunnel entrance	
20952	" " " " P.H. Int.	
20953	" " " " " "	
20954	" " " " " "	



20955	Storm Damage of Mar. 2 <sup>nd</sup> S.A.R. <sup>2</sup> Broken flumeline & tunnel	3-30-38
20956	" " " " " "	"
20957	" " " " Byers Shovel crossing bridge	"
20958	Display - Edison Booth at Orange Show	"
20959	" " " " " "	"
20960	" " " " Metals Congress - Pan-Pac Ex Bldg.	3-23-38
20961	" " " " " " " "	"
20962	" " " " " " " "	"
20963	" " " " " " " "	"
20964	" " " " " " " "	"
20965	Linotype at Puente (Shoop)	3-24-38
20966	Window Display - Edison Bldg.	4-6-38
20967	Linotype at Puente (Shoop)	3-24-38
20966	Window Display - Edison Bldg.	4-6-38
20967	CHART - Industrial Power & Lighting	"
20968	" " " " Oil Field Power	"
20969	" " " " Manufacturing Power	"
20970	" " " " General	"
20971	Night Lighting Market at 98 <sup>th</sup> & L.B. Blvd	4-4-38
20972	" " " " + Theater	"
20973	" " " " " "	"
20974	Chart - Annual Sales to Domestic Consumers	Jan 38
20975	" " " " " "	"
20976	" " " " " "	"
20977	" " " " Gross Revenue	"
20978	" " " " Total new income sold	"
20979	" " " " Employee's Notice	"
20980	Gen. M. Auto Assembly Plant - Copy	"
20981	R. of W. - Sign Boards on Valley Blvd.	3-20-38

20982	R. of Way - Sign Board on Valley Blvd.	3-20-38
20983	" " " " In Industrial Dist	"
20984	" " " " " "	"
20985	" " " " " "	"
20986	" " " " " "	"
20987	" " " " " "	"
20988	" " " " " "	"
20989	" " " " " "	"
20990	" " " " " "	"
20991	" " " " " "	"
20992	" " " " " "	"
20993	" " " " " "	"
20992	" " " " " "	"
20993	" " " " " "	"
20994	" " " " " "	"
20995	" " " " " "	"
20996	" " " " " "	"
20997	" " " " " "	"
20998	" " " " " "	"
20999	" " " " " "	"
21000	" " " " " "	"





21055	Storm Damage - Storm of Mar 2nd S.A.R.I. Headworks - 4-22-38
21056	" " " " " "
21057	" " " " " "
21058	" " " " " "
21059	" " " " " "
21060	" " " " " "
21061	" " " " " "
21062	" " " " " "
21063	" " " " " "
21064	" " " " " "
21065	" " " " " "
21066	" " " " " Mr. & Mrs. Brewer
21067	P. L. 11 Plant at Long Beach 4-25-38
21068	" " " " " Mr. & Mrs. Brewer
21069	Proctor 4 Gambol Plant at Long Beach 4-25-38
21070	Flr Cond. - Portable Unit - in office (Moore)
21071	" " " " " cat. shot
21072	" " " " " G.E.
21073	" " " " " Industrial
21074	Pumping Plant - Foothill Irrigation Co. 4-27-38
21075	" " Int. with Mr. " "
21076	" " off W.C. - Showing Weir
21077	" " " " Foothill Irrigation Co. Reservoir
21078	" " " " - Ext. La Verne Water Assn.
21079	" " " " - Int. with Mr. Davis
21080	* 21078 " " " " - Ext
21081	" " " " " "
21082	" " " " " Motor
21083	* 21081 " " " " " "

21082	Garden Lighting - Dr. H. W. Adams Puente 4-27-38
21083	" " Day " " "
21084	" " Night " " "
21085	" " " " " "
21086	Safety - Cops making Charleston wall at S. Ave 5-4-38
21087	" " " " " "
21088	Claim - Tree topped on C.B. Hayden Prop. Laguna
21089	" " " " " "
21090	Window Display - Mixmaster - Edison Bldg
21091	Chart on Safety - Cops pointing it out. 5-6-38
21092	Bill Board - of Gas Co.
21093	Elec. Heater for Distiller
21094	Heavy Duty Range - So. Gate Hospital N.E. Olton, Tex. 5-9-38
21095	Elec. Heater for Distiller
21096	Heavy Duty Range - So. Gate Hospital N.E. Olton, Tex. 5-9-38
21097	Group of Employees - S.M. Comm. Off. 5-12-38
21098	" " " " " "
21099	Linotype Machine at S.M. Outlook
21100	" " " " " "
21101	Oven at Mop Factory - S. Pas. 5-13-38
21102	Heavy Duty - Grill & Kettles at Vuopillat Cafe - Hermosa - 5-23-38

21101	R. of W. Along S.A. River E. of Olive -	5-2-38
21102	"	"
21103	"	"
21104	"	"
21105	"	"
21106	"	"
21107	"	"
21108	"	"
21109	"	"
21110	"	"
21111	"	"
21112	"	"
21113	"	"
21112	"	"
21113	"	"
21114	"	"
21115	"	"
21116	"	"
21117	"	"
21118	"	"
21119	Ancient Motor discovered in Redlands Meat Market	5-11-38
21120	"	"
21121	"	"
21122	"	"
21123	Oil Pump at	Long Beach 5-16-38
21124	"	"
21125	"	"
21126	"	"
21127	"	"

21128	Oil Pump at	L.B. 5-16-38
21129	"	"
21130	"	"
21131	"	"
21132	"	"
21133	"	"
21134	"	"
21135	"	Wilmington
21136	"	"
21137	Accident To Donald A Jones, Scene of - Alameda St. Randolph	5-17-38
21138	"	"
21139	"	"
21140	"	"
21139	"	"
21140	"	"
21141	"	"
21142	Heavy Duty - Elec. Oven - S.M. Market	5-23-38
21143	"	"
21144	Office Bldg. New, at Montebello	5-25-38
21145	Ⓢ Roaster	5-1-38
21146	Pines Coffee Shop - Ext. - Arcadia -	5-24-38
21147	Air Conditioning - Richardson's Mortuary - EXT - Ontario	"
21148	" " " " - Chapel	"
21149	" " Abbott's Clinic - EXT - Ont.	"
21150	" " " " Int - "	"
21151	" " " " " "	"
21152	" " Drapers Mortuary Ext, "	"
21153	" " " " Int "	"
21154	" " Hardware Store - Office	"



21155	Air Conditioning - Fallis Bldg - Ontario	5-24-38
21156	" " Dept Store - Ext. "	"
21157	" " " Int. "	"
21158	" " Upland Hospital - Ext.	"
21159	" " " Oper. Room	"
21160	" " " " "	"
21161	" " " Lab.	"
21162	" " Maternity Hospital - Del. Rm. Pomona	"
21163	Orange Co. Props - Katella Sub	6-7-38
21164	" " La Habra "	"
21165	" " Fullerton " + E.D.S.	"
21166	" " Orange "	"
21167	" " Atwood Sub	"
21166	" " Orange "	"
21167	" " Atwood Sub	"
21168	" " " "	"
21169	" " Irvine "	"
21170	" " Fairview "	"
21171	" " Santa Ana "	"
21172	" " " " + E.D.S.	"
21173	" " Laguna "	"
21174	" " Huntington Beach - E.D.S.	6-9-38
21175	" " " Ocean View Sub.	"
21176	" " Los Alamitos "	"
21177	" " Huntington Beach Office	"
21178	" " Laguna Office	6-7-38
21179	" " Palboa "	"
21180	" " Santa Ana "	"
21181	" " Orange "	"

21182	Props. in Orange Co. - Fullerton Office	6-7-38
21183	" " - Placentia "	"
21184	" " - La Habra "	"
21185	Transportation - Special Truck # 234 - Right Side	6-2-38
21186	" " " " Rear part	"
21187	" " " Left "	"
21188	" " " " " "	"
21189	" " " Rear View	"
21190	" " " Control in rear	"
21191	" " " Derrick Const.	"
21192	Accident - 251 Teleg. Rd. -	Taken 6-13-38
21193	" " " "	"
21194	Accident - 251 Teleg. Rd. -	Taken 6-13-38
21193	" " " "	"
21194	" " " "	"
21195	" " " "	"
21196	" " " "	"
21197	" " " "	"
21198	Sw. Board of Miss. Glass (now at Warehouse)	6-16-38
21199	Chino Sub -	6-20-38
21200	Saaborn Hospital - Pomona - See # 21162	6-20-38



4x5" negs

21201	Officer Ray Coleman, Huntington Park	4/38
21202	" " " " " "	"
21203	" " " " " "	"
✓21204	" " " " " "	"
21205	" J.H. Perst, Fullerton	"
21206	" " " " " "	"
✓21207	" " " " " with children	4/38
21208	" " " " " "	"
✓21209	" " " " " "	"
✓21210	" " " " " "	"
✓21211	Sodium Vapor, Firestone Blvd.	4/38
✓21212	" " Florence Blvd. Huntington Park	"
✓21213	Sodium Vapor, Firestone Blvd. 1 D "	4/38
✓21212	" " Florence Blvd. Huntington Park	"
21213	" " Randolph St. Huntington Park	"
✓21214	" " 1st St. Santa Ana	"
21215	" " " " " "	"
✓21216	" " E. Long Beach	"
21217	" " #101, Fullerton	"
21218	" " Justin	"
21219	Schwartz Electric Home, La Cacerente, Patia Mrs. S. & "lady"	5/38
21220	" " " " " "	"
21221	" " " " " "	"
21222	" " " " Kitchen	"
21223	" " " " " & Mrs. S.	"
21224	" " " " " "	"
✓21225	" " " " Exterior	"
✓21226	" " " " Living Room	"
21227	Vandermerito, Santa Ana "Poor Lighting"	5/38

21228	Vandermerito, Santa Ana, "Poor Lighting"	5/38
21229	" " " " " " " " " " " " " " " "	"
21230	Wertinghouse "Auto meal" with "Dinner for 8"	"
21231	" " " " " " " " " " " "	"
✓21232	" " " " Chap brooding	"
✓21233	" " " " Hotcakes	"
✓21234	" " " " Bacon	"
✓21235	" " " " Layer Cakes	"
21236	" " " " " " " " " "	"
✓21237	Marion McKinney, Home Economist, West. Auto meal	5/38
21238	" " " " " " " " " "	"
21239	" " " " " " " " " "	"
✓21239	" " " " " " " " " "	"
21239	" " " " " " " " " "	"
✓21240	" " " " " " " " " "	"
✓21241	" " " " " " " " " "	"
21242	U.S.C. Architectural Exhibit, Santa Ana, Lighted Model	"
21243	" " " " " " " " " "	"
21244	" " " " " " " " " Closeup	"
21245	" " " " " " " " " "	"
21246	" " " " " " " " " Store Elecentours	"
21247	" " " " " " " " " Model's Spectators	"
21248	" " " " " " " " " Photos "Old" Fronts	"
21249	" " " " " " " " " Drawing "New" Fronts	"
21250	" " " " " " " " " Entrance	"
21251	" " " " " " " " " Spectators - general	"
21252	" " " " " " " " " Graphs Maps	"
21253	" " " " " " " " " "	"
21254	" " " " " " " " " "	"



- 21255 U.S.C. Arch. Exhibit, Santa Ana, Value Model 5/38  
 ✓ 21256 Edison Girls Roaster School, Westinghouse Co., Class  
 ✓ 21257 Ltr: Misses Johnson, Whillab, Terry & "Full meal"  
 21258 Joe Scholl & Miss Serrigstad  
 ✓ 21259 Home Economist Marion McKinney & Miss Gardener  
 ✓ 21260 General View of Preparations  
 ✓ 21261 L to R: Joe Scholl, Mr. Rice, Mr. Hudg, at Table  
 21262 Luncheon, General Shot  
 + 21263 L to R: Miss Gardener, Miss Pritchett, Biscuits  
 21264 Adams Sportswear, Santa Ana  
 21265 " " " "  
 21266 Big & Little G.E. Fans 6/38  
 21265 " " " "  
 21266 Big & Little G.E. Fans 6/38  
 ✓ 21267 Santa Monica Lifeguard Service, Group & Inhalator  
 21268 " " " " " Guards on Boat  
 21269 " " " " " " " "  
 21270 " " " " " " " " Radio  
 ✓ 21271 2nd Set Rival Roaster Appliance  
 ✓ 21272 " " " " " " " " Phone  
 ✓ 21273 " " " " " " " "  
 21274 " " " " " " " "  
 21275 " " " " " " " "  
 ✓ 21276 Hollywood Tort Club, Improved, Exterior  
 ✓ 21277 " " " " " " " " Main Kitchen  
 21278 " " " " " " " " Tort Club Entrance  
 21279 " " " " " " " " Chef Peddler in Main Kitchen  
 21280 " " " " " " " " Coffee Shop Kitchen  
 ✓ 21281 " " " " " " " " Kitchen Hardware

- 21292 Hollywood Tort Club, Tiger Lovers 6/38  
 21293 " " " " " " " " Cactus Exterior  
 ✓ 21294 Helen Ring, Balminton Pix at H. Mayer 6/38  
 21295 " " " " " " " " "  
 21296 " " " " " " " " "  
 21297 " " " " " " " " "  
 21298 " " " " " " " " "  
 ✓ 21299 " " " " " " " " "  
 21290 V.E. Carser home, San Bernardino 6/38  
 21291 " " " " " " " " Desert Kiosk on roof  
 21292 Flowers, Auditorium, For Mrs. Rees 6/38  
 21293 " " " " " " " " "  
 21292 Flowers, Auditorium, For Mrs. Rees 6/38  
 21293 " " " " " " " " "  
 ✓ 21294 G.E. Scavenger Alarm Clock 7/38  
 ✓ 21295 Everbat Timer Clock 7/38  
 21296 Mr. Cayton, Antea, Spray pump 7/38  
 21297 D.B. Footrest Compresor, Cayton Ranch, Antea 7/38  
 21298 Incubators, Geo. England, England Ranch, Ingwood 7/38  
 21299 Egg Ginder " " " " "  
 21300





21355	Display Window -	6-24-38
21356	Accident. - Commonwealth + Pritchard Ave - Fullerton -	6-27-38
21357	" (Jno. Muzio)	"
21358	"	"
21359	"	"
21360	"	"
21361	"	"
21362	"	"
21363	"	"
21364	Accident - <sup>Bro. Lester</sup> Brown Boy at L.B. Cons. Sub.	7-13-38
21365	"	"
21366	"	"
21367	"	7-12-38
21368	"	"
21369	"	"
21370	Test of Kelman Switches - Laguna Bell	7-10-38
21371	"	"
21372	Window Display - Ed. Bldg	7-11-38
21373	School Room at Montecito - Before change	7-1-38
21374	"	"
21375	" Whittier - New installation.	7-13-38
21376	"	"
21377	"	"
21378	Redlands "Daily Facts" Newspaper	7-12-38
21379	"	"
21380	Accident El Monte - Jas B Van Sickle	7-14-38
21381	"	"

21382	Accident El Monte - Jas. B. Van Dicklin	
21383	" " " "	
21384	Transformers at China Sub	8-10-38
21385	Accident - Don Jones - Alameda & Randolph - 9 after Sunset	8-8-38
21386	" " " "	
21387	Walnut Dehydrator - Mr C. A. Bush	8-16-38
21388	Orange Packing at Camarillo - G.V.	"
21389	" " " " 1 Peaches Sorter	"
21390	" " " " " "	"
21391	Lighting in office of Lemon House - Satacay	"
21392	Brooder at M.K. Braten Chicken Ro. Ojai	"
21393	Lighting in office of Lemon House - Satacay	"
21392	Brooder at M.K. Braten Chicken Ro. Ojai	"
21393	Chickens " " " "	"
21394	Printing office at Santa Barbara	"
21395	" " " " Linotype machines	"
21396	Pumping Plant on " Santa Rosita Ro.	"
21397	" " " " " "	"
21398	Lighting after - San Bernardino Library -	8-17-38
21399	" " " " " "	"
21400	" " " " " "	"
21401	" " " " " "	"
21402	" " " " " "	"
21403	" " " " " "	"



✓21401	Surgical Sterilizer, Murphy Memorial Hospital, Whittier	7/38
✓21402	" " " " " "	"
✓21403	Laboratory " " " Autoclave	"
✓21404	Sterile Water Containers, Murphy Memorial, Whittier	"
✓21405	Exterior " " " "	"
✓21406	Carrier Room Cooler Installation	7/38
✓21407	Heliumator " " " "	7/38
21408	Exchange Products Co Plant, Ontario	7/38
21409	Ford Lunch " " "	"
21410	M.O.D. Orange Packing House, " "	"
21411	1st National Bank " " "	"
21412	Fallis Men's Store, Interior	"
✓21413	" Dept " Exterior	"
✓21412	Fallis Men's Store, Interior	"
✓21413	" Dept " Exterior	"
✓21414	Huntington Beach Oil Rig Gen. View	7/38
✓21415	" " " " " "	"
✓21416	" " " " " "	"
21417	Ref. W. Carr Property - Eagle Rock - Canfield Line - Looking East	7/21/38
21418	" " " " " " North	"
21419	" " " " " " East	"
21420	" " " " " " East	"
✓21421	Santa Ana - Tustin Citrus Assoc., Tustin, Switch Panel	7/38
✓21422	" " " " " Mr. Theris, Mgr.	"
✓21423	" " " " " Gen. View Interior	"
✓21424	" " " " " Streamlined Brogden	"
✓21425	" " " " " Grading Table	"
21426	" " " " " Pre-cooler room	"
21427	" " " " " Exterior	"

✓21428	Citrus Association, Tustin, Hand Wrapping	7/38
✓21429	" " " " " Compressor Room	"
✓21430	" " " " " Pre-cooler Storage	"
✓21431	Lawry's Restaurant, Beverly Hills, Steam Table	7/38
21432	" " " " " Unloading Oven	"
✓21433	" " " " " Exterior, Night	"
21434	" " " " " Deep Fat Fryer	"
21435	Pioneer-Flint Kate, Vernon, Unloading Rig	7/38
✓21436	" " " " " Bester Machine	"
21437	" " " " " Felt Machine	"
✓21438	" " " " " Trucking Felt Rolls	"
21439	" " " " " Asphaltting Felt	"
✓21440	" " " " " Sprinkling Rack	"
21439	" " " " " Asphaltting Felt	"
✓21440	" " " " " Sprinkling Rack	"
✓21441	" " " " " Drying Felt	"
21442	" " " " " Cutting Roll Roofing	"
✓21443	" " " " " High Voltage Panel	"
✓21444	" " " " " Water in Felt Machine	"
✓21445	Lighting - Daylight - Mountain View School, El Monte	7/38
✓21446	Sodium Vapor Lighting - S. Park & W. 5th, Pomona	7/38
✓21447	Mrs. Lacey, Bacteriologist, Health Center, Pomona	"
21448	" " " " " " "	"
✓21449	"Dandelion" Small Incubator, for Poultry Book	8/38
21450	Panel Board Lyon Co. Poultry Equipment	8/38
21451	Polair Cooler at E Richardson Hatchery, Temple	8/38
21452	" " " " " Interior	"
21453	" " " " " showing damper control	"
21454	"San Gabriel Village" - Better Inc. Model home exterior	8/38







116

21501	Street Lighting at Covina-Harvey Blvd. Mayor Turning on Its - 8-26-38	
21502	" " " " " "	
21503	" " Covina City Council + c. " "	
21504	" " Light at intersection " "	
21505	" " Old sign on Hiway " "	
21506	Air Conditioning - Theater in Monrovia 9-2-38	
21507	" " - Coffee Shop " "	
21508	" " Int. Dress Shop Alhambra " "	
21509	" " Ext. " " " "	
21510	Stone Polishing Machine (Lap) Arcadia " "	
21511	" Cutting " " " "	
21512	Ind. Lighting - Herbert's Mach. Co. 8-31-38	
21513	" " " " " "	
21512	Ind. Lighting - Herbert's Mach. Co. 8-31-38	
21513	" " " " " "	
21514	" " " " " "	
21515	Poultry - Brooder - at Mr. Jansen's - Baldwin Pk. 9-8-38	
21516	Engine at Wreck. " "	
21517	Transformer - G.E. Burned - on Isenberg Rd. # 5498242 - 9-13-38	
21518	" " " " " "	
21519	" " " " " 4666481	
21520	" " " " " "	
21521	Air Cond. - Columbia Steel - Ext. " "	
21522	" " " " - Lobby " "	
21523	" " " " - Office " "	
21524	Pomona Fair Exhibits 9-16-38	
21525	" " " " " "	
21526	" " " " " "	
21527	" " " " " "	

117

21528	Pomona Fair Exhibits 9-16-38	
21529	" " " " " "	
21530	" " " " " "	
21531	" " " " " "	
21532	" " " " " "	
21533	" " " " " "	
21534	" " " " " "	
21535	" " " " " "	
21536	" " " " " "	
21537	" " " " " "	
21538	" " " " " "	
21539	" " " " " "	
21538	" " " " " "	
21539	" " " " " "	
21540	" " " " " "	
21541	" " " " " "	
21542	Accident - Webb + Webb - Marengo Ave + Woodbury Rd. 9-19-38	
21543	" " " " " "	
21544	" " " " " "	
21545	" " " " " "	
21546	" " " " " "	
21547	Am. Legion - Edison Post Float " "	
21548	" " " " " " " "	
21549	PRINTING OFFICE - WHITTIER NEWS - Linotype Machines 9-20-38	
21550	" " " " " Mr. Jackson - Foreman " "	
21551	Evaporator at Vernon City Plant 9-20-38	
21552	" " " " " "	
21553	" " " " " "	
21554	" " " " " "	



21555	Evaporator at Vernon City Sub	9-20-38
21556	Super-Heater " "	" "
21557	Small Pole Dolly Cap-2000 lbs.	9-23-38
21558	" " " "	" "
21559	" " " "	" "
21560	" " " "	" "
21561	Edison Bldg - Leaky Places (S+W)	9-27-38
21562	" " " "	" "
21563	" " " "	" "
21564	" " " "	" "
21565	" " " "	" "
21566	" " " "	" "
21567	Elec. Range - Mr + Mrs Pickens - Norwalk.	10-4-38
21568	" " " "	" "
21569	Elec. Range - Mr + Mrs Pickens - Norwalk.	10-4-38
21570	Sodium Vapor Lts - Mission Rd + Anita Blvd - San Gabriel -	10-5-38
21571	Poultry - Taking chicks out of Incubator - England Ro.	10-6-38
21572	" " Putting " in boxes " "	" "
21573	San Gabriel - Police Chief + 3 M-Cycle officers	10-5-38
21574	" " " " " "	" "
21575	Catalogue of Trans. Bushings for Catalog - Geal Store	10-3-38
21576	(W) New 220 KV Switch -	10-7-38
21577	Copy of Report on H.L. Dams by Dennis H.W. Page 1	10-7-38
21578	" " " " " "	" "
21579	" " " " " "	" "
21580	" " " " " "	" "
21581	" " " " " "	" "

21582	Copy of Rept. cont. Page 8	
21583	<del>Feed Chopper</del> " 9	
21584	Feed Chopper at Grant Ro. Chino	10-12-38
21585	Chino Sub - New Control House	" "
21586	Poultry - England Ro. Inglewood	10-13-38
21587	" " " "	" "
21588	" " " "	" "
21589	" " " "	" "
21590	Night Light - Pepper Trees at Ontario	10-13-38
21591	" " " "	" "
21592	(W) Corncop Oil Sw. Test at Laguna Bell	10-16-38
21593	" " " " - Men -	" "
21594	(W) Corncop Oil Sw. Test at Laguna Bell	10-16-38
21595	" " " " - Men -	" "
21596	Santa Monica Sub -	10-17-38
21597	Heavy Duty - Elec. Oven at Pomona College	10-18-38
21598	Mr Logan - Egg Man - Pomona Av. Bearley Ranch	" "
21599	" " " " " "	" "
21600	Copy of Letter from Sheriff Biscailuz	10-18-38
	El Monte Herald - Editor	10-19-38
	" " " " - Linotype Machine -	" "







21655	Western Cordage Co, Orange, reeling & twisting fibre	11/38
21656	" " " " , twisting fibre cable	"
21657	" " " " , reeling twisted rope	"
21658	" " " " " " " "	"
✓21659	" " " " storing " "	"
✓21660	Mrs. Moffat & maid, Ester, San Fernando	11/38
✓21661	Exterior, Moffat house	"
✓21662	" " " " " "	"
✓21663	Badminton Ct. " " " "	"
21664	Fullerton "Treasure Hunt", Exterior, Daylight	11/38
21665	" " " " Nite	"
21666	" " " " Crowd	"
21667	" " " " Interior	"
21668	" " " " Crowd	"
21667	" " " " Interior	"
21668	" " " " " "	"
21669	" " " " " "	"
21670	" " " " Winners Line-up	"
✓21671	" " " " Mr. Lindley & Welsh	"
21672	" " " " " "	"
21673	" " " " Demonstration, Washer	"
21674	" " " " , Radio	"
21675	" " " " Ironer	"
✓21676	Lillian Presnell with Homozone Air-Purifier	11/38
✓21677	Lyon Homemade type brooder-Poultry book	12/38
21678	" Coil Poultry Heaters	" 12/38
✓21679	" Outdoor brooder element	" 12/38
✓21680	" Hover fan type brooder	" 12/38
✓21681	" Thermostats	" 12/38

✓21682	Lyon Water Warmer, Poultry book	12/38
✓21683	" Brooder element	" 12/38
✓21684	" " " , long	" 12/38
✓21685	" Spotlight egg tester	" 12/38
✓21686	Busse ranch, Goudens, fly trap	" 12/38
✓21687	" " " , gun man	" 12/38
✓21688	" " , brooders, Mr. Busse	" 12/38
✓21689	" " " Mrs. Busse	" 12/38
✓21690	" " , manure bin, Mr. Busse	" 12/38
✓21691	Childers & Hatch, Santa Ana, vacuum	" 12/38
✓21692	" " " " , egg machine	" 12/38
✓21693	Poultry Sun Porch, Bennett's, Tustin	" 12/38
✓21694	" " " " , egg machine	" 12/38
✓21693	Poultry Sun Porch, Bennett's, Tustin	" 12/38
✓21694	Beauchamp hatchery, Poomsy, motor tray cleaner	" 12/38
✓21695	State Game Farm, Chino, interior colony brooder	" 12/38
✓21696	" " " " , quail	" 12/38
✓21697	" " " " , colony brooders	" 12/38
✓21698	" " " " , quail	" 12/38
✓21699	" " " " , pheasants	" 12/38
✓21700	" " " " , colony brooder	" 12/38

21701	Accident To S. Sakamoto on Telegraph Rd + Lakewood Dr	10-24-38
21702	" " " "	"
21703	" " " "	"
21704	" " " "	"
21705	" " " "	"
21706	" " " "	"
21707	Accident To Arlene Mallory at 190 <sup>th</sup> + Vermont	10-31-38
21708	" " " "	"
21709	" " " "	"
21710	" " " "	"
21711	" " " "	"
21712	" " " "	"
21713	" " " "	"
21714	" " " "	"
21713	" " " "	"
21714	" " " "	"
21715	Repairs on Edison Bldg - By Stone + Webster	11-8-38
21716	" " " "	"
21717	" " " "	"
21718	" " " "	"
21719	Night Photos - Long Beach - Florsheim St. Ext	11-9-38
21720	" " " " Int	"
21721	" " " " C.C. Lewis - Jeweler - Ex	"
21722	" " " " Stationery Ex	"
21723	" " " " Int	"
21724	" " " " " "	"
21725	" " " " Sears + Wade - Linoleum Ex	"
21726	" " " " Int	"
21727	Window Display - Halloween -	10-30-38

21728	Copy Portrait - Sheriff Capt D.W. Hirstine of Temple	11-9-38
21729	Copy of Safety Award	"
21730	Elec. Home of Guy Nicolls - Alhambra	11-9-38
21731	" " Kit. " "	"
21732	Repairs on Edison Bldg - Finished	11-11-38
21733	" " " "	"
21734	Elec. Kitchen of Mrs Hathaway Norwalk	11-16-38
21735	" " " " H.S. McGladwin	"
21736	" " " " L.A. Wicklund	"
21737	" " " " Irving Wardman	"
21738	" " " " Johnston	"
21739	" " " " Meyers	"
21740	" " " " Johnston	"
21739	" " " " Meyers	"
21740	" " " " Taber	"
21741	" " " " R. Little	"
21742	" " " " " "	"
21743	Ind. Lighting Office of E. Whittier Pack House	"
21744	" " " " Drafting Room of Aircraft - Norwalk	"
21745	" " " " " "	"
21746	" " " " Office of Packing House - Los Nietos	"
21747	" " " " Cold Room - in Packing Plant - Vernon	11-18-38
21748	" " " " School at Whittier	11-14-38
21749	" " " " " " Abraham Lincoln School	"
21750	Accident To Car #3301 Front	11-21-38
21751	" " " " Rear	"
21752	" " " " R. Side	"
21753	" " " " L. " "	"
21754	" " " " Rear + R	"



21755	Accident To Car #304	11-21-38
21756	Indus. Lt. in Cold Room of Packing Plant (After)	11-22-38
21757	Condenser at Chino	11-16-38
21758	" "	"
21759	" "	"
21760	" "	"
21761	Copy of Oil Well Drilling Motors	"
21762	" " " "	"
21763	" " " "	"
21764	Chief of Police of San Marino	12-7-38
21765	Police Officers ..	"
21766	" " "	"
21767	Bus. Mgr. of L.B. Telegram - Chas Paddock	11-25-38
21766	" " "	"
21767	Bus. Mgr. of L.B. Telegram - Chas Paddock	11-25-38
21768	Linotype Mach. of ..	"
21769	Kitchen of Pauling Sanit. San Fernando	11-29-38
21770	" " " "	"
21771	Vernon Diesel Gen. Plant - Ext.	12-19-38
21772	" " " - Sw. Bld.	"
21773	" " " - Gen. V. Int.	"
21774	" " " - Eng.	"
21775	Santa Ana Register - Mgr.	12-22-38
21776	" " - Comp. Rm.	"
21777	" " "	"
21778	Accident To Car of Leo Vasquez	12-16-38
21779	" " "	"
21780	" " "	"
21781	" " "	"

21782	Accident To Edison Car (Same accident - Vasquez)	12-23-38
21783	" "	"
21784	" "	"
21785	" "	"
21786	Lighting material for Salesman	"
21787	" " " "	"
21788	Lighting - Before - Loan Co. Altadena	11-28-38
21789	" After - " " "	12-27-38
21790	Xmas Tree Lighting at Bev. Hills	12-28-38
21791	" " " "	"
21792	" " " "	"
21793	" " " "	"
21792	" " " "	"
21793	" " " "	"
21794	" " " "	"
21795	" " " "	"
21796	" " " "	"
21797	" " " "	"
21798	Light Meter Demonstration - Rankin & Shoop	"
21799	Window Display - Ed. Bldg	"
21800	Lamp Post - L.B. Blvd. Double made into Single - 1-6-39	"

21801	Knott's Berry Place - Entrance	1-4-39
21802	" " " - <del>Ann. Ext.</del>	"
21803	" " " - Store	"
21804	" " " - Dining Room	"
21805	" " " " "	"
21806	" " " - Making Pies	"
21807	" " " " "	"
21808	" " " Refrigerator	"
21809	Lighting - Before - El Monte School	1-4-39
21810	" " " " "	"
21811	" After - " "	"
21812	" Wellman Jewellery Store - Alhambra - Ext. Day	1-4-39
21813	" " " " " " "	"
21812	" Wellman Jewellery Store - Alhambra - Ext. Day	1-4-39
21813	" " " " " " Night	"
21814	" " " " " Windows	"
21815	" " " " " Int.	"
21816	" " " " " " "	"
21817	" Oxnard Sugar factory office	1-3-39
21818	" " " " " " "	"
21819	Fred Hamilton - 40th with Edison - Flowers	1-19-39
21820	" " " " " " "	"
21821	Lamp Display	"
21822	" " " " " " "	"
21823	Play Area Lighting - Drawing	1-21-39
21824	Advertising Program for 1939 - Domestic Sales	1-39
21825	" " " " " Industrial	"
21826	Sup. of School at El Monte	1-4-39
21827	Chief of Highway Patrol Santa Ana	1-9-39

21828	Group of Highway Patrol officers at Santa Ana	1-9-39
21829	Air plane at Mines field - Ernie Smith - Front	1-6-39
21830	" " " " " Side	"
21831	Reconstruction of M.C. 1 Pipe Line across wash from #2+3-1-11-39	
21832	" " " " " " "	"
21833	" " Headworks of M.C. 3	"
21834	" at S.A.R. 3	"
21835	" " " " "	"
21836	" " " " "	"
21837	" " Canal bet. S.A.R. 1 + 2	"
21838	" at S.A.R. 1	"
21839	" " " " "	"
21838	" at S.A.R. 1	"
21839	" " " " "	"
21840	" " " " (Headwks for #2)	"
21841	" " " " "	"
21842	" " " " "	"
21843	" " Sierra Plant	"
21844	Copy of Page 1 of S+W Report on Backfills on Dams at H.L.	1-20-39
21845	" 2	"
21846	" 3	"
21847	" 4	"
21848	" 5	"
21849	" 6	"
21850	" 7	"
21851	" 8	"
21852	" 9	"
21853	" 10	"
21854	" 11	"



21855	Copy of Page 12 - Report continued	1-20-39
21856	" " 13 " "	" "
21857	Trans. Dept - Tool Boxes for Trucks	1-10-39
21858	" " " "	" "
21859	" " " "	" "
21860	KNX at Torrance - G.V. of Studio	1-20-39
21861	" " - Sub Station	" "
21862	" " at " "	" "
21863	" " " "	" "
21864	" " " "	" "
21865	" " " "	" "
21866	" " " "	" "
21867	Lighting - News Paper - Monrovia	1-24-39
21868	" " Editor - Davis	" "
21869	Copy - Euclid Ave	" "
21870	Stand Lamp	" "
21871	Map + Annexations To L.A.	" "
21872	Window Display Ed. Bldg	" "
21873	Accident - H.S. Gray - Monterey Rd + Orange Grove	2-1-39
21874	" " " "	" "
21875	" " " "	" "
21876	" " " "	" "
21877	" " " "	" "
21878	" " " "	" "
21879	Pumping Plant of <sup>Bank E.</sup> Mr Soule - Ojai	2-8-39
21880	" " " "	" "
21881	" " " "	" "

21882	School Room at Montecito <sup>Union Elem. School</sup> After	2-8-39
21883	" " " "	" "
21884	Heavy Duty - Deep fat Kettle - <sup>Wierfeldt's</sup> Cafe - S. Bar.	" "
21885	" " " "	" "
21886	" " " - Californian	" "
21887	" Toaster + Brailer	" "
21888	Mr. Rasmick Recreational Director - S. Bar	" "
21889	" " " "	" "
21890	Night lighted Tennis Courts	" "
21891	Brick Co encroaching on Ed. R. of W. - So. Western Ave	2-9-39
21892	" " " "	" "
21893	Brick Co encroaching on Ed. R. of W. - So. Western Ave	2-9-39
21892	" " " "	" "
21893	" " " "	" "
21894	" " " "	" "
21895	" " " "	" "
21896	" " " "	" "
21897	" " " "	" "
21898	" " " "	" "
21899	" " " "	" "
21900	" " " "	" "

21901	State Game Farm, Chino, inspecting brooder, poultry book	12/38
21902	" " " " Gen. View, brooders "	12/38
21903	" " " " " " " "	12/38
21904	Poultry house lighting, Young ranch, Downey	12/38
✓21905	Dr. Juncos examining chicken, pathological lab	12/38
✓21906	Making bacteriological exam " " " "	12/38
✓21907	Staff, pathological lab, L.A.	12/38
21908	Fred Richardson, Temple, portable spring gun	12/38
✓21909	" " " " incubators	12/38
✓21910	" " " " exhaust fan	12/38
✓21911	F.H. Allen & Marshall Richardson & brooder	12/38
✓21912	Geo. Richardson Ranch, Temple, testing eggs	12/38
✓21913	" " " " incubator & brooder	12/38
✓21912	Geo. Richardson Ranch, Temple, testing eggs	12/38
✓21913	" " " " vacuuming incubator	12/38
✓21914	" " " " traying eggs	12/38
✓21915	" " " " feed chopper	12/38
✓21916	" " " " Marshall R. & chicken	12/38
✓21917	Miss Grakulas doll, decorating contest	12/38
✓21918	Judges inspecting dolls	12/38
✓21919	Winners, 1938 doll decorating contest	12/38
✓21920	" " " " " "	12/38
✓21921	" " " " " "	12/38
✓21922	Child & dolls	12/38
✓21923	Judges	12/38
✓21924	Lobby window	12/38
✓21925	Fisher's workroom, General Store, Alhambra	12/38
✓21926	Merchandise ensemble, McFadden book	12/38
✓21927	Front, Appliance Store, Central Office	12/38

✓21928	Interior, Appliance Store, Central Office	12/38
✓21929	" " Range Storage, General Store, Alhambra	12/38
✓21930	" " Appliance Store, Central Office	12/38
✓21931	" " " " " "	12/38
✓21932	" " Mech. Storage, General Store	12/38
✓21933	Exterior, Loading Dock	12/38
✓21934	Electric Dodge, Santa Monica, long shot	12/38
✓21935	" " " " " " close up	12/38
✓21936	Polishing dryer, Le Roy Goodwin, Santa Monica	12/38
✓21937	Dryers, " " " "	12/38
✓21938	Sodium Vapor, Hunt. Drive & , San Marino	12/38
✓21939	" " " " " " " "	12/38
✓21938	Sodium Vapor, Hunt. Drive & , San Marino	12/38
✓21939	" " " " " " " "	12/38
✓21940	Pouring bath tubs, Washington Eljer Co., Vernon	1/39
✓21941	Mixing enamel	"
✓21942	Making sand mold	"
✓21943	Fitting molds	"
✓21944	Inspecting tubs	"
✓21945	Prep. enamel	"
✓21946	Smelting iron	"
✓21947	Enameling furnace	"
✓21948	Lillian Presnell & merchandise offer	1/39
✓21949	Iron on merchandise offer	"
✓21950	Radio	"
✓21951	Group	"
✓21952	Toaster	"
✓21953	Lillian Presnell & merchandise offer	"
✓21954	" " " "	"



✓21955	Westinghouse	advertisement	
✓21956	"	range for year adut	1/39
✓21957	Jane Sinclair with cookie tin	"	"
✓21958	"	"	1/39
✓21959	Thermador Speed-Ray Stovesline heater	"	1/39
✓21960	Wesix electric heater	"	"
✓21961	Mr. Hauser, Fontana, & electric brooder	"	1/39
✓21962	"	"	"
✓21963	Grading table, lighting, Brown Estate house,	Highhouse	"
✓21964	Exterior	"	1/39
✓21965	Mr. Medley with mgr.	"	"
✓21966	Lighting, exterior Sampson home, Alhambra	"	"
✓21967	"	Doorway mgr.	"
✓21966	Lighting, exterior Sampson home, Alhambra	"	"
✓21967	"	Doorway	"
✓21968	" Living room	"	"
21969	" Bed room	"	"
✓21970	Exterior, daytime	also A-21970	"
✓21971	Exterior, Paff home, San Bernardino, range adut	"	1/39
✓21972	Mrs. Paff	"	"
✓21973	Xmas lighting, Fontinos home, San Marino	"	1/39
✓21974	"	Ubil home	"
✓21975	"	Nuccio home	"
✓21976	"	Johnson	"
✓21977	"	"	"
✓21978	Joan Summers & Westinghouse	"	"
✓21979	"	"	range 1/39
✓21980	"	"	"
✓21981	"	"	"

✓21982	Joan Summers & Westinghouse	range	1/39
✓21983	"	"	"
✓21984	Anaconda Wire & Cable Co., Orange, inspecting copper strand	"	1/39
✓21985	"	"	"
✓21986	"	"	"
✓21987	"	"	"
✓21988	"	"	"
✓21989	"	"	"
<del>21990</del>	<del>"</del>	<del>"</del>	<del>"</del>
✓21991	"	"	"
✓21992	"	"	"
✓21993	"	"	"
✓21992	"	"	"
✓21993	"	"	"
✓21994	Frank Hansen, Jane Sinclair, & Polaroid disc	"	1/39
✓21995	"	"	"
✓21996	Foster Simpson & Lillian Presnell & musical life	"	"
✓21997	Mr. Rankin & Virginia Thompson & color wheels	"	"
✓21998	Nightingale & Helen Ramsey, & Hindu ball	"	"
✓21999	Mr. Rodgers & Miss Merino, & 1000 watt bulb	"	"
✓22000	Helen Pedersen & flame dance	"	"

22001	H.L. - Dam 3 - Relocation of road N. of Dam 3	10-19-38
22002	Drilling template for Anchor Bolts - Sluice Valve #1	9-25-38
22003	" " " Bolts	9-25-38
22004	Core Drilling for Anchor Holes Valve #4	9-25-38
22005	Toe of Dam 6 before guniting	"
22006	Guniting along Toe of Dam 6	"
22007	" Fresno side	10-4-38
22008	" "	7
22009	" "	"
22010	Dam 2 - Completed Rock fill	10-18-38
22011	Dam 6 - Gunite completed	11-11-38
22012	" - Foundation rock - down stream	10-17-38
22013	" " "	11-11-38
22012	" - Foundation rock - down stream	10-17-38
22013	" " "	"
22014	" " "	"
22015	" " "	"
22016	" " "	"
22017	" - Completed gunite - Madera side	21
22018	" - Inst. Sluice gates	"
22019	" - Sluice Pipe #3 ready for valve	11-5-38
22020	" Lowering gate frame - Valve #3	"
22021		
22022	22021. Florence Lake Dam, View of Intrados, Arch #1	11-15-38
22023	22022. " View of Intrados, Arch #2	"
22023	22023. " View of Intrados, Arch #3	"
22024	22024. " " " #4	"
22024	22025. " 3 views of Intrados, Arch #5,	
22025	22026. " Right bottom, left bottom and top.	11-17-38
22025	22027. "	
22026		
22027		

22028	"	View of Intrados, Arch #6	11-17-38
22029	"	" " " #7	"
22030	"	" " " #8	"
22031	"	" " " #9	"
22032	"	" " " 10	"
22031	"	2 views of Angle Buttress #10, from Arch 10 and Arch 11 sides.	11-20-38
22032	"	3 views of Intrados, Arch #11, Bottom right, bottom left and top.	11-17-38
22033	"		
22034	"	View of Intrados, Arch #12	"
22035	"	2 views of Intrados, Arch #13, Bottom and top.	11-17-38
22036	"	2 Views of Intrados, Arch #14, Bottom and top	"
22037	"	2 Views of Intrados, Arch #15,	"
22038	"	2 Views of Intrados, Arch #16, Top and bottom.	11-20-38
22039	"	2 Views of Intrados, Arch #17, Top and bottom.	"
22040	"	2 Views of Intrados, Arch #16, Top and bottom.	11-20-38
22041	"	2 Views of Intrados, Arch #17, Top and bottom.	"
22042	"	3 Views of Intrados, Arch #18, Bottom right, bottom left, and top.	11-20-38
22043	"		
22044	"	2 Views of Intrados, Arch #19, Top and Bottom.	11-20-38
22045	"	2 Views of Intrados, Arch #20, Top and	
22046	"		
22047	"		
22048	"		
22049	"		
22050	"		
22051	"		
22052	"		
22053	"		
22054	"		



22055

22056

22057

22058

22059

22060

22061

22062

22063

22064

22065

22066

22067

22068

22069

22070

22071

22072

22073

22074

22075

22076

22077

22078

22079

22080

22081

22055.	"	Bottom.	11-20-38
22056.	"	View of Intrados, Arch #21.	11-18-38
22057.	"	" " " #22	"
22058.	"	" " " #23	"
22059.	"	" " " #24	"
22060.	"	" " " #25, also west side of Angle	
		Buttress #25.	11-18-38
22061.	"	View of Angle Buttress #25 from Arch #26 side.	11-20-38
22062.	"	View of Intrados, Arch #26	11-15-38
22063.	"	View of Intrados, Arch #27,	"
22064.	"	" " " #28	"
22065.	"	" " " #29	"
22066.	"	" " " #30	"
22067.	"	" " " #31	11-20-38
22068.	"	" " " #32	11-15-38
22069.	"	" " " #33	"
22070.	"	" " " #34	"
22071.	"	3 views of Intrados, Arch #34, Bottom right,	
22072.	"	bottom left and top.	11-20-38
22073.	"	3 Views of Intrados, Arch #35, Bottom right,	
22074.	"	bottom left and top.	11-20-38
22075.	"		
		3 views of Intrados, Arch #35, Bottom right,	
22074.	"	bottom left and top.	11-20-38
22075.	"		

22076.	Florence Lake Dam, 3 Views of Intrados, Arch #36, Bottom right	
22077.	" " bottom left and top.	11-20-38
22078.	" " View of Downstream side of Spillway	11-
22079.	" " 3 views of Intrados Arch #37, Bottom right	
22080.	" " bottom left and top.	11-

22082

22083

22084

22085

22086

22087

22088

22089

22090

22091

22092

22093

22094

22095

22096

22097

22098

22099

22100

22082.	"	"	
22083.	"	"	View of Intrados, Arch #38.
22084.	"	"	
22085.	"	"	2 Views of Intrados, Arch #39, Right half
22086.	"	"	3 Views of Intrados, Arch #40, Bottom Right
22087.	"	"	bottom left and top. 11-18-38
22088.	"	"	
22089.	"	"	View of Intrados, Arch #41. "
22090.	"	"	View of Intrados, Arch #42. "
22091.	"	"	2 Views of Intrados, Arch #43, Right half and
22092.	"	"	left half. 11-18-38
22093.	"	"	View of Intrados, Arch #44. "
22094.	"	"	2 Views of Intrados, Arch #45, Right half and
22095.	"	"	left half. 11-18-38
22096.	"	"	2 Views of Intrados Arch #46, Right half and
22097.	"	"	left half. 11-18-38
22098.	"	"	3 Views of Intrados, Arch #47, Bottom right,
22099.	"	"	bottom left and top. 11-18-38
22100.	"	"	" 11-18-38

22100.	"	"	" and top. 11-18-38
			11-18-38

22055	22055.	"	Bottom.	11-2
22056	22056.	"	View of Intrados, Arch #21.	11-2
22057	22057.	"	" " " #22	
22058	22058.	"	" " " #23	
22059	22059.	"	" " " #24	
22060	22060.	"	" " " #25, also wes	
			Buttress #25.	11-
22059	22061.	"	View of Angle Buttress #25 from Ar	11-2
22060	22062.	"	View of Intrados, Arch #26	11-
	22063.	"	View of Intrados, Arch #27,	
	22064.	"	" " " #28	
22061	22065.	"	" " " #29	
22062	22066.	"	" " " #30	
	22067.	"	" " " #31	11-
22063	22068.	"	" " " #32	11-
	22069.	"	" " " #33	
22064	22070.	"	" " " #34	
	22071.	"	3 views of Intrados, Arch #34, Bot	
22065	22072.	"	bottom left and top.	11-2
22066	22073.	"	3 Views of Intrados, Arch #35, Bot	
	22074.	"	bottom left and top.	11-2
	22075.	"		
22063	22073.	"	3 Views of Intrados, Arch #35, Bot	11-2
22066	22074.	"	bottom left and top.	11-2
	22075.	"		
22067				
22068				
22069				
22070				
22071				
22072				
22073				
22074				
22075				
22076	22076.	Florence Lake Dam, 3 Views of Intrados, Arch #36, Bottom right		
22077	22077.	" " bottom left and top.	11-20-38	
	22078.	" "		
22078	22079.	" " View of Downstream side of Spillway	11-	
	22080.	" " 3 views of Intrados Arch #37, Bottom right		
22079	22081.	" " bottom left and top.	11-	
22080				
22081				

22082	22082.	"	"	
	22083.	"	"	View of Intrados, Arch #38.
22083	22084.	"	"	"
	22085.	"	"	2 Views of Intrados, Arch #39, Right half and L. half.
22084	22086.	"	"	3 Views of Intrados, Arch #40, Bottom Right
	22087.	"	"	bottom left and top. 11-18-38
22085	22088.	"	"	
	22089.	"	"	View of Intrados, Arch #41.
22086	22090.	"	"	View of Intrados, Arch #42.
	22091.	"	"	2 Views of Intrados, Arch #43, Right half and
22087	22092.	"	"	left half. 11-18-38
	22093.	"	"	View of Intrados, Arch #44.
22088	22094.	"	"	2 Views of Intrados, Arch #45, Right half and
	22095.	"	"	left half. 11-18-38
22089	22096.	"	"	2 Views of Intrados Arch #46, Right half and
	22097.	"	"	left half. 11-18-38
22090	22098.	"	"	3 Views of Intrados, Arch #47, Bottom right,
	22099.	"	"	bottom left and top. 11-18-38
22091	22100.	"	"	" 11-18-38
22092				
22093				
22094				
22095				
22096				
22097				
22098				
22099				
22100				



22101	22101.	"	"	View of Intrados, Arch #48.	"	28	22128.	-	Florence Lake Dam - Closer view of Angle Buttress No.10	4-3-39
22102	22102.	"	"	" " " #49	"	29	22129.	-	Florence Lake Dam - Extrados of Arches 10 & 11 and Upstream face of Angle Buttress 10.	4-3-39
22103	22103.	"	"	2 Views of Angle Buttress #49, from Arch #49 and Arch #50 sides.	11-17-38	30	22130.	-	Florence Lake Dam - View of Extrados of Arches 12 & 13	4-1-39
22104	22104.	"	"	View of Intrados, Arch #50.	"	31	22131.	-	Florence Lake Dam - View of Extrados of Arches 14 & 15	4-1-39
22105	22105.	"	"	2 Views of Intrados, Arch #51, Bottom and top.	11-17-38	32	22132.	-	Florence Lake Dam - View of Extrados of Arches 16 & 17	4-3-39
22106	22106.	"	"	2 Views of Intrados, Arch #52, Top and Bottom.	11-17-38	33	22133.	-	Florence Lake Dam - View of Extrados of Arches 17 & 19	4-3-39
22107	22107.	"	"	View of Intrados, Arch #53.	"	34	22134.	-	Florence Lake Dam - " " " " " 20	4-3-39
22108	22108.	"	"	2 Views of Intrados, Arch #54, Top and bottom.	11-17-38	35	22135.	-	Florence Lake Dam - " " " " " 21 & 22	4-3-39
22109	22109.	"	"	View of Intrados, Arch #55.	"	36	22136.	-	Florence Lake Dam - " " " " " 23	4-3-39
22110	22110.	"	"	2 Views of Intrados, Arch #56.	"	37	22137.	-	Florence Lake Dam - " " " " " 24	4-3-39
22111	22111.	"	"	2 Views of Intrados, Arch #57.	11-17-38	38	22138.	-	Florence Lake Dam - View of Extrados of Arch 25 and Upstream face of Angle Buttress 25.	4-3-39
22112	22112.	"	"	View of Intrados, Arch #58.	11-17-38	39	22139.	-	Florence Lake Dam - View of Extrados of Arch 26	4-3-39
22113	22113.	"	"	Spurt through open day's work joint 1' from haunch, Buttress #36 in Arch #36, Elevation 7304.	11-20-38	40	22140.	-	Florence Lake Dam - View of Extrados of Arch 27	4-3-39
22114	22114.	"	"	View of leakage water measuring station "50A" below Arch #50.	11-20-38	22141	22141.	-	Florence Lake Dam - View of Extrados of Arches 28 & 29	4-3-39
22115	22115.	"	"	Dam #6 Close-up of Anchor bolt hole Sluice Valve Job.		22142	22142.	-	Florence Lake Dam - " " " " " 30 & 31	4-3-39
22116	22116.	"	"	View of leakage water measuring station "50A" below Arch #50.	11-20-38	22143	22143.	-	Florence Lake Dam - " " " " " 32 & 33	4-3-39
22117	22117.	"	"	Dam #6 Close-up of Anchor bolt hole Sluice Valve Job.		22144	22144.	-	Florence Lake Dam - View of Extrados of Arch 34	4-3-39
22118	22118.	"	"			22145	22145.	-	Florence Lake Dam - View of Extrados of Arch 35	4-3-39
22119	22119.	"	"			22146	22146.	-	Florence Lake Dam - " " " " " 36	4-3-39
22120	22120.	"	"			22147	22147.	-	Florence Lake Dam - View of Upstream side of spillway section	4-3-39
22121	22121.	"	"			22148	22148.	-	Florence Lake Dam - View of Extrados of Arch 34	4-3-39
22122	22122.	"	"			22149	22149.	-	Florence Lake Dam - View of Extrados of Arch 35	4-3-39
22123	22123.	"	"			22150	22150.	-	Florence Lake Dam - " " " " " 36	4-3-39
22124	22124.	"	"			22151	22151.	-	Florence Lake Dam - " " " " " 36	4-3-39
22125	22125.	"	"			22152	22152.	-	Florence Lake Dam - View of Upstream side of spillway section	4-3-39
22126	22126.	"	"			22153	22153.	-	Florence Lake Dam - View of Looking down on Spillway Sec.	4-4-39
22127	22127.	"	"			22154	22154.	-	Florence Lake Dam - View of Upstream side of South Half of Spillway Section.	4-3-39
22128	22128.	"	"			22155	22155.	-	Florence Lake Dam - View of Extrados of Arches 37 & 38	4-3-39
22129	22129.	"	"			22156	22156.	-	Florence Lake Dam - " " " " " 39	4-3-39
22130	22130.	"	"			22157	22157.	-	Florence Lake Dam - " " " " " 40 & 41	4-3-39
22131	22131.	"	"			22158	22158.	-	Florence Lake Dam - " " " " " 42 & 43	4-3-39
22132	22132.	"	"			22159	22159.	-	Florence Lake Dam - " " " " " 44 & 45	4-3-39
22133	22133.	"	"			22160	22160.	-		
22134	22134.	"	"			22161	22161.	-		
22135	22135.	"	"			22162	22162.	-		
22136	22136.	"	"			22163	22163.	-		
22137	22137.	"	"			22164	22164.	-		
22138	22138.	"	"			22165	22165.	-		
22139	22139.	"	"			22166	22166.	-		
22140	22140.	"	"			22167	22167.	-		
22141	22141.	"	"			22168	22168.	-		
22142	22142.	"	"			22169	22169.	-		
22143	22143.	"	"			22170	22170.	-		
22144	22144.	"	"			22171	22171.	-		
22145	22145.	"	"			22172	22172.	-		
22146	22146.	"	"			22173	22173.	-		
22147	22147.	"	"			22174	22174.	-		
22148	22148.	"	"			22175	22175.	-		
22149	22149.	"	"			22176	22176.	-		
22150	22150.	"	"			22177	22177.	-		
22151	22151.	"	"			22178	22178.	-		
22152	22152.	"	"			22179	22179.	-		
22153	22153.	"	"			22180	22180.	-		
22154	22154.	"	"			22181	22181.	-		
22155	22155.	"	"			22182	22182.	-		
22156	22156.	"	"			22183	22183.	-		
22157	22157.	"	"			22184	22184.	-		
22158	22158.	"	"			22185	22185.	-		
22159	22159.	"	"			22186	22186.	-		
22160	22160.	"	"			22187	22187.	-		
22161	22161.	"	"			22188	22188.	-		
22162	22162.	"	"			22189	22189.	-		
22163	22163.	"	"			22190	22190.	-		
22164	22164.	"	"			22191	22191.	-		
22165	22165.	"	"			22192	22192.	-		
22166	22166.	"	"			22193	22193.	-		
22167	22167.	"	"			22194	22194.	-		
22168	22168.	"	"			22195	22195.	-		
22169	22169.	"	"			22196	22196.	-		
22170	22170.	"	"			22197	22197.	-		
22171	22171.	"	"			22198	22198.	-		
22172	22172.	"	"			22199	22199.	-		
22173	22173.	"	"			22200	22200.	-		
22174	22174.	"	"			22201	22201.	-		
22175	22175.	"	"			22202	22202.	-		
22176	22176.	"	"			22203	22203.	-		
22177	22177.	"	"			22204	22204.	-		
22178	22178.	"	"			22205	22205.	-		
22179	22179.	"	"			22206	22206.	-		
22180	22180.	"	"			22207	22207.	-		
22181	22181.	"	"			22208	22208.	-		
22182	22182.	"	"			22209	22209.	-		
22183	22183.	"	"			22210	22210.	-		
22184	22184.	"	"			22211	22211.	-		
22185	22185.	"	"			22212	22212.	-		
22186	22186.	"	"			22213	22213.	-		
22187	22187.	"	"			22214	22214.	-		
22188	22188.	"	"			22215	22215.	-		
22189	22189.	"	"			22216	22216.	-		
22190	22190.	"	"			22217	22217.	-		
22191	22191.	"	"			22218	22218.	-		
22192	22192.	"	"			22219	22219.	-		
22193	22193.	"	"			22220	22220.	-		
22194	22194.	"	"			22221	22221.	-		
22195	22195.	"	"			22222	22222.	-		
22196	22196.	"	"			22223	22223.	-		
22197	22197.	"	"			22224	22224.	-		
22198	22198.	"	"			22225	22225.	-		
22199	22199.	"	"			22226	22226.	-		
22200	22200.	"	"			22227	22227.	-		
22201	22201.	"	"			22228	22228.	-		
22202	22202.	"	"			22229	22229.	-		
22203	22203.	"	"			22230	22230.	-		
22204	22204.	"	"			22231	22231.	-		
22205	22205.	"	"			22232	22232.	-		
22206	22206.	"	"			22233	22233.	-		
22207	22207.	"	"			22234	22234.	-		
22208	22208.	"	"			22235	22235.	-		
22209	22209.	"	"			22236	22236.	-		
22210	22210.	"	"			22237	22237.	-		
22211	22211.	"	"			22238	22238.	-		
22212	22212.	"	"			22239	22239.	-		
22213	22213.	"	"			22240	22240.	-		
22214	22214.	"	"			22241	22241.	-		
22215	22215.	"	"			22242	22242.	-		
22216	22216.	"	"			22243	22243.	-		
22217	22217.	"	"			22244	22244.	-		
22218	22218.	"	"			22245	22245.	-		
22219	22219.	"	"			22246	22246.	-		
22220	22220.	"	"			22247	22247.	-		
22221	22221.	"	"			22248	22248.	-		
22222	22222.	"	"			22249	22249.	-		
22223	22223.	"	"			22250	22250.	-		
22224	22224.	"	"			22251	22251.	-		
22225	22225.	"	"			22252	22252.	-		
22226	22226.	"	"			22253	22253.	-		
22227	22227.	"	"			22254	22254.	-		
22228	22228.	"	"			22255	22255.	-		
22229	22229.	"	"			22256	22256.	-		
22230	22230.	"	"			22257	22257.	-		
22231	22231.	"	"			22258	22258.	-		
22232	22232.	"	"			22259	22259.	-		
22233	22233.	"	"			22260	22260.	-		
22234	22234.	"	"			22261	22261.	-		
22235	22235.	"	"			22262	22262.	-		
22236	22236.	"	"			22263	22263.	-		
22237	22237.	"	"			22264	22264.	-		
22238	22238.	"	"			22265	22265.	-		
22239	22239.	"	"			22266	22266.	-		
22240	22240.	"	"			22267	22267.	-		
22241	22241.	"	"			22268	22268.	-		
22242	22242.	"	"			22269	22269.	-		
22243	22243.	"	"			22270	22270.	-		
22244	22244.	"	"			22271	22271.	-		
22245	22245.	"	"			22272	22272.	-		



22101	22101.	"	"	View of Intrados, Arch #48.	
22102	22102.	"	"	" " " #49	
22103	22103.	"	"	2 Views of Angle Buttress #49, from A	
22104	22104.	"	"	#49 and Arch #50 sides.	11
22105	22105.	"	"	View of Intrados, Arch #50.	
22106	22106.	"	"	2 Views of Intrados, Arch #51, Bottom	
22107	22107.	"	"	and top.	11-17
22108	22108.	"	"	2 Views of Intrados, Arch #52, Top and	
22109	22109.	"	"	Bottom.	11-17-3
22110	22110.	"	"	View of Intrados, Arch #53.	"
22111	22111.	"	"	2 Views of Intrados, Arch #54, Top and	
22112	22112.	"	"	bottom.	11-17-3
22113	22113.	"	"	View of Intrados, Arch #55.	"
22114	22114.	"	"	View of Intrados, Arch #56.	"
22115	22115.	"	"	2 Views of Intrados, Arch #57.	11-
22116	22116.	"	"	"	"
22117	22117.	"	"	View of Intrados, Arch #58.	11-17-3
22118	22118.	"	"	Spurt through open day's work joint	
22119	22119.	"	"	haunch, Buttress #36 in Arch #36, Elev	
22120	22120.	"	"	View of leakage water measuring stat	
22121	22120.	"	"	Arch #50.	11-20-38
22122	22120.	"	"	Dam #6 Close-up of Anchor bolt hole	
22123				View of leakage water measuring stat	
22124				Arch #50.	11-20-38
22125	22120.	"	"	Dam #6 Close-up of Anchor bolt hole	
22126					
22127					
22128	22121.	Florence Lake Dam	-	View of Extrados of Arch #1 and Upst	
22129	22122.	Florence Lake Dam	-	Buttress 0.	
22130	22123.	Florence Lake Dam	-	Extrados of Arch 2 and West half of	
22131	22124.	Florence Lake Dam	-	Arch 3.	
22132	22125.	Florence Lake Dam	-	Extrados of East Half of Arch 3 and	
22133	22126.	Florence Lake Dam	-	West Half of Arch 4.	
22134	22127.	Florence Lake Dam	-	Extrados East Half of Arch 4 and	
22135	22128.	Florence Lake Dam	-	Arch 5.	
22136	22129.	Florence Lake Dam	-	Extrados Arch 6	
22137	22130.	Florence Lake Dam	-	Extrados of Arches 7 & 8	
22138	22131.	Florence Lake Dam	-	Extrados Arch 9	

22128	22128.	-	Florence Lake Dam	-	Closer view of Angle Buttress No. 10	4-3-39
22129	22129.	-	Florence Lake Dam	-	Extrados of Arches 10 & 11 and	
22130					Upstream face of Angle Buttress 10.	4-3-39
22131	22130.	-	Florence Lake Dam	-	View of Extrados of Arches 12 & 13	4-1-39
22132	22131.	-	Florence Lake Dam	-	View of Extrados of Arches 14 & 15	4-1-39
22133	22132.	-	Florence Lake Dam	-	View of Extrados of Arches 16 & 17	4-3-39
22134	22133.	-	Florence Lake Dam	-	View of Extrados of Arches 17 & 19	4-3-39
22135	22134.	-	Florence Lake Dam	-	" " " " " 20	4-3-39
22136	22135.	-	Florence Lake Dam	-	" " " " " 21 & 22	4-3-39
22137	22136.	-	Florence Lake Dam	-	" " " " " 23	4-3-39
22138	22137.	-	Florence Lake Dam	-	" " " " " 24	4-3-39
22139	22138.	-	Florence Lake Dam	-	View of Extrados of Arch 25 and Upstream	
22140					face of Angle Buttress 25.	4-3-39
22141	22139.	-	Florence Lake Dam	-	View of Extrados of Arch 26	4-3-39
22142	22140.	-	Florence Lake Dam	-	View of Extrados of Arch 27	4-3-39
22143	22141.	-	Florence Lake Dam	-	View of Extrados of Arches 28 & 29	4-3-39
22144	22142.	-	Florence Lake Dam	-	" " " " " 30 & 31	4-3-39
22145	22143.	-	Florence Lake Dam	-	" " " " " 32 & 33	4-3-39
22146	22144.	-	Florence Lake Dam	-	View of Extrados of Arch 34	4-3-39
22147	22145.	-	Florence Lake Dam	-	View of Extrados of Arch 35	4-3-39
22148	22146.	-	Florence Lake Dam	-	" " " " " 36	4-3-39
22149	22147.	-	Florence Lake Dam	-	View of Upstream side of spillway section	4-3-39
22150	22148.	-	Florence Lake Dam	-	View of Extrados of Arch 34	4-3-39
22151	22149.	-	Florence Lake Dam	-	View of Extrados of Arch 35	4-3-39
22152	22150.	-	Florence Lake Dam	-	" " " " " 36	4-3-39
22153	22151.	-	Florence Lake Dam	-	View of Upstream side of spillway section	4-3-39
22154	22152.	-	Florence Lake Dam	-	View of Looking down on Spillway Sec.	4-4-39
22155	22153.	-	Florence Lake Dam	-	View of Upstream side of South half of	
22156					Spillway Section.	4-3-39
22157	22154.	-	Florence Lake Dam	-	View of Extrados of Arches 37 & 38	4-3-39
22158	22155.	-	Florence Lake Dam	-	" " " " " 39	4-3-39
22159	22156.	-	Florence Lake Dam	-	" " " " " 40 & 41	4-3-39
22160	22157.	-	Florence Lake Dam	-	" " " " " 42 & 43	4-3-39
22161	22158.	-	Florence Lake Dam	-	" " " " " 44 & 45	4-3-39





22155

22156

22157

22158

22159

22160

22161

22162

22163

22164

22165

22166

22165

22166

22167

22168

22169

22170

22171

22172

22173

22174

22175

22176

22177

22178

Florence Lake Dam - north side of Buttrick #38

9-23-39

22179

22180

West side of Buttrick #52

22181

Huntington Lake Dam No. 1

9-28-39

22182

Huntington Lake Dam No. 1 (See file card)

9-28-39

22183

22184

22185

22186

22187

22188

22189

22190

22191

22192

No film received

22193

Huntington Lake Dam No. 1.

22192

No film received

22193

Huntington Lake Dam No. 1.

22194

22195

Huntington Lake - Grouting upstream toe at No. end of Dam 3

9-29-39

22196

not received

22197

Huntington Lake Dam No. 1 (See file card)

10-19-39

22198

22199

22200



✓ 22201	Westinghouse - "Discovery" meals - 1st. meal unprepared	1/39
✓ 22202	" " " " prepared	"
✓ 22203	" " " 2nd " unprepared	"
✓ 22204	" " " " prepared	"
✓ 22205	" " " 3rd " unprepared	"
✓ 22206	" " " " prepared	"
✓ 22207	" " " 4th " unprepared	"
✓ 22208	" " " " prepared	"
✓ 22209	" " " 5th " unprepared	"
✓ 22210	" " " " prepared	"
✓ 22211	" " " 6th " unprepared	"
✓ 22212	" " " " prepared	"
✓ 22211	" " " 6th " unprepared	"
✓ 22212	" " " " prepared	"
✓ 22213	" " " 7th " unprepared	"
✓ 22214	" " " " prepared	"
✓ 22215	" " " 8th " unprepared	"
✓ 22216	" " " " prepared	"
✓ 22217	" " " 9th " unprepared	"
✓ 22218	" " " " prepared	"
✓ 22219	" " " Sheriff Biscuit	"
✓ 22220	" " " " " "	"
✓ 22221	" " " " " "	"
✓ 22222	Electric Induction Furnaces - Utility Mfg. Co. Vernon	2/39
✓ 22223	Generator Room	"
✓ 22224	Pouring Steel - Induction	"
✓ 22225	Operator at Induction Panel	"
✓ 22226	Removing Sludge, Induction Furnace	"

✓ 22228	Lacy Air Balance Unit - Hancock Oil - Long Beach	2/39
✓ 22229	Gas Pipe Line Pump - Hancock Oil - Long Beach	"
✓ 22230	Luftkin Pump Unit, Richfield Oil - Long Beach	"
✓ 22231	Luftkin Reduction Gear Unit - Massey & Assoc. Long Beach	"
✓ 22232	Kobe Hydraulic Pump, Allied Petroleum - Long Beach	"
✓ 22233	Chef Coffee master Window - Lobby Entrance	2/39
✓ 22234	Industrial Lighting - Mechanics working light	2/39
✓ 22235	Industrial - Hotpoint factory - Ontario - Making Sand mold	2/39
✓ 22236	" " " Pouring iron scale plates	"
✓ 22237	" " " Ingersoll milling machine	"
✓ 22238	" " " " closeup	"
✓ 22239	" " " Ingersoll milling machine	"
✓ 22238	" " " " closeup	"
✓ 22239	" " " Drawing iron tops	"
✓ 22240	" " " Plating iron tops	"
✓ 22241	" " " Iron Assembly line	"
✓ 22242	Pumping - Oil - Hunt. Beach - Standard Oil P.E. #1 -	2/39
✓ 22243	" " Southwest Exploration Co. State #14	"
✓ 22244	" " " " State #1	"
✓ 22245	" " " " " "	"
✓ 22246	" " Wilshire Oil - Hunt. Bch. #5	"
✓ 22247	" " " " " #17	"
✓ 22248	" " Tidewater - Miley - Keck Lease	"
✓ 22249	" " West American Oil - Kiesel #1	"
✓ 22250	" " Tidewater Assoc. Fowler #5	"
✓ 22251	" " " Gathering Pump	"
✓ 22252	" " General View	"
✓ 22253	" " " " "	"





22301	Brick Co. encroaching on R. of W. on So. Western Ave	2-15-39
22302	" " " " " "	" "
22303	Aviation Field at 92 <sup>nd</sup> + Western Ave	2-9-39
22304	" " " " " "	2-15-39
22305	Airports on Western Ave +	2-9-39
22306	" " " " " "	2-15-39
22307	" " " " " "	2-9-39
22308	" " " " " "	2-15-39
22309	" " " " " "	" "
22310	Mar " East of " " "	" "
22311	Chino Sub - Sw. Bd	2-13-39
22312	" " " " " "	" "
22313	" " " " " "	2-13-39
22312	" " " " " "	" "
22313	" " " " " " Dispatcher's Board	" "
22314	" " " " " "	" "
22315	" " " " " " Disturbance Recorder	" "
22316	" " " " " " Relays - Front	" "
22317	" " " " " " " " - Rear - Conversion	" "
22318	" " " " " " " " " " off	" "
22319	Elec. Cooker (W)	2-14-39
22320	" " " " " "	" "
22321	" " " " " "	" "
22322	" " " " " " G.E.C.	" "
22323	" " " " " "	" "
22324	" " " " " " Proctor	" "
22325	" " " " " "	" "
22326	" " " " " " Everhot	" "
22327	" " " " " "	" "

22328	Accident - D.N. Scott - N. Tyler Ave - El Monte	2-21-39
22329	" " " " " "	" "
22330	" " " " " "	" "
22331	" " " " " "	" "
22332	" " " " " "	" "
22333	" " " " " "	" "
22334	" " " " " "	" "
22335	Accident - Dale Norton S. Berdoo Rd -	" "
22336	" " " " " "	" "
22337	" " " " " "	" "
22338	" " " " " "	" "
22339	" " " " " "	" "
22338	" " " " " "	" "
22339	" " " " " "	" "
22340	Mr. Editor of Laguna - So. Coast News	2-20-39
22341	Elec. Drying machine -	" "
22342	Pr. Press at	" "
22343	Heavy Duty - Blue Green Cat Cafe - S. Ana	" "
22344	" " " " " "	" "
22345	Fullerton J. C. - Lighting - Machine Shop	" "
22346	" " " " " "	" "
22347	" " " " " " - Bank	" "
22348	" " " " " " - Drafting Room	" "
22349	Accident to Car # 3150 (at Sun Ln.)	2-27-39
22350	" " " " " "	" "
22351	" " " " " "	" "
22352	" " " " " "	" "
22353	Night Lighting - Tate's - H. Park	" "
22354	" " " " " "	" "

22355	Night Photo - Tate's (interior) H.P.R.	2-27-39
22356	" " - M + M. Market - So Pas.	"
22357	" " " " " "	"
22358	" " " " " "	"
22359	" " " " " "	"
22360	" " " " " "	"
22361	Electric Home of Mr. Trompeter - Arcadia	3-7-39
22362	" " " " Kitchen	"
22363	" " " " " "	"
22364	" " " " Range	"
22365	" " " " Bath Room	"
22366	Mr. Alhambra Rec. Director	"
22365	" " " " Bath Room	"
22366	Mr. Alhambra Rec. Director	"
22367	Five Girls at Pomona	3-3-39
22368	Comp. Chart - Elec. lamps vs. gas burner -	"
22369	Map. Oil Fields of Calif.	"
22370	Mag. Article - Controlled Directional Drilling	"
22371	" " " " " "	"
22372	" " " " " "	"
22373	" " " " " "	"
22374	Chart - Capacity of Oil Tanks	"
22375	" " " " Small Cylindrical	"
22376	" - Belt Speed - F.P.M.	"
22377	" Wire + Fuse sizes for Motor Br. Cii.	"
22378	" Gravity Index of oil	"
22379	" Delinquent Bills	"
22380	Demonstration Board of Trans. System	3-7-39
22381	" " " " " "	"

22382	Air Conditioning - Savitz Cafe - Ext - L.B.	3-16-39
22383	" " " " Int. - " "	"
22384	" " " " Kay Jewellery Ext. "	"
22385	" " " " Int. "	"
22386	" " " " Cafe Int - Pomona	3-14-39
22387	" " " " 1st Nat. Bank - Uplands Ext "	"
22388	" " " " " " Uplands Int "	"
22389	" " " " City Hall - Front "	"
22390	" " " " Smith Jewellery Store - Redlands - Int "	"
22391	" " " " Courtner's Mortuary Ext "	"
22392	" " " " " " Int " "	"
22393	" " " " Studio Theaters Ext. San Bernardino "	"
22392	" " " " " " Int " "	"
22393	" " " " Studio Theaters Ext. San Bernardino "	"
22394	" " " " Red Chief Motel - Ext. Upland "	"
22395	" " " " " " Int " "	"
22396	Map of Trans. System (Cross)	"
22397	Night Lt. Arn. Ave - Long Beach	2-24-39
22398	" " " " " "	"
22399	Copy - So. Kitchen - Front. Ext. Alhambra	3-16-39
22400	" - Letter - Fed. Sav. + Loan Ass	"



22401	Hotpoint	Range, Miss Robertson	3-25-39
22402	"	" " " "	"
22403	"	" " Front View	"
22404	"	" " Angle	"
22405	"	" " Front	"
22406	"	" " Angle	"
22407	"	" " " "	"
22408	Masterpiece	" " " "	5-15-39
22409	Mr. Johnston, Hermosa Beach Review, & Ludlow	"	"
22410	Poultry Yard, <sup>Elmer</sup> Hausers, Fontana	5-10-39	"
22411	"	Pomona	"
22412	<sup>Glass making</sup> Technical Glass Co., Vernon, Silica Sand	5-19-39	"
22413	"	" " Molten Glass	"
22412	<sup>Glass making</sup> Technical Glass Co., Vernon, Silica Sand	5-19-39	"
22413	"	" " Molten Glass	"
22414	"	" " Glass Blob on Pipe	"
22415	"	" " Blowing Goblet	"
22416	"	" " Blown Goblet	"
22417	"	" " Electric Lehr	"
22418	"	" " Glass Cutter	"
22419	"	" " Finished Goblets	"
22420	Three Fisher Window, 5th St. Entrance	6-6-39	"
22421	Mr. Gage, Alhambra Engineer, & Mary Shoop	6-6-39	"
22422	"	" " Sodium Vapor Ad.	"
22423	Exterior, Bertile Mfg. Co., Ontario	6-7-39	"
22424	Electric Oven	" " " "	"
22425	"	" " " " Unloading	"
22426	Shower Stall	" " " "	"
22427	Empowtive Coder	" " " "	"

22428	Sodium Vapor, Garfield Ave. & Alhambra Rd.	6-12-39	"
22429	<sup>Dairy Series, Elect. Timer</sup> Brewer Feed Mixer - H. Knevelband, Bellflower	6-15-39	"
22430	Perfection Milk - H. Te Velde, Artesia	"	"
22431	Milk Pump - Geo. De Vries, <sup>Novauik</sup> <del>Artesia</del>	"	"
22432	Aerator - Bonnie Dykstra, Artesia	"	"
22433	Walk-in Cooler & H. Lautenbach, Artesia	"	"
22434	Thermador Sterilizer - "Jack" De Vries, Artesia	"	"
22435	Bottling Machine - W. A. Thompson, Hynes	"	"
22436	Brewer Feed Mixer, Geo. De Vries, Artesia	"	"
22437	Electric Kettles, Eto. Delatessen, M-H Mkt. So. Pas.	"	"
22438	"	"	"
22439	Bedminton Lighting, F. Doolittle, Glendale	6-16-39	"
22440	Bride Window, Lobby Entrance	6-16-39	"
22439	Bedminton Lighting, F. Doolittle, Glendale	6-16-39	"
22440	Bride Window, Lobby Entrance	6-16-39	"
22441	Lighting, Ping Pong, Highland Springs, <sup>Bedmont</sup>	6-22-39	"
22442	" Shuffleboard	"	"
22443	Minton home, Redlands, Exterior, Front	6-22-39	"
22444	" " " " Back	"	"
22445	" " " Interior, Kitchen	"	"
22446	" " " Mrs. Minton	"	"
22447	Bottled Milk in Refrigerator. See 22429 -	6-15-39	"
22448	<sup>Industrial</sup> Lighting, Emasco Co., Vernon, Lathe, Good Lighting	6-28-39	"
22449	" " " " Bad	"	"
22450	" " " " Good	"	"
22451	" " " " Bad	"	"
22452	" " " Doorway, Good	"	"
22453	" " " " Bad	"	"
22454	Typewritten Sheet -	"	"



22401	Remodeling Job, Pomona, for Smith slides	5-9-39	9
22402	Interior, Egg Cooker, Fontana Farms, Fontana	5-9-39	
22403	Exterior " " " " " "	"	
22404	Westinghouse Automatic with glass top	5-9-39	
22405	Jane Sinclair's Automatic	"	
22406	" " " " " "	"	
22407	Mother's Day Window, 5th St. Entrance	5-9-39	
22408	Masterpiece " " " " "	5-15-39	
22409	Mr. Johnston, Hermosa Beach Review, & Ludlow	"	
22410	Poultry Yard, <sup>Elmer</sup> Hausers, Fontana	5-10-39	
22411	Glass making: " Pomona	"	
22412	Technical Glass Co., Vernon, Silica Sand	5-19-39	
22413	" " " Molten Glass	"	
22414	" " " Glass Blob on Pipe	"	
22415	" " " Blowing Goblet	"	
22414	" " " Glass Blob on Pipe	"	
22415	" " " Blowing Goblet	"	
22416	" " " Blown Goblet	"	
22417	" " " Electric Lehr	"	
22418	" " " Glass Cutter	"	
22419	" " " Finished Goblets	"	
22420	Three Fisher Window, 5th St. Entrance	6-6-39	
22421	Mr. Gage, Alhambra Engineer, & Mary Shoop	6-6-39	
22422	" " " Sodium Vapor Ad.	"	
22423	Exterior, Pertile Mfg. Co., Ontario	6-7-39	
22424	Electric Oven " " " "	"	
22425	" " " " " Unloading	"	
22426	Shower Stall " " " "	"	
22427	Exposition Cooker " " " "	"	

22428	Sodium Vapor, Garfield Ave. & Alhambra Rd.	6-12-39	
22429	Dairy Series, Elect. Timer Brewer Feed Mixer - H. Knevelband, Bellflower	6-15-39	
22430	Perfection Milkier - H. Te Velde, Artesia	"	
22431	Milk Pump - Geo. De Vries, <sup>Norwalk</sup> <del>Artesia</del>	"	
22432	Aerator - Bonnie Dykstra, Artesia	"	
22433	Walk-in Cooler & H. Lautenbach, Artesia	"	
22434	Thermador Sterilizer - "Jack" De Vries, Artesia	"	
22435	Bottling Machine - W. A. Thompson, Hynes	"	
22436	Brewer Feed Mixer, Geo. De Vries, Artesia	"	
22437	Electric Kettles, Eto. Delestessen, M-H Mkt. So. Pas.	"	
22438	" " " " " "	"	
22439	Bedmont Lighting, F. Doolittle, Glendale	6-16-39	
22440	Bride Window, Lobby Entrance	6-16-39	
22441	Lighting, Ping Pang, Highland Springs, <sup>Bedmont</sup>	6-22-39	
22442	" Shuffleboard " " "	"	
22441	Lighting, Ping Pang, Highland Springs, <sup>Bedmont</sup>	6-22-39	
22442	" Shuffleboard " " "	"	
22443	Minton home, Redlands, Exterior, Front	6-22-39	
22444	" " " " Back	"	
22445	" " " Interior, Kitchen	"	
22446	" " " Mrs. Minton	"	
22447	Bottled Milk in Refrigerator. See 22429 -	6-15-39	
22448	Industrial Lighting, Emasco Co., Vernon, Lathes, Good Lighting	6-28-39	
22449	" " " " " Bad	"	
22450	" " " " " Good	"	
22451	" " " " " Bad	"	
22452	" " " " " Doorway, Good	"	
22453	" " " " " Bad	"	
22454	Typewritten Sheet - " " "	"	



22455	Typewritten Sheet - Industrial Lighting - Good Lighting	6-28-39
22456	Blue Jay Skating Rink, Arrowhead, Welding Pipe	6-30-39
22457	" " " " Freezing Machine	"
22458	Huntington Lake Dam No. 1. (See file card)	10-28-39
22459	" " " " "	"
22460	" " " " "	"
22461	" " " " "	11-14-39
22462	" " " " "	"
22463	" " " " "	"
22464	" " " " "	"
22465	" " " " "	"
22466	" " " " "	"
22467	" " " " "	"
22466	" " " " "	"
22467	" " " " "	"
22468	" " " " "	"
22469	" " " " "	"
22470	Huntington Lake Dam No. 2 Upstream face 1+50 to 3+50	11-16-39
22471	" " " " Upstream face 3+50 to 4+75	"
22472	" " " " " 4+75 to 6+00 to Backfill	"
22473	" " " " (See file card)	"
22474	" " " " "	"
22475	" " " " "	"
22476	" " " " "	"
22477	" " " " "	"
22478	" " " " "	"
22479	" " " " "	"
22480	" " " " "	11-14-39
22481	" " " " "	11-16-39

22482	Huntington Lake Dam No. 2 (See file card)	11-16-39
22483	" " " " "	"
22484	" " " " "	"
22485	Huntington Lake Dam No. 3	"
22486	" " " " "	"
22487	" " " " No. 1 Limited sec. 8+70 to East (no neg.)	11-28-39
22488	Huntington Lake Dam No. 1 (See file card)	11-30-39
22489	" " " " "	"
22490	Huntington Lake Dam No. 1 (No neg. received) Limited sec.	11-28-39
22491	" " " " " " " " at Sta. 9+50	"
22492	Huntington Lake Dam No. 1. (See file card)	11-30-39
22493	" " " " "	"
22494	" " " " "	"
22493	" " " " "	"
22494	" " " " "	"
22495	Huntington Lake Dam No. 1 (No neg. received)	11-28-39
22496	Huntington Lake Dam No. 1 (No neg. received)	11-28-39
22497	Huntington Lake Dam No. 1 (See file card)	11-28-39
22498	" " " " "	"
22499	" " " " "	"
22500	" " " " "	"

22501	Chart - Cost of Service for 6 Rm House -	3-15-39
22502	" " " " 7 " " "	"
22503	" Bad Debt.	"
22504	" of Chino Disturbance Recorder. V. Cht.	3-22-39
22505	Travel Recorder Mechanism (Hunt)	3-27-39
22506	Heating Element for Elec. Brooder	"
22507	Sam Gates presents \$1000 <sup>to Mr. Niebecker</sup> Ch. for improved home	3-23-39
22508	" " " " " "	"
22509	Elec. Home of H. Park	3-22-39
22510	" Kitchen	"
22511	Mfr. Mgr. - H. Park Signal	3-28-39
22512	Linotype Machine at " "	"
22513	Copy of Twp. Map - Tw 20 R. 23 W.	3-21-39
22512	Linotype Machine at " "	"
22513	Copy of Twp. Map - Tw 20 R. 23 W.	3-21-39
22514	" " " " 24 "	"
22515	" " " " 25 "	"
22516	" " " " 26 "	"
22517	" " 21 R 23	"
22518	" " " " 24	"
22519	" " " " 25	"
22520	" " " " 26	"
22521	" " 22 R 23	"
22522	" " " " 24	"
22523	" " " " 25	"
22524	" " " " 26	"
22525	" " 23 R 23 E	"
22526	" " " " 24 "	"
22527	" " " " 25 "	"

22528	Copy of Map - Twp 23 R. 26 E	3-21
22529	" " " 24 R 24 E	"
22530	" " " 24 " 25 "	"
22531	" " " " 26 "	"
22532	Vernon Plant - Sw. Racks	3-29-39
22533	" " " " "	"
22534	" " Rear Panel	"
22535	" " Trans	"
22536	" " " "	"
22537	Accident - Rear of #5143 E. R. Blvd.	3-30-39
22538	" " " "	"
22539	" " " "	"
22540	" " " "	"
22539	" " " "	"
22540	" " " "	"
22541	" " " "	"
22542	" " " "	"
22543	" " " "	"
22544	" " " "	"
22545	" " " "	"
22546	" " " "	"
22547	" " " "	"
22548	Dairy - Copy - Sterilizer	4-39
22549	Sodium-Vapor - Night - S. Berdo	4-7-39
22550	" " " Redlands Y	"
22551	" " " Inglewood - Firestone Blvd	4-11-39
22552	Pumping Plant of Placentia	4-10-39
22553	Copy of letter from M+M Market - So Pas.	3-17-39
22554	Gpy of Dispatchers Display Board	4-39



22555	Copy of Weather Charts of Calif - July Mean Temp	4-13-39
22556	" " " " Humidity	"
22557	" " " " " "	"
22558	" " " " Dry Bulb Temp.	"
22559	" " " " " "	"
22560	" Chart - Elec Power in Petroleum Industry (Howe)	"
22561	" " Annual Sales to Domestic Customers	"
22562	" " U.O.Co. Voltage & Light Output	"
22563	Dist. Poles with Dry Rot	4-3-39
22564	" " " " " "	"
22565	" " " " " "	5-2-39
22566	Heat Exchanger at Vernon Plant	4-20-39
22567	" " " " " "	5-2-39
22568	Heat Exchanger at Vernon Plant	4-20-39
22569	" " " " " "	"
22570	Ben Fairbrother - Ch. of Police of Inglewood	4-5-39
22571	" " " " " "	"
22572	Light Standard at Bell	4-13-39
22573	" " " " " "	"
22574	" " " " " "	"
22575	" " " " " "	"
22576	" - Other party's Car # 9T-4822	4-22-39
22577	" " " " " "	"
22578	" " " " " "	"
22579	" " " " " "	"
22580	Governor Mine at Acton	4-24-39
22581	" " Mill - " "	"

22582	Accident at R.R. Crossing at Puente	4-25-39
22583	" " " " " "	"
22584	" " " " " "	"
22585	" " " " " "	"
22586	" " " " " "	"
22587	" " " " " "	"
22588	Television Rec. Set at Long Beach	4-26-39
22589	Brick yard encroachment on R. of W. at West 174 St.	"
22590	" " " " " "	"
22591	Accident to Fred W. Orr Tower # 10, 16 Eagle Rock	4-1-39
22592	" " " " " "	"
22593	" " " " " "	"
22594	" " " " " "	"
22595	" " " " " "	"
22596	" " " " " "	"
22597	" " " " " "	"
22598	" " " " " "	"
22599	" " " " " "	"
22600	" " " " " "	"

(See next page)

22601	Accident to F.W. Orr (Fatal) T.6 MO - Eagle Rock	5-1-39
22602	" " " " " "	"
22603	" " " " E-Tower "	5-4-39
22604	" " " " " "	"
X 22605	" " " " " "	"
22606	Hansen Dam Tower Line Change - S.W. Headquarters -	5-3-39
22607	" " " " Exc. for Tower # 227 E+W	"
22608	" " " " " " 226-3E	"
22609	Tower 227-5 Boulder Line -	"
22610	" 229-3 " " (Trees Trimmed)	"
22611	" Exc. at 3-3 on China - Barre Line	"
22612	" " " 4-1 " " " "	"
22613	" Exc. at 3-3-4-1+4-3 on China - Barre Line	"
22612	" " " 4-1 " " " "	"
22613	" " " 3-3-4-1+4-3 " " " "	"
22614	Site of Barre Sub - Well driller on job	"
22615	Garden Lighting at Frank Hansen's	"
22616	" " " " " "	"
22617	" " " " " "	"
22618	Elec. Home - 500 - Ext. - Alhambra	5-4-39
22619	" " " " Kitchen "	"
22620	" " " " " "	"
22621	" " 505 - Ext " "	"
22622	" " " " Kitchen "	"
22623	" " Mrs Hargrove " "	5-11-39
22624	" " Mrs Clayton Whitman apt - Monterey Park	"
22625	" " " " Kitchen " "	"
22626	" " " " " " " "	"
22627	" " " " Living Room " "	"

22628	Night - St. Lt. H. Pk. - 57 <sup>th</sup> + Pac. (After)	5-12-39
22629	" " " " 56 " " (Before)	"
22630	" - Auto Sales Room - Fudge -	"
22631	Copy of old map of Long Beach Channel	"
22632	" " " " " "	"
22633	" " " " " "	"
22634	" " " " " "	"
22635	" " " " " "	"
22636	Hotpoint Windsor Rouge & Miss Robertson	3-25-39
22637	" " " " " "	"
22638	" " " " Front	"
22639	" " " " Angle	"
22638	" " " " Front	"
22639	" " " " Angle	"
22640	" Salisbury " Front	"
22641	" " " " Angle	"
22642	" " " " " "	"
22643	Accident - Edison Truck - 3 <sup>rd</sup> + Park Way L.B.	4-22-39
22644	" " " " " "	"
22645	" " " " " "	"
22646	Chart - G. E. Psychrometric - (Douglas)	5-1-39
22647	" Temp. at Fresno -	"
22648	Copy (Flo. Lake Dam report by Dennis Page 1	5-15-39
22649	" " " " 2	"
22650	" " " " 3	"
22651	" " " " 4	"
22652	" " " " 5	"
22653	" " " " 6	"
22654	" " " " 7	"



22655	Pump Plant of Dr Chas H. Allen - Ontario	5-18-39
22656	News Paper Office of San Bernardino Sun - Mr L. L. Mc Fall	"
22657	" " " " - Linotype Mach.	"
22658	Glen W. Garwood - Supt. of Parks - So. Pasadena	"
22659	Elec. & Gas Range Comb.	5-19-39
22660	" " " " " "	"
22661	School Lighting - Before - Carmanita Ave - Whit. Dist -	5-23-39
22662	" " " " " " After -	"
22663	Lighting - Bowling Alley - Ext - H. Park	5-26-39
22664	" " " " " " - Int.	"
22665	" " " " " " " "	"
22666	" " " " " " " "	"
22665	" " " " " " " "	"
22666	" " " " " " " "	"
22667	" " Hi Lo Market - Night	25
22668	" " " " " " " "	"
22669	" " Race Track - Night - Midget Cars - S. Bedno	5-26-39
22670	" " " " " " " "	"
22671	" " Box Market - Ext - Night - Whittier	5-31-39
22672	" " " " " " " " Int	"
22673	" " Machine Shop " " " "	"
22674	Trans Line - Near Hansen Dam	"
22675	" " " " " " " "	"
22676	" " " " " " " "	"
22677	" " " " " " " "	"
22678	" " " " " " " "	"
22679	" " " " " " " "	"
22680	" " on Barre-Chino Line	"

22682	Trans Line - Barre-Chino - at Tower	Lk So. 5-31-39
22683	Barre Sub - Genl View	6-1-39
22684	" " " " " " Forms in for foundation of Control House	"
22685	" " " " " " Setting forms & boring holes for piling	"
22686	" " " " " " " " " "	"
22687	" " " " " " Piling in place	"
22688	" " " " " " Well & Pump	"
22689	Lighting - All Souls Church - Int. Alhambra	6-6-39
22690	" " " " " " " "	"
22691	" " " " " " Swanberger's Store for Men - Santa Ana	6-9-39
22692	" " " " " " " "	"
22693	" " " " " " " "	"
22692	" " " " " " " "	"
22693	" " " " " " " "	"
22694	" " " " " " " "	"
22695	Heavy Duty - Jones Cafe - L.B. - G & E. Range	6-14-39
22696	" " " " " " " "	"
22697	" " " " " " Battery of Roosters	"
22698	" " " " " " " "	"
22699	Accident - Portraits of Chas Walker	A-B-C 6-19-39
22700	" " " " " " " " A-B-C	"





22755	Core samples removed from Florence Lake Dam	8-16-39
22756	" " " " " "	"
22757	" " " " " "	"
22758	" " " " " "	"
22759	" " " " " "	"
22760	Tower Lighthouse-Barre Line, (neg. no. 17 S&W) mural trans.	8-1-39
22761	Rack at Barre Sub. (neg. no. 20 S&W)	"
22762	Barre Sub (S&W neg. no. 8-352) Frasher's Inc. Ord. no. 1408-SW.	9-13-39
22763	" " " " " 8-353	"
22764	" " " " " 8-354	"
22765	" " " " " 8-355	"
22766	Chino-Barre Line (S&W neg. no. 8-356)	"
22767	" " " " " 8-357	"
22768	Chino-Barre Line (S&W neg. no. 8-356)	"
22767	" " " " " 8-357	"
22768	" " " " " 358	"
22769	" " " " " 359	"
22770	So. Cal. Edison Co. - Commercial Office - Vernon, 4314 Santa Fe	9-19-39
22771	" " " " " "	"
22772	Maywood Drug Co. 5901 Atlantic Blvd. Maywood.	9-26-39
22773	Chas. L. Brown Service Sta. 3126 E. Florence Ave. 1 Hg. Park	"
22774	Barre Sub. V. of Control House, Transf. Hoist, etc. S&W #16	10-9-39
22775	" " View of 66 K.V. rack from N.W. S&W #17	10-9-39
22776	" " View of 220 K.V. rack, Condenser rack, etc. S&W #18	10-9-39
22777	Boulder Chino Trans. Line. Broken strand found on N. conductor 115' E. (no. 2280) 8 Tower 81-2	10-6-39
22778	Crystal Dam	9-8-39
22779	Discharge Channel Eagle Dam	9-7-39
22780	Eagle Lake	9-7-39
22781	Upstream face Eagle Dam	9-7-39

22782	Sierra Ontario #2 Intake. Gen. View	11-24-39
22783	Sierra Forebay and Energy Absorber. (Old Ontario #2 P.H. Site)	"
22784	Sierra Power House - Interior view.	"
22785	Sierra Power House and Ontario #1 Intake	"
22786	Concrete Cores, Htg. Lake Dams 1, 2, & 3. U1-17, 18 & 19	11-24-39
22787	" " " " U1-20, 21 & 22	"
22788	" " " " 2-7, 8, 9, 10 & 11	"
22789	" " " " 3-5, 6, & 7	"
22790	" " " " 3-8, 9, & 10	"
22791	Installations of 2-600 H.P. - B&W Balers - Bakersfield - Front View	12-7-39
22792	" " " " " Rear view	"
22793	Florence Lake Tunnel, Cp. 63 B.C. (M-71)	
22794	" " Cp. 62 B.C. Timber Section (M-42) Rear view	
22793	Florence Lake Tunnel, Cp. 63 B.C. (M-71)	
22794	" " Cp. 62 B.C. Timber Section (M-43)	
22795	" " Cp. 62 B.C. Passing steel (M-35)	
22796	Kangaroo Court, Cp. 62, B.C. (M-41)	
22797	" " Cp. 62, B.C. (M-38)	
22798	" " Cp. 62, B.C. (M-50)	
22799	Warehouse, Cp. 63, B.C. (M-73)	
22800	Cold Storage - Cp. 63, B.C. (M-74)	

22801	Huntington Lake Dam No. 1 (See file card)	11-28-39
22802	" " " "	"
22803	" " " "	"
22804	" " " "	"
22805	" " " "	"
22806	" " " "	"
22807	" " " "	"
22808	" " " "	"
22809	" " " "	"
22810	" " " "	"
22811	Huntington Lake Dam No. 2 (See file card)	"
22812	" " " "	"
22813	Huntington Lake Dam No. 3	"
22814	" " " " No. 1 Completed granite. (No neg. received)	"
22813	Huntington Lake Dam No. 3	"
22814	" " " " No. 1 Completed granite. (No neg. received)	12-12-39
22815	Huntington Lake Dam No. 1 (See file card)	12-12-39
22816	" " " "	"
22817	" " " "	"
22818	Huntington Lake Dam No. 2	"
22819	" " " "	"
22820	" " " "	"
22821	" " " "	"
22822	" " " "	"
22823	" " " "	"
22824	" " " "	12-18-39
22825	" " " "	"
22826	San Joaquin River above P.H. #8 showing results of fire on earth	1-5-40
22827	" " " " Gaging station	"

22828	San Joaquin River - Looking upstream, etc.	1-5-40
22829	" " Looking down on south side, etc.	"
22830	Florence Lake Dam, Arch #1, after extrados inspection	3-19-40
22831	" " " " #2 " " "	3-19-40
22832	" " " " #3 " " "	3-19-40
22833	" " " " #4 " " "	3-19-40
22834	" " " " #5 " " "	3-19-40
22835	Cores #7, 8, 9, 10 & 11 Cut from upstream face of Dam #2	12-21-39
22836	Cores #5, 6, 7, 8, 9 & 10 Cut from upstream face of Dam #3	"
22837	Views of Stator ring of #2 Generator, K.R. #1 (taken by J.C. Staver)	1-8-40
22838	" " " " " " "	"
22839	" " " " " " "	"
22840	Dam 6 - Upstream Gates 3 & 4	"
22839	" " " " " " "	"
22840	Dam 6 - Upstream Gates 3 & 4	12-3-39
22841	" " Genl. view looking towards Dam 6	"
22842	" " Excavating around upstream gates #1 & 2	"
22843	" " " " " " "	"
22844	" " " " " " "	"
22845	" " Trash bars around gates 3 & 4	"
22846	" " Excavating around upstream gates #1 & 2	"
22847	" " " " " " "	"
22848	" " " " " " "	"
22849	" " " " " " "	"
22850	Moving multi circuit Tower at mi. O Tower to El Modena Ave. E. Rock	1-25-40
22851	" " " " " " "	"
22852	" " " " " " "	"
22853	" " " " " " "	"
22854	" " " " " " "	"



22855	Moving multi circuit Tower at mo. Tower 6, El Modeno Ave. Eagle Rock	1-25-40
22856	" " " " " "	"
22857	" " " " " "	"
22858	" " " " " "	"
22859	" " " " " "	"
22860	" " " " " "	"
22861	" " " " " "	"
22862	" " " " " "	"
22863	Florence Lake Dam - Drilling 6" core from staging extrados Arch #16	Mar. 1940
22864	" " " Chipping for downstream " #6	Feb. "
22865	" " " Close up of thermometer resistance " #6	"
22866	Florence Lake Dam - Arch #18 after extrados inspection	Mar. 1940 4-17-40
22867	" " " " 21 " " " " " "	"
22868	" " " " " 20 after extrados inspection	Mar. 1940 4-17-40
22867	" " " " " 21 " " " " " "	"
22868	" " " " " 22 " " " " " "	"
22869	" " " " " 23 " " " " " "	"
22870	" " " " " 52 " " " " " "	4-13-40
22871	" " " " " 13 Chipping seams	4-21-40
22872	" " " " " 40 & 41 " " " " " "	"
22873	" " " " " 40 " " " " " "	4-18-40
22874	" " " " " 37 Chipping diagonal crack	4-21-40
22875	" " " " " 37 Diagonal crack on left side	4-23-40
22876	" " " " " 13 Guniting on Arch 13 & chipping on Arch 14	"
22877	" " " " " #51 after guniting	4-18-40
22878	" " " " " #19 Chipping on Arch 19	4-28-40
22879	" " " " " #17 Close-up of seam	4-25-40
22880	" " " " " No. 2 of cycle of 7 chipping out seam	4-25-40
22881	" " " " " No. 3 of cycle of 7	"

22882	Florence Lake Dam - No. 4 of cycle of 7	4-27-40
22883	" " " No. 5 " " " 7	"
22884	" " " No. 6 " " " 7	"
22885	" " " No. 7 " " " 7	4-28-40
22886	" " " Guniting extrados of Arch 2	5-23-40
22887	" " " " " " 2 (close up)	"
22888	" " " Crotch bet. Arches 1 & 2	"
22889	" " " Extrados of Arch #9	6-19-40
22890	Flo. Lake Dam Walkway repair. See index card.	7-2-40
22891	" " " " " " " "	7-7-40
22892	" " " " " " " " Close up	7-13-40
22893	" " " " " " " " Progress picture	"
22894	" " " " " " " " - wire up	7-13-40
22893	" " " " " " " " Progress picture	"
22894	" " " " " " " " " " " "	"
22895	" " " " " " " " " " " "	"
22896	" " " " " " " " " " " " showing gunite machine.	June 1940
22897	" " " " " " " " " " " " Intrados of Arch 9. (See index card)	7-7-40
22898	" " " " " " " " " " " " " 8 " " " "	"
22899	" " " " " " " " " " " " " 7 " " " "	"
22900	" " " " " " " " " " " " " 2 " " " "	7



22901	Florence Lake Dam - Completed walkway.	9-6-40
22902	" " " Upstream face of spillway.	"
22903	" " " showing guniting	"
22904	" " " Guniting at South end of spillway	9-14-40
22905	" " " Guniting around drum gate intake.	"
22906	" " " Replacement of concrete floor of intake.	"
7/ 22907	B.C.#1 Close view of damaged generator cables & potheads (see file card)	7-16-40
22908	B.C.#1 " " " " " "	"
22909	B.C.#1 Close up views showing damage to neutral current transf.	"
22910	" " " " " gend turns, stator coils etc. (see index card)	"
22911	" " " " " showing burned stator coils, etc. (see index card)	"
22912	Htg. Lake Dam No. 1, showing extent of settlement	5-3-40
4/ 22913	Temperature corrections for chaining (L.A. Matthews)	4-16-40
4/ 22914	Elev. Lake Dam No. 1, showing extent of settlement	5-3-40
4/ 22915	Temperature corrections for chaining (L.A. Matthews)	4-16-40
4/ 22916	Elevation of El Porto Sub. (no negative in file)	"
22917	Condenser Fullerton Sub.	4-22-40
22918	Sew. Board Panel Fullerton Sub.	"
22919	Condenser Fairview Sub.	"
22920	Sew. Bd. Panel - Fairview Sub.	"
10/ 22921	B Creek Misc. B 579 steel Penstock section on truck	
10/ 22922	" " B. 595 " " " "	
22923	Heading bench Cp. 63, B.C. Florence Tunnel	
10/ 22924	B.C.-3 - Dam & Intake Tower	
22925	B.C.-3 Intake tower	
10/ 22926	BC 3 Manifold steel on truck.	
10/ 22927	Florence Lake Dam B-542 and Reservoir	
22928		

✓ 22928	Sluice Gate in Florence Lake Dam	12-3-25
10/7 22929	Ball game at Cp. 62 B.C. (M-36)	Florence tunnel
10/7 22930	Machine Doctor's Bench Cp. 62 (M-46)	" "
" 22931	West End Dining Room Cp. 62 B.C. (M-31)	" "
" 22932	Tool Sharpening Shop Cp. 63 B.C. (M-15)	" "
10/7 22933	Dining Room Cp. 63 B.C. (M-60)	" "
10/7 22934	B.C. 3	
10/7 22935	BC 2A. Y Branch (37A) Penstock pipe	
10/7 22936	BC 2A " " (34A) " "	
" 22937	P.H. 2A. Transf. crossing bridge	
" 22938	Cp 7.5 intake to P.H. 2 (B600) B.C. 1	
" 22939	B.C. 2A. Pelton Water (3023) wheel nozzle assembly (Copy)	
" 22938	Cp 7.5 intake to P.H. 2 (B600) B.C. 1	
" 22939	B.C. 2A. Pelton Water (3023) wheel nozzle assembly (Copy)	
" 22940	Drafting Room - Eng. Dept. Boylston St. (Copy) (PI Personnel)	
" 22941	Big Creek 2A. Pipe (3497-A) fabrication (Copy)	
" 22942	Shaver Dam - Pouring (B458) foundation (Copy)	
" 22943	BC 2A pipe fabrication (3651-A) (Copy)	
" 22944	" " " (2652-A) (Copy)	
" 22945	" " " (3589-A) (Copy)	
" 22946	S.G. & E. Ly. Scene along (934) railroad. (Copy)	
" 22947	" " " (913) " (Copy)	
" 22948	S.G. & E. Locomotive (296) (Copy)	
10/7 22949	" Scene along (357) road. (Copy)	
5-17-40 22950	Florence Lake Dam - Mr. Redinger, Mr. Waugh, Mr. Holmes 5-17-40	
" 22951	" " " Experimental Coatings	
" 22952	Detail Arch 8 J.M. "Asbestile" coating	
" 22953	"Insulmastic" Coating Arch 7	
" 22954	Arch #2 Basin t. " " " " " "	



✓ 22955	Florence Lake Dam Arch #2	5-17-40
22956	" Notching joint Arch #2	"
✓ 22957	Applying "carbozite", primer Arch #9	"
✓ 22958	Florence Lake Spillway, Detail	"
✓ 22959	Acid water etched surface Florence Lake Spillway	"
✓ 22960	Florence Lake Dam Spillway training wall	"
✓ 22961	Florence Lake Dam River Section (approximate water level)	"
✓ 22962	F.L. Dam Arch intrados E. of spillway typical spalling due to $\text{NaCO}_3$ cry	"
✓ 22963	Dam #5	5-18-40
✓ 22964	Dam #6	"
✓ 22965	P.H. 8 unit 2 spare 42,200 H.P. runner	"
✓ 22966	Stevenson Creek - Test Dam	"
✓ 22967	Penstock 3	"
✓ 22968	P.H. 3 Penstock Creek - Test Dam	"
✓ 22967	Penstock 3	"
✓ 22968	P.H. 3 Penstock banding	"
✓ 22969	P.H. 3 Spherical manifolds	"
✓ 22970	Detail spherical manifold	"
✓ 22971	P.H. 3, 38,400 H.P. Turbine runner (nr. Chesson in picture)	"
✓ 22972	Ward Lake	5-17-40
✓ 22973	Ward Lake	"
✓ 22974	Specimens after 20° F. Ductility Test	6-14-40
✓ 22975	Edison Cottage - Marine Sub. - Radio Tower. Oliveras Suit	"
✓ 22976	Oliveras house near Marine Sub. Radio Tower	"
✓ 22977	Radio Tower - Marine Sub.	"
✓ 22978	" " " "	"
✓ 22979	" " " "	"
✓ 22980	B.C. 2-A Pelton Water Wheel Assembly (copy)	7-9-40
✓ 22981	Cp. 63, Big Creek Dining Room (copy)	"

✓ 22982	Florence Lake Tunnel, Cp. 62, Concrete mixer (M66)	7-9-40
✓ 22983	Camp 62 Big Creek (M50)	"
✓ 22984	West Heading, Florence Tunnel, Cp. 61, Big Creek	"
✓ 22985	Driving Tunnel in soft ground, Florence Tunnel Cp. 61, B.C.	"
✓ 22986	Florence Lake Tunnel, sand & water run, intake heading	"
✓ 22987	" " Emergency pumping sta. in 61 West Heading	"
✓ 22988	Florence Lake Tunnel Intake upstream venturi meter lining	"
✓ 22989	" " Reservoir, as seen from Kaiser Ridge	8-19-40
✓ 22990	Train leaving El Prado S.G. & E. Ry. N31450	1-12-13
✓ 22991	Setting Tower footing stubs by direct measurement B.Chino	9-5-40
✓ 22992	Driving 30' Piles below ground surface (See index card) B.Life	9-9-40
✓ 22993	Excavating for concrete caps ahead of Pile Driver Boulder Chino	9-9-40
✓ 22994	Driving 30' Piles below ground surface (See index card) B.Life	9-9-40
✓ 22993	Excavating for concrete caps ahead of Pile Driver Boulder Chino	9-9-40
✓ 22994	Erecting Pole for Wood H-Frame (See file card) Chino Cap	"
✓ 22995	Erecting Steel H-Frames by hand at inaccessible location	"
✓ 22996	View of Camp No. 1 at mile 32 (B.C. Trans. Line)	7-5-40
✓ 22997	Making up Reinforcement Cages for concrete Piles (B.Chino)	"
✓ 22998	Drilling for concrete pile foundations Boulder Chino	"
✓ 22999	Pouring Cast-in-place Concrete Piles Boulder Chino	"
✓ 23000	Pomona Commercial Office. (By The Mott Studios)	5-1-44



23001	Auto of E. F. Waycott damaged on Co. prop. near SAR 3, 5-7-40	6-10-40
23002	" " " " " "	"
23003	" " " " " "	"
23004	" " " " " "	"
23005	K.R. #3 Flume 15-16	6-10-40
23006	K.R. #3 Flume #16-17 showing spalling of concrete	"
23007	K.R. #3 Sandbox, showing spalling of concrete beams	"
23008	K.R. #3 #2 Unit relief valve piston (Feb. 1940)	"
23009	Preparing Florence Lake Dam Arches 7, 8, 9 for test coatings	5-12-40
23010	Chipped and hammered surface, Arch 8	"
23011	"Snogs" at 61-C	5-11-40
23012	Kaiser Pass	"
23013	"Cat." plowing snow near old 61-C	"
23012	Kaiser Pass	"
23013	"Cat." plowing snow near old 61-C	"
23014	"Cat." and sled transportation over Kaiser Pass	"
23015	Hunt. Lake dam #1, fill subsidence	"
23016	D.H. Redinger on Kaiser Pass	"
23017	Typical rock "carving" near Florence Lake Dam spillway	5-12-40
23018	Typical plug and feather rock "carving" west end Florence Lake Dam	"
23019	Dam 4	5-11-40
23020	Dam 4	"
23021	Back hammering surface arch 7, F.L. dam	"
23022	Huntington Lake spillway	"
23023	1/33 Enamel after 21 cycles in weatherometer. Bitumastic Aluminum Paint	6-13-40
23024	16 Hemastic after 21 cycles in weatherometer Bitumastic Paint	"
23025	28 asphalt Emulsion, Royal Picta Co. after 21 cycles in weatherometer	"
23026	31 Pioneer asph. Emulsion after 21 cycles in W. Stephenson R.M.S. Aluminum Paint	"
23027	12 Carbogite after 14 cycle in W. Carbogite Aluminum Paint	"
23028	31 Asphalt Emulsion, non-corrosive P.O. Co. after 21 C. in weatherometer	"
23029	12 Bitumastic 70B after 21 C. in weather. Bitumastic Aln. Paint	"
23030	27 Arco Burn Gum " " " " " "	"
23031	34 Armo Coat Cement Floor Paint 21 cycles in weatherometer	"

23028	43 Johns. Manville Asbestos after 21 C. in W. meter	6-15-40
23029	18 Carbogite V. Containing Vermiculite, after 43 C. in W. meter	"
23030	71 Somaastic mix A. after 21 C. in W. meter	"
23031	6 Somaastic with white wash covering Plant mix, after 21 C. in W. meter	"
23032	Specimens used in cracking, crazing and sag tests	6-14-40
23033	Bond Test Specimens after testing	"
23034	Specimens used in Cracking, Crazing & sag Tests	"
23035	Special Freezing & Thawing eye Test on Somaastic. Note broken Bond with concrete	"
23036	Bond Test Specimens after testing	"
23037	Specimens used in cracking, crazing & sag tests	"
23038	Spec. after special test of timber facing on hercost 60 lbs. sq. in. cone pressure, etc.	"
23039	Close up of Union Oil Co. Asphalt membrane after cracking & crazing test	"
23040	Close up of Specimen in Bond Test	"
23041	General view of Refrigerator and Equipment	"
23042	View of large oven	"
23043	General view of Refrigerator and Equipment	"
23044	View of large oven	"
23045	Apparatus for Permeability Tests. Test in progress.	"
23046	Slow motion Testing machine in Refrigerator & accessory Equip. etc.	"
23047	Ultra Violet Light machine. Specimens in place.	"
23048	Standard Weatherometer. Specimens in place.	"
23049	General View of Testing Machine used in Bond Tests. Specimens in place.	"
23050	Specimens used in Cracking, Crazing & Sag Tests	"
23051	Permeability Tests, Specimens after testing	"
23052	Specimens used in Cracking, Crazing & Sag Tests	"
23053	Bond Test Specimens after testing	"
23054	Sag Test Assembly for use in large oven	"
23055	Spec. Test of Barnett Membrane. Specimen after Shear Test, etc.	"
23056	Bond Test Specimens after testing	"
23057	Florence Lake about 4:30 PM (See file card)	6-11-40
23058	Edison Cottage Marine Sub. Radio Tower	6-11-40
23059	Florence Lake about 4:30 PM (See file card)	6-11-40
23060	Cliveras house near Marine Sub. Radio Tower sent	6-11-40
23061	Florence Lake about 4:30 PM (See file card)	6-11-40
23062	Radio Tower Marine Sub. Cliveras sent	6-11-40



## Small Films

10/7 23055	Florence Lake about 4:30 PM (See file card) <del>Radio Tower - Marine Sub</del> Oliveras, Smit	6-11-40 6-24-40
" 23056	Florence Lake about 5:00 PM <del>Radio Tower - Marine Sub</del> Oliveras, Smit	6-11-40
" 23057	Florence Lake about 6:15 PM (See file card)	6-11-40
" 23058	West end Florence Lake Dam	7-3-26
10/7 23059	Florence Lake Dam Excavation for river section	4-30-28
" 23060	Highgrove Plant Site Looking up stream at Old Highgrove pl. site	6-26-40
" 23061	" " " Showing penstock discharge	6-26-40
10/7 23062	" " " Forebay chamber, note section of penstock <sup>proximity of main highway</sup>	"
10/7 23063	" " " View of Highgrove forebay chamber from Highway	"
23064	Proposed Forebay road location. Holland Summit looking N.W.	7-30-40
" 23065	" " " bet. " " & Forebay	"
23066	Structures at end of flume. (See card index for more details)	"
23067	" " " " " " " " " " " "	"
23068	Structures at end of flume. (See card index for more details)	"
23067	" " " " " " " " " " " "	"
23068	Gate house at end of flume and the top of penstock	"
23069	Say "when" ("Atlas" Kulberg)	"
23070	Looking upstream from Sta. 291+00 (S.T. Oscar in lead)	"
23071	Looking down stream from Sta. 269+00	"
23072	O.N. Kulberg and H.A. Barber at Godby Rock.	"
23073	" " " " " " " " " " " "	"
23074	Looking downstream from Sta. 259+00	"
23075	Looking back at bad stretch from Sta. 257+00	"
23076	Looking back from Sta. 246+00	"
23077	Looking upstream from Sta. 214.50	"
23078	Looking upstream at Grand Canyon from Sta. 133+00	"
23079	" " " near Slick Rock Canyon	"
23080	Flume from Sta. 69+00	"
23081	Flume near upper end.	"

## Small Films

23082	Flume from Sta. 13+00 at old sandbox	7-30-40
23083	Looking downstream from suspension bridge near intake	"
23084	Intake structure showing gate stem and racks. Kaweah #1 P.H.	"
23085	Diversion dam at intake (East Fork of Kaweah River)	"
23086	Looking down the flume showing fish wheel (See index cards)	"
23087	Flume intake structure, showing radial gate at right	"
23088	Exterior view of Kaweah Ph. #1	"
23089	Main entrance of P.H. #1	"
23090	One of the original units now as a monument.	7-30-40
10/7 23091	A.B. Chance - suspension tools. Live Line tools	7-30-40
" 23092	Edison. " " " " " "	"
" 23093	" " " " " " " " " "	"
23094	A.B. Chance Demonstration Trailer	"
23095	A.B. Chance - suspension tools Live Line Tools	"
23096	" " " " " " " " " "	"
10/7 23097	Gen. view of the river section of Fl. Lake	11-12-25
10/7 23098	Florence Lake Dam, Arch 53	12-3-25
" 23099	<sup>Vermilion Valley</sup> East from Granite Knob. Vermilion Valley.	8-31-40
23100	<sup>Vermilion Valley</sup> Up Mono Creek from Granite Knob. Ver. Valley.	8-31-40
10/7 23101	<sup>Vermilion Valley</sup> East from N. end of Ver. Valley dam site	8-31-40
10/7 23102	<sup>Vermilion Valley</sup> East along N. leg of Ver. Valley dam site	8-31-40
23103	<sup>Vermilion Valley</sup> N.E. at junction of Mono. & Cold creek <sup>Ver. Valley dam site</sup>	8-31-40
10/7 23104	<sup>Vermilion Valley</sup> E. near E. end of dam. Ver. valley dam site	8-31-40
" 23105	<sup>Vermilion Valley</sup> N. from E. leg. of Ver. valley dam site	8-31-40
10/7 23106	E. from Lava Knob 500' N. of dam site.	8-31-40
10/7 23107	Blaney dam site looking S.	8-30-40
10/7 23108	Blaney dam site. S. - 1	"



## Small films

23100	Blaney dam site - upstream on 7650 contour	8-30-40
23110	- - - looking north	8-30-40
23111	- - - - -	8-30-40
23112	Jackass Dam site looking west	8-31-40
23113	Lower Jackass dam site looking East	8-31-40
23114	Edison Co. Ambulance. Transportation Dept.	9-10-40
23115	" " " "	"
23116	" " " "	"
23117	" " " "	"
23118	" " " "	"
23119	" " " "	"
23120	Dam 6, Gen. View of W. abutment gunite B.C. 3	8-29-40
23121	" " Cutting seat for Whirley pier B.C. 3	"
23120	Dam 6, Gen. View of W. abutment gunite B.C. 3	8-29-40
23121	" " Cutting seat for Whirley pier B.C. 3	"
23122	Florence Lake Dam Walkway repairs 1 <sup>st</sup> tangent	"
23123	" " " Gunite placing set up	8-30-40
23124	" " " Gunite on 4 <sup>th</sup> Tangent	"
23125	" " " note traveling scaffold for gunite work	"
23126	" " " Walkway repair gunite set up	"
23127	" " " Repair crew & transportation	"
23128	" " " Typical chipping & reinf. 4 <sup>th</sup> Tangent	"
23129	" " " Gunite on 4 <sup>th</sup> tangent	"
23130	" " " Experimental coatings arches 7-8-9	"
23131	" " " Arch 8 Asbestos coating torn off near haunch	"
23132	" " " Chipping spillway	"
23133	Lower end of Italian Bar Below P.H. 3	8-29-40
23134	Italian Bar Below P.H. 3	"
23135	Cobble Bar at P.H. 3	"

## Small films

23136	Mono Reservoir showing silt accumulation	8-31-40
23137	Mono Diversion Dam	"
23138	Sand Pit - lower Jackass - used for F.L. dam gunite	8-30-40
23139	Resurfaced roadway at Dam #1	9-1-40
23140	Stevenson Creek Test Dam	8-29-40
23141	Southerly Location proposed road to Kaweah #1 Forebay	7-25-40
23142	Detail of N. abutment Stevenson Cr. Dam	8-29-40
23143	Detail of cracking and spalling E. abut. Dam 6	"
23144	Dam 6, Detail of leakage - sluice gates	"
23145	Dam 6 gunite. Detail of cracking and spalling (see index card)	"
23146	Dam 6 crest detail showing solution of Cement by spilling water.	"
23147	Dam 6, West Abut. gunite	"
23146	Dam 6 crest detail showing solution of Cement by spilling water.	"
23147	Dam 6, West Abut. gunite	"
23148	Boring for concrete pile footing with Caisson dr. rig.	9-12-40
23149	" " " " " "	"
23150	Pouring concrete for concrete pile footings	"
23151	Setting of reinforcement cage for concrete pile footing	"
23152	Centering tripod support for concrete pile footing stub.	"
23153	View of Camp No. 1 at Mile 32	"
23154	" " " " " "	"
23155	Barre Sub. - End bells and rotor - on cars as received	9-27-40
23156	" " Putting North bearing in place on shaft, June 6	"
23157	" " Jacking stator down on pad. May 29	"
23158	" " Removing cradle from Rotor, June 5	"
23159	" " South end bearing in place on shaft, June 17	"
23160	" " South end section moving North on to pad June 18	"
23161	" " Rotor on jacks so that cradle could be dismantled 6-5	"
23162	" " " " " "	"



## Small films

23163	Barre Substa. Removing shaft extension June 20	9-27-40
23164	Rotor being moved into place in Stator June 12	"
23165	Barre Sub. Stator as shipped. Rec'd. May 18	"
23166	" " Placing trucks under South end Section May 20	"
23167	" " Bars skimmed for grouting under sole plate May 15	"
23168	" " End bells on car Rec'd. May 15	"
23169	" " Foundation ready for sole plate " "	"
23170	" " Unloading End bells May 16	"
23171	" " End bells as stored on transfer car May 16	"
23172	" " End bell in place Jul. 23	"
23173	" " End section leaving car. May 20	"
23174	" " Rotor almost in place June 12	"
23175	" " Rotor as shipped. Rec'd May 15	"
23176	" " End section as shipped Rec'd May 15	"
23175	" " Rotor as shipped. Rec'd May 15	"
23176	" " End section as shipped. Rec'd May 10	"
23177	" " Rotor as shipped showing bracing May 21	"
23178	" " South end section moving into place June 18	"
23179	" " Trucks used for moving sections May 25	"
23180	" " Stator section in position ready to be set on pad	"
23181	" " End section leaving car. May 20	"
23182	" " Stator section moving south to pod.	"
23183	" " Moving south end section off car May 20	"
23184	" " South end section moving south etc.	"
23185	" " Bearing - May 15	"
23186	" " Pulling rigging on end section May 20	"
23187	" " Rotor moving south. June 4	"
23188	" " Rigging end section etc. May 17	"
23189	" " Placing end bells on transfer car. 5-16	"

## Small films

23190	Setting sole plate Barre Sub. May 16	9-27-40
23191	Barre Sub. Stator moving away from car May 20	"
23192	" " Rotor leaving car moving East May 23	"
23193	" " Rotor as shipped - uncovered May 21	"
23194	" " Rotor moving South June 3	"
23195	" " Rotor as shipped showing bracing May 21	"
23196	" " Rotor with most of cradle removed June 5	"
23197	" " Cleaning Rotor before shipping into stator	"
23198	" " North end section moving south, June 7	"
23199	" " Setting gas control house on foundation 7/23	"
23200	" " Rotor in cradle moving south, June 3	"



For Transmission 8X10  
(341 Bishop)

23201	Chino Yard, showing new S and A towers	10-1-40
23202	Topping out for erection of Towers M3-T4	"
23203	Hot line crossing showing guard poles 4-4 to 5-1	"
23204	Tensioning conductor between 6-2 - 6-3	"
23205	Chino Capistrano Line - Wood H frame 25-1, looking south	"
23206	" " " Driving foundation piles about M7	"
23207	Boulder Chino Trans. Line - Excavating tower foundations. M49-T1	10-2-40
23208	" " " " " " at M44-T2	10-1-40
23209	" " " " " " Concreting tower foundation M36-T2	"
23210	" " " " " " Hand excavating for comb. earth & rock fudn.	"
23211	Cima Camp #2	"
23212	Gould Eagle Rock Line 10-4-40. Erecting DC Tower M2-T2	10-4-40
23213	" " " " " " Dismantling tower M1-T1	"
23212	Gould Eagle Rock Line 10-4-40. Erecting DC Tower M2-T2	10-4-40
23213	" " " " " " Dismantling tower M1-T1	"
23214	" " " " " " Removing conductor M1-T4	"
23215	" " " " " " New line from 240-3 to Eagle Rock Sub.	"
23216	" " " " " " Eagle Rock To 240-6	"
23217	Boulder-Chino Trans. Line - Erecting tower steel, etc.	11-1-40
23218	" " " " " " " with crane	"
23219	" " " " " " Drilling thru embedded split collars	"
23220	" " " " " " Pouring concrete for pile footings	"
23221	" " " " " " Partially completed Camp No 3	"
23222	Chino-Capistrano " " " Completed double circuit section	"
23223	" " " " " " Single " Line	"
23224	" " " " " " Pulling up conductor dead end	"
23225	" " " " " " " " etc.	"
23226	Eagle Rock-Gould " " " New single circuit section	"
23227	" " " " " " Part of completed double circuit	"

8X10 For Transmission  
(1273)

23228	View of tie from M35-T2 to Capistrano Rack	12-2-40
23229	Transposition at Steel H-Frame Tower M17-T2	"
23230	Temporary wood pile line Connection from M0-T3 to Chino Rack	"
23231	Crossings of Two Boulder-Chino Lines under the City of L.A. Lines	"
23232	Reel Set-up and "Bull" Wheel at M1-T1 etc.	"
23233	Side view of "Bull" wheel & reel set up at M1-T1, etc.	"
23234	Close-up View of "Bull" Wheel in use at M1-T1	"
23235	P. & H. crane with 105' Boom used on Tower erection	"
23236	Making second lift Consisting of two bottom Panels	"
23237	Making lift of two Upper Panels Bolted together, etc.	"
23238	Raising Bridge with Insulators attached	"
23239	Placing Concrete for Tower Foundations by "Hi-Line"	"
23240	Reeling in Pulling line with Reel truck at M1-T1	"
23239	Placing Concrete for Tower Foundations by "Hi-Line"	"
23240	Reeling in Pulling line with Reel truck at M1-T1	"
23241	" " " " " "	"
23242	Tower M0-T5 with wire stringing completed & Bird guards, etc. erected	1-3-41
23243	Completed first & 2nd Boulder lines - M1-T1.	"
23244	"Meggering" Insulators at Tower M18-T3	"
23245	"Clipping-in" Conductor at Tower M28-T4	"
23246	Hanging Dead End Insulator strings at Tower M31-T4	"
23247	Erecting Bridge with Insulators attached with P & H Crane	"
23248	Erecting Tower steel with Byers Crane at Location M55-T2	"
23249	Pisgah Substa. site with rough grading completed.	1-4-41
23250	Hand Excavation for Tower foundations, Location M135-T1.	"
23251	Drill Rig with 30" Bucket in position for drilling, etc.	"
23252	2nd Boulder Chino Trans Line - Installing transposition tower	2-3-41
23253	" " " " " " Pulling out conductors & ground wires.	"
23254	View of 1st & 2nd Boulder-Chino Lines looking East from M18-81	"



23255	2 <sup>nd</sup> Boulder-Chino Trans. Line - Erecting tower by hand at Lo. M90-T1.	2-3-41
23256	Pisgah Substa. View of Construction operations.	"
23257	Pisgah - View of Camp No. 4 under construction	"
23258	" - View of Material Yard at Pisgah, Cal. Mi. 131	"
23259	Bo. Chino Trans. Line Placing concrete from Ready mix truck - Loc. M212-T2	"
23260	" " " Hand excavation for tower footings in Heavy Wash.	"
23261	" " " Drilling Holes for Concrete Piles in Vineyard	"
23262	2 <sup>nd</sup> Boulder-Chino Trans. Line - Drilling for concrete Piles M229-T5	3-3-41
23263	" " " Lowering reinf. Cage for con. pile	3-5-41
23264	" " " Placing concrete for pile footings	3-3-41
23265	Pisgah Sub. - View of construction at Pisgah Sub.	3-4-41
23266	2 <sup>nd</sup> Boulder-Chino Trans. Line - First lift in erecting Tower	"
23267	" " " Tensioning Conductor at M91-T2	"
23268	2 <sup>nd</sup> Boulder-Chino Trans. Line - First lift in erecting Tower	"
23269	" " " Tensioning Conductor at M91-T2	"
23270	" " " Pulling Out Conductor under tension	"
23271	Transposition at M107-T2 showing extension traps in Dead End strings	4-2-41
23272	Installing Bird Guards at M113-T1	"
23273	Erecting Bridge with Insulators attached at M142-T2	"
23274	View of Camp 5 at M157-T1	"
23275	View of Pisgah Substa. looking from the East	"
23276	View of Control House & Oil Tanks at Pisgah Substa.	"
23277	View of Operators Cottage & Garage under Constr. at Pisgah Sub.	"
23278	2 <sup>nd</sup> Boulder-Chino Trans. Line - Checkers at M173-T5	4-30-41
23279	" " " Clipping in at M141-3	"
23280	Pisgah Substa - General View	"
23281	" " Control House, Oil Filter Hse, etc.	"
23282	" " Operators Cottage & Garage	"
23283	2 <sup>nd</sup> Boulder-Chino Trans. Line - Steel Yard at Hesperia	5-7-41

23282	Barre Lighthouse 2 <sup>nd</sup> Boulder-Chino Trans. Line - Barre Sub. M15-T4	5-1-41
23283	" " " Pulling casing for cover Piles M12-T1	"
23284	" " " Placing concrete, etc. M9-T2	"
23285	Pisgah Sub. - General View	6-1-41
23286	" " Control House & Racks	"
23287	Boulder-Chino Trans. Line - Building road at mile 210	"
23288	Barre Lighthouse Trans. Line - Tower erection by crane, Mi. 7	"
23289	" " " Tower erection by hand, Mi. 7	"
23290	" " " Looking North from Barre Sub.	"
23291	Barre Sub - General View of new work	"
23292	Barre Lighthouse Trans. Line - Mucking out holes T90	"
23293	" " " Driving wood sheeting, T89	"
23294	" " " Mucking out holes T90	"
23295	" " " Driving wood sheeting, T89	"
23296	" " " Showing piles & reinforcement	"
23297	" " " Placing concrete - T91	"
23298	" " " Backfilling, showing finished footings	"
23299	View of new racks & switches supports - Barre Sub.	7-1-41
23300	Barre Lighthouse Line - View of Get-Away from new rack	"
23301	" " " Clipping in Conductor at mi. 6 Tower 2	"
23302	" " " View of rolling transpositions M10-T3 to M10-T6	"









## Small Films

23401	Barre Sub. - Guiding south end bell into place, June 28	9-27-40
23402	" " North end, stator & rotor in place, etc. 6-14-40	"
23403	" " Placing Exciter in place, July 23	"
23404	" " Turning stator on car for unloading, May 20	"
23405	" " Stator leaving car, May 20	"
23406	" " 4 Sections on cribbing ready to be moved, May 21	"
23407	" " Rotor in air about 10' from ground, etc. May 22	"
23408	" " Lowering rotor on to cradle, May 22	"
23409	" " Rotor in cradle ready to leave car, May 23	"
23410	" " Rotor leaving car, May 23	"
23411	" " Putting south end bell in place, June 28	"
23412	Live wire Dead End Insulator Changing Device	10-10-40
23413	" " " " " " " "	"
23414	Live wire Dead End Insulator Changing Device	10-10-40
23413	" " " " " " " "	"
23414	" " " " " " " "	"
23415	" " " " " " " "	"
23416	" " " " " " " "	"
23417	" " " " " " " "	"
23418	" " " " " " " "	"
23419	" " " " " " " "	"
23420	Live Line suspension Insulator changing Device	"
23421	" " " " " " " "	"
23422	" " " " " " " "	"
23423	" " " " " " " "	"
23424	Florence Lake Tunnel Intake House	9-26-40
23425	Gravel at outlet P.H. 8 Diversion tunnel	10-7-40
23426	Dam 6, res. - surging flow - average 100 S.F.	"
23427	" " Excavating for new sluice gates	10-5-40

## Small Films

23428	Chipping face of Dam 4	9-25-40
23429	Florence Lake Dam	9-26-40
23430	Dam 6 Res. above #3 intake	10-5-40
23431	Dam 6 upper reservoir	"
23432	Dam 6 reservoir just above cableway B C #3	"
23433	E. bank above cableway B C #3	"
23434	Dam 6 res. unwatered	"
23435	Upper end, Dam 6 reservoir B C #3	"
23436	Dam 6, reservoir P.H. #3, Big Creek 3	10-7-40
23437	Placing wire mesh Dam #4 P.H. 2 Big Creek 2	"
23438	Dam 4, S. end. Start of gunite repair	"
23439	Dam 4 repair	"
23440	Dam 6, setting sluice gate	"
23439	Dam 4 repair	"
23440	Dam 6, setting sluice gate	"
23441	Dam 6, Surge arriving at sluice gates	"
23442	Dam 6, Setting new sluice gate	"
23443	Setting sluice gate	"
23444	Dam 6 res. at slackline cableway	"
23445	Dam 4 repair	10-12-40
23446	Dam 6, Trash rack section	"
23447	Flume on Borel canal - excellent condition 1930 constr.	11-6-40
23448	Patching Borel canal lining	"
23449	Floating repair plant - Borel Canal	"
23450	Borel Canal, Mar. 1937 Gunite repair (reinforced)	"
23451	Canal and transition - Borel canal	"
23452	Borel canal Flume (1930 constr.)	"
23453	F.L. Dam Arch 3 walkway spalled flash coat gunite	10-11-40
23454	Dam #6 new pier and crane (no film received)	10-12-40



Small films  
Live Line Dead end insulation changing device (See photo card)

23455	Dam 6 N. sluice gates (no film received)	10-12-40
23456	Live line Tools for repairing Damaged Conductor Strands	11-15-40
23457	" " " " " "	"
23458	" " " " " "	"
23459	" " " " " "	"
23460	" " " " " "	"
23461	" " " " " "	"
23462	" " " " " "	"
23463	" " " " " "	"
23464	" " " " " "	"
23465	" " " " " "	"
23466	" " " " " "	"
23467	" " " " " "	"
23468	Pitman Ck. below Tamarack Mt.	"
23467	" " " " " "	"
23468	Pitman Ck. below Tamarack Mt.	Nov. 1940
23469	Detail view showing rock & concrete wall.	"
23470	Pitman Creek new station showing cable tie anchor	"
23471	" " " Mr. Tamarack Mt.	"
23472	" " " Showing concrete & rock wall	"
23473	Pitman Creek near Tamarack Mt. - Gaging station	"
23474	" " " showing completed station	9-29-40
23475	" " " Down stream side of new station	Nov. 1940
23476	" " " showing placement of 3 ft. corrugated pipe	Sept. 1940
23477	B.C. 2-2A Removing tank from water after completion of test	11-17-40
23478	" " " View of water rheostat with only partial load on it	"
23479	" " " Clouds of steam arising from water rheostat in oper.	"
23480	" " " Another view of water rheostat in operation.	"
23481	" " " Water rheostat used in testing unit #3	"

Small films

23482	Cross Arm changing job on Visalia-Goshen 66KV Line	11-10-40
23483	" " " " " "	"
23484	" " " " " "	"
23485	" " " " " "	"
23486	" " " " " "	"
23487	" " " " " "	"
23488	" " " " " "	"
23489	" " " " " "	"
23490	" " " " " "	"
23491	" " " " " "	"
23492	Footing excavation Pisgah Sub.	12-23-40
23493	Excavating structure footings - Pisgah Sub.	"
23494	Boulder Chino tower footing nr. mi. 132 (Typical setting shrinkage)	"
23493	Excavating structure footings - Pisgah Sub.	"
23494	Boulder Chino tower footing nr. mi. 132 (Typical setting shrinkage)	"
23495	Boulder Chino footing near mile 132	"
23496	Boulder Chino tower footing nr. mi. 132. Typical setting shrinkage checking	"
23497	Huntington Lake Spillway - W.H. Holmes & W.L.C.	10-11-40
23498	Concrete Test Pans at Florence Lake	"
23499	" " " " " "	"
23500	Bear Dam - Mono Bear.	"

23501	Water Softener equipment Vernon Diesel Plant	10-29-40
23502	" " " " " " " "	" "
23503	Edison Cottages at Boulder City	11-1-40
23504	Close up of single cottage at Boulder City	"
23505	Rector Substa.	(old neg.)
23506	" " " " " " " "	" "
23507	" " " " " " " "	" "
23508	Rector Substa.	"
23509	" " " " " " " "	" "
23510	" " " " " " " "	" "
23511	Florence Lake Dam	"
23512	Stadia coefficients	"
23513	" " " " " " " "	" "
23514	" " " " " " " "	" "
23513	" " " " " " " "	" "
23514	" " " " " " " "	" "
23515	" " " " " " " "	" "
23516	" " " " " " " "	" "
23517	Eagle Bell Line - Construction road on Armstrong Prop. m. Gould	3-24-41
23518	" " " " " " " "	" "
23519	" " " " " " " "	" "
23520	" " " " " " " "	" "
23521	" " " " " " " "	" "
23522	" " " " " " " "	" "
23523	Condenser at Torrance	3-25-41
23524	" " Katella	"
23525	" " " " " " " "	" "
23526	" " " " " " " "	" "
23527	Cores of Huntington Lake Dam - Taken at Alhambra (2 neg)	6-2-41

23528	Barre-Lighthipe Line - Measuring Cut-off for instal. Dead End	7-1-41
23529	" " " " " " " "	" "
23530	" " " " " " " "	" "
23531	" " " " " " " "	" "
23532	Barre Sub.	7-22-41
23533	Seal Beach Rebuild - Looking East. Barre Light	"
23534	Barre-Lighthipe Line - Completed Looking back from 6.4	"
23535	Guard Poles & cables 1-4 to 1-5	"
23536	Barre-Lighthipe Construction alongside M.C. lines	"
23537	Boulder-Chino Line - Erecting tower by hand.	8-1-41
23538	" " " " " " " "	" "
23539	" " " " " " " "	" "
23540	Barre Sub. (Mrs. B. took this extra view)	7-22-41
23539	" " " " " " " "	" "
23540	Barre Sub. (Mrs. B. took this extra view)	7-22-41
23541	2nd Boulder-Chino Line - Hinging up Bottom panels of Tower M220-T1.	9-1-41
23542	" " " " " " " "	9-2-41
23543	" " " " " " " "	" "
23544	" " " " " " " "	" "
23545	" " " " " " " "	" "
23546	Chino Laguna Bell - Driving wood Piles for Tower Foundations, Loc. #148	"
23547	Chino Laguna Bell - Excavating for Earth Type Tower Footings	9-3-41
23548	Florence Lake Dam - Central and west portion	7-3-26
23549	Site of East abutment of Florence Lake Dam	4-30-25
23550	2nd Boulder-Chino - Making up Conductor Dead End Connection	10-1-41
23551	" " " " " " " "	" "
23552	" " " " " " " "	" "
23553	" " " " " " " "	" "
23554	Chino Laguna Bell - Assembling tower steel on ground in exact	"



198

8x10

23555	Chino Laguna Bell - Placing concrete for Cast in place tower.	10-1-41
23556	" " Building Permanent Patrol Road bet Towers	"
23557	" " " Hand excavation for Earth Ligne Tower footings.	"
23558	Distr. Line - Location of Sierra Madre Dairy fire of Oct. 3	10-3-41
23559	" " " " " " " " " " " "	"
23560	" " " " " " " " " " " "	"
23561	Frequency changer at Chino Substa.	10-22-41
23562	" " " " " " " " " " " "	"
23563	Snow Motor (Taken for P.H. Ducker)	10-15-41
23564	Eagle Rock Substation.	10-22-41
23565	" " " " " " " " " " " "	"
23566	" " " " " " " " " " " "	"
23567	" " " " " " " " " " " "	"
23566	" " " " " " " " " " " "	"
23567	" " " " " " " " " " " "	"
23568	Magunden Substation	10-25-41
23569	" " " " " " " " " " " "	"
23570	" " " " " " " " " " " "	"
23571	" " " " " " " " " " " "	"
23572	" " " " " " " " " " " "	"
23573	Vestal Substation	10-26-41
23574	" " " " " " " " " " " "	"
23575	" " " " " " " " " " " "	"
23576	" " " " " " " " " " " "	"
23577	Rector Substation	"
23578	" " " " " " " " " " " "	"
23579	" " " " " " " " " " " "	"
23580	" " " " " " " " " " " "	"
23581	" " " Board	"

8x10

199

23582	La Fresa Sub.	10-28-41
23583	"	"
23584	"	"
23585	"	"
23586	" No print received from GHB	"
23587	Lighthouse Substation	10-28-41
23588	"	"
23589	"	"
23590	Laguna Bell Substation	10-29-41
23591	"	"
23592	"	"
23593	"	"
23592	"	"
23593	"	"
23594	"	"
23595	"	"
23596	Barre Substation	"
23597	"	"
23598	"	"
23599	"	"
23600	Chino Substation	10-29-41

23601	Testing insulators on energized 220KV lines.	about 1935
23602	" " " "	"
23603	" " " "	"
23604	" " " "	"
23605	" " " "	"
23606	Repairing Damaged Conductor strands with "Live Line" tools	1-15-1941
23607	Changing vibration Damages on 220KV lines with new method hot sticks	9-1-38
23608	" " " "	"
23609	" " " "	"
23610	" " " "	"
23611	" " " "	"
23612	Repairing Damaged Conductor strands with "Live Line" Tools.	1-15-41
23613	Tools used for "Live Line" inspection & Cutter key replacement on B.C. 220KV	"
23614	Repairing Damaged Conductor strands with "Live Line" Tools.	1-15-41
23613	Tools used for "Live Line" inspection & Cutter key replacement on B.C. 220KV	"
23614	" " " "	"
23615	" " " "	"
23616	" " " "	"
23617	" " " "	"
23618	" " " "	"
23619	" " " "	"
23620	" " " "	"
23621	B.C. 2 - Incline R.R. bridge over tailrace	Jan. 1934
23622	B.C. 2A - Transformer house and 220KV oil sw. & rack	" "
23623	B.C. P.H. #1 Showing location of auto transformers and County Road	" "
23624	B.C. 2 220 K.V. towers on roof and lines to P.H. #8	" "
23625	B.C. P.H. #1 Auto Transformers and rack structures	" "
23626	Dam #2 Chipped out horizontal constr. joint. (Htg. Lake)	6-1-38
23627	Dam #3A Old core drill hole 12 in front of Dam	"

23628	Dam #3A Htg. Lake. View of grouting connections.	6-1-38
23629	" " " Drilling 30 ft. grout holes.	"
23630	Dam #3A Drilling 30 ft. grout holes.	"
23631	Upstream face looking south after compl. of concreting & grout work	"
23632	Upstream of face looking north after compl. of concreting & grouting	"
23633	" " " " " " " "	"
23634	Dam #3A Concreting trench in front of cut-off wall	"
23635	" " " " " " " "	"
23636	" " " " " " " "	"
23637	Dam #3A Chipped out pocket of loose and leaky rock Sta. 1+15	"
23638	" " Hole under bottom of cut-off wall, discovered during excavation	"
23639	Dam #3 Typical chipped out vertical contraction crack before grouting	"
23640	" " Hole under bottom of cut-off wall, discovered during excavation	"
23639	Dam #3 Typical chipped out vertical contraction crack before grouting	"
23640	Dam #3 Chipped out vertical and horizontal cracks near north end.	"
23641	West end Dam #2 Grouting core drill hole.	"
23642	Face of Dam #2 after grouting chipped out cracks east from Sta.	"
23643	" " " " " " " "	"
23644	Dam #2 Grouting chipped out areas.	"
23645	Dam #3 Core drilling at West End	"
23646	Dam #1 East end. Grouting equipment in operation	"
23647	Dam #2 Chipping out vertical contraction crack near East end.	"
23648	Dam #3	"
23649	Dam #2 Another view toward excavation behind old concrete plant	"
23650	Dam #1 Area near Sta. 5+66 elev. 690.4± after guniting	"
23651	Dam 3A	"
23652	"	"
23653	"	"
23654	"	"





## Small Films

23701	Dam No. 6 - Placing first sand bag dam on Fresno side	3-8-38
23702	" " " Spill over Madera side of Dam 6	3-20-38
23703	" " " Spill over dam	3-8-38
23704	B.C. #8 Raising weir between Units 1 & 2	2-27-38
23705	Huntington Lake Dam - Close up of replacement bearing spillway weir	3-27-38
23706	Florence Lake Dam - West side of Butress 13	9-5-38
23707	Dam No. 6 Guniteing Madera side	2-17-38
23708	" " " " "	"
23709	Huntington Lake Dam No. 1. Rock backfill	9-10-38
23710	Dam No. 6 Looking down on gunite fillet, Fresno side	9-2-38
23711	Florence Lake Dam - Looking into Arch 53	9-5-38
23712	Htg. Lake Dams - Lower 84" Butterfly-valve house	4-1-38
23713	Dam No. 2 Rock facing downstream side of Dam No. 2	9-5-38
23712	Htg. Lake Dams - Lower 84" Butterfly-valve house	4-1-38
23713	Dam No. 2 Rock facing downstream side of Dam No. 2	9-10-38
23714	Huntington Lake Loading rock from East side of Old Dam #2	"
23715	Htg. Lake Dam No. 1. Extension to main spillway	"
23716	" " " Rock backfill completed	"
23717	Dam No. 6 - Madera side of canyon below Dam No. 6.	9-2-38
23718	Sierra P. H.	Old neg.
23719	" " "	"
23720	Huntington Lake - Filling Tunnel #1 Big Creek (By m.w. Glenn)	1930
23721	B.C. #3 Set-up for grinding clearance Ring #3 Unit (by Glenn)	"
23722	" " " " " " "	"
23723	" " " " " " "	"
23724	B.C. #8 Intake at Dam 5 (By m.w. Glenn)	3-28-31
23725	" " " " " "	"
23726	" " " " " "	"
23727	" " " " " "	"

## Small Films

23728	B.C. #8 No. 2 Unit - Runner in service (by m.w. Glenn)	1-28-31
23729	" 3 " 3 " " " "	"
23730	" " 3 " Runner	"
23731	" " 3 " " "	"
23732	" " " Runner from No. 3 unit after 345 days service (m.w. Glenn)	"
23733	B.C. No. 8 No. 2 Unit Runner in service	"
23734	B.C. #3, #3 unit - Runner after 345 days service	"
23735	B.C. #1 Johnson valves No. 3 unit showing debris	2-7-31
23736	" " " " " " "	2-8-31
23737	B.C. #2 Installation of trash rack at sluice gate Dam #4	5-20-30
23738	" " " " " " "	5-20-30
23739	" " " " " " "	"
23738	" " " " " " "	5-20-30
23739	" " " " " " "	"
23740	" " " " " " "	"
23741	" " " " " " "	"
23742	" " " " " " "	"
23743	Florence Lake Tunnel - Test from 1000 to 2000 C.F.S.	8-20-30
23744	" " " " " " "	"
23745	" " " " " " "	"
23746	" " " " " " "	"
23747	" " " " " " "	"
23748	" " " " " " "	"
23749	" " " " " " "	"
23750	" " " " " " "	"
23751	" " " " " " "	"
23752	" " " " " " "	"
23753	" " " " " " "	"
23754	" " " " " " "	"



23755	Florence Lake Tunnel - Test from 1000 to 2000 C.F.S. (M.W. Glenn)	8-20-30
23756	" " " " " " " "	"
23757	B.C. #1 Damage caused by #1 Penstock break (M.W. Glenn)	1930
23758	" " " " " " " "	"
23759	" " " " " " " "	"
23760	" " " " " " " "	"
23761	" " " " " " " "	"
23762	Accident to School bus	Feb. 1931
23763	" " " " " " " "	Feb. 1931
23764	B.C. #8 Exterior view	1930
23765	" " Interior "	"
23766	B.C. #8 G.E. Bearing no. 1 unit	3-1-32
23765	" " Interior " " "	"
23766	B.C. #8 G.E. Bearing no. 1 unit	3-1-32
23767	" " " " " " " "	3-1-32
23768	B.C. #1 Boring Rig - superseded by that shown on 26560	Mar. 1930
23769	" " " " " " " "	"
23770	" " " " " " " "	"
23771	" " " " " " " "	"
23772	P.H. #8 - Rear view	Old neg.
23773	Florence Lake Tunnel - Gas shovel at Camp 60 (old No. A866)	11-18-27
23774	" " " Showing flow from tunnel outlet (A867)	"
23775	" " " Stand pipe at Dam #2 (A868)	"
23776	" " " Water flowing from tunnel outlet (A869)	"
23777	Huntington Lake Dam #2 (A871)	"
23778	Steel H frame failure at mi. 19 H frame 4 of Chino-Capis.	3-5-41
23779	" " " " " " " "	"
23780	" " " " " " " "	"
23781	" " " " " " " "	"

23782	Steel H frame failure at mi. 19 H frame 4 of Chino-Capiatranso line	3-5-41
23783	" " " " " " " "	"
23784	Tap arrangement from Big Creek lines to Piedra Sub.	3-13-41
23785	19-4 on Chino-Capiatranso 115 KV Line Assembly of tower footing	3-5-41
23786	Laguna Bell-Puente 66 KV Line 16-2 Transm. Miscel.	3-7-41
23787	Nr. 16-2 on Laguna Bell-Puente 66 KV line. " "	"
23788	Laguna Bell-Puente Line 16-2 Transm. Miscel.	"
23789	Laguna Bell-Puente 66 KV line 16-2 " "	"
23790	Piedra Sub - Looking West	3-13-41
23791	" " " " " "	"
23792	Tower 105-6 on West Vestal-Magunson 220 KV line	"
23793	Piedra Sub. Looking North-East	"
23792	Tower 105-6 on West Vestal-Magunson 220 KV line	"
23793	Piedra Sub. Looking North-East	"
23794	" " " East	"
23795	Piedra Sub. - showing P.B. & E. break-a-way tower	"
23796	Piedra Sub. - Looking North	"
23797	Tower footing - 2 <sup>nd</sup> Boulder-Chino Line mi. 46	"
23798	Chino-Capiatranso Line 19-4 showing a cattle guard by anchor Loc.	"
23799	Tap arrangement from Big Creek 220 KV line to Piedra Sub.	"
23800	Tower footing 2 <sup>nd</sup> Boulder-Chino Line mile 46.	"

208

Small Films

23801	Florence Lake Dam study of concrete conditions by F.R. McMillan (Copy) 1929
23802	" " " " " " " "
23803	" " " " " " " "
23804	" " " " " " " "
23805	" " " " " " " "
23806	Consumers Sub. Shell Oil Co. Sub. #2 Dominguez 4-14-41
23807	" " Shell Chemical Sub. " "
23808	" " " " " " " "
23809	" " Shell Sub. #4 " "
23810	" " " " #5 " "
23811	" " " " #1 " "
23812	" " " " #2 " "
23813	" " " " #4 " "
23812	" " " " #2 " "
23813	" " " " #4 " "
23814	Location of soil sample #1, Hemminghouse Ranch 4-24-41
23815	" " " " #2 " "
23816	" " " " #3 " "
23817	" " " " #4 " "
23818	" " " " #5 " "
23819	" " " " #6 " "
23820	" " " " #8-9 " "
23821	" " " " #10 " "
23822	" " " " #11 " "
23823	" " " " #12 " "
23824	" " " " #13 " "
23825	" " " " #13-A " "
23826	" " " " #14 " "
23827	" " " " #15 " "

209

Small Films

23828	Location of soil sample #16 Hemminghouse Ranch 4-24-41
23829	" " #17 " "
23830	" " #18 " "
23831	" " #19 " "
23832	" " #20 " "
23833	" " #21 " "
23834	" " #22 " "
23835	" " #23 " "
23836	" " #24 " "
23837	" " #25 " "
23838	" " #26 " "
23839	" " #27 " "
23840	" " #28 " "
23839	" " #27 " "
23840	" " #28 " "
23841	" " #29 " "
23842	" " #30 " "
23843	" " #31 " "
23844	" " #32 " "
23845	" " #33 " "
23846	" " #34 " "
23847	" " #35 " "
23848	" " #36 " "
23849	" " #37 " "
23850	" " #38 " "
23851	" " #39 " "
23852	" " #40 " "
23853	" " #41 " "
23854	" " #42 " "



23855	Location of soil sample #43	Herminghaus Ranch	4-24-41
23856	"	" #44	"
23857	"	" #45	"
23858	"	" #46	"
23859	"	" #47	"
23860	"	" #48	"
23861	"	" #49	"
23862	"	" #50	"
23863	"	" #51	"
23864	"	" #52	"
23865	"	" #53	"
23866	"	" #54	"
23867	"	" #55	"
23866	"	" #54	"
23867	"	" #55	"
23868	"	" #56	"
23869	"	" #57	"
23870	"	" #58	"
23871	"	" #59	"
23872	"	" #60	"
23873	"	" #61	"
23874	"	" #62	"
23875	"	" #63	"
23876	"	" #64	"
23877	"	" #67	"
23878	"	" #68	"
23879	"	" #69	"
23880	"	" #70	"
23881	"	" #71	"

23882	Location of soil sample #72	Herminghaus Ranch	4-24-41
23883	"	" #73	"
23884	"	" #74	"
23885	"	" #75	"
23886	"	" #76	"
23887	"	" #77	"
23888	"	" #78	"
23889	"	" #79	"
23890	"	" #80	"
23891	"	" #80-A	"
23892	"	" #81	"
23893	"	" #82	"
23892	"	" #81	"
23893	"	" #82	"
23894	"	" #83	"
23895	"	" #84	"
23896	"	" #85	"
23897	"	" #86	"
23898	"	" #87	"
23899	"	" #88	"
23900	"	" #89	"

Small films

23901	Location of Soil Sample	#	90	Herminghouse Ranch	4-24-41
23902	"	#	91	"	"
23903	"	#	92	"	"
23904	"	#	93	"	"
23905	"	#	94	"	"
23906	"	#	95	"	"
23907	"	#	96	"	"
23908	"	#	97	"	"
23909	"	#	98	"	"
23910	"	#	99	"	"
23911	"	#	100	"	"
23912	"	#	101	"	"
23913	"	#	102	"	"
23914	"	#	103	"	"
23913	"	#	102	"	"
23914	"	#	103	"	"
23915	"	#	104	"	"
23916	"	#	105	"	"
23917	"	#	106	"	"
23918	"	#	107	"	"
23919	"	#	108	"	"
23920	"	#	109	"	"
23921	"	#	112	"	"
23922	"	#	113	"	"
23923	"	#	114	"	"
23924	"	#	115	"	"
23925	"	#	116	"	"
23926	"	#	117	"	"
23927	"	#	118	"	"

Small Films

23928	Location of soil sample #119 Herminghouse Ranch.	4-24-41
23929	" " #120 "	"
23930	" " #122 "	"
23931	" " #123 "	"
23932	Dam #4	3-28-41
23933	Upstream face of Dam #4	"
23934	Dam #4	"
23935	Tunnel #3 Outlet	"
23936	Foundation of former flume section Friant Dam	4-9-41
23937	Friant Dam looking North	"
23938	Friant Bridge (1905) checks on end post filled with hard brownish deposit.	"
23939	Friant Bridge - detail of end post and hand rail.	"
23940	Bridge built in 1905 below friant. Concrete in good condition	"
23941	Friant Bridge - detail of end post and hand rail.	"
23940	Bridge built in 1905 below friant. Concrete in good condition	"
23941	S. End Friant Dam	"
23942	Friant Dam - Typical cooling pipe header.	"
23943	Experimental arch dam and Stevenson creek.	4-10-41
23944	P.H. #3 Cracking & Carbonate deposit on lamp post	"
23945	P.H. #3 So. Face of No. handrail spalling caused by Sodium carbonate	"
23946	Chlorinator house at P.H. No. 3	"
23947	L.H. Tuthill & G.J. Douglas at Huntington Lake.	4-11-41
23948	L.H. Tuthill at Stevenson Cr. Test Dam	"
23949	Huntington Lake Dam #3	"
23950	At Huntington Lake	"
23951	Upstream face Dam #1, Huntington Lake	"
23952	Huntington Lake Dam #1, Base of intake structure	"
23953	" " " Spillway constructed in 1937.	"
23954	Huntington Lake Dam #2 showing sound concrete, etc. (1912)	"



23955	L. H. Luthill & C. J. Douglass at Huntington Lake Dam #3	4-11-41
23956	Huntg. Lake Dam #3 - disintegrated band 6' above backfill	"
23957	K.R. #3 Sandbox	3-16-41
23958	K.R. #3 Sandbox	"
23959	Cross Tie on Kern River #3 Sandbox	"
23960	Kern River #3 Sandbox - River Wall	"
23961	Shaver Dam. N. abut. & gallery leakage	3-22-41
23962	Huntg. Lake Dam #1 Scaling of granite coat	3-23-41
23963	" " near Sta. 6+00, dark area covered with scaling compound.	"
23964	Huntg. Lake Dams - upstream face	"
23965	Near Huntg. Lake. Prying Sno-Motor away from rock ledge	3-24-41
23966	Near Kaiser Pass	"
23967	Sno-Motor near Badger Flats	"
23968	Shooting Kaiser Pass	"
23967	Sno-Motor near Badger Flats	"
23968	Shooting granite Test bars at Berkeley	1-24-41
23969	Kaiser Pass - Sno-Tractor	3-24-41
23970	Crossing Kaiser Pass - Sno-Tractor	"
23971	Florence Lake Dam - Gunite checking on upstream face of spillway	3-25-41
23972	" " " " checking on Arch 2 Walkway gunite	"
23973	" " " " Gunite checking upstream face of spillway	"
23974	" " " " Old gunite on Arch #20	"
23975	" " " " Arch #8 from D.S. side - reservoir empty.	3-26-41
23976	" " " " " Close-up of Asbestos torn by snow load.	"
23977	" " " " " Worm's eye view of walkway in Frog Pond Sec.	"
23978	" " " " " Tangents 3 and 4	"
23979	" " " " " Frog Pond Section	"
23980	Intrados Arch #26	"
23981	Florence Lake Dam - River Section	"

23982	Florence Lake Dam - Insulmastic - Asbestos - Carbogite coatings	3-26-41
23983	" " " " River Section	"
23984	" " " " Frog Pond section	"
23985	Florence Lake Tunnel - Outlet of	3-24-41
23986	Accident - N & S Chino-Calton 66 KV. Line	4-27-41
23987	" " " "	"
23988	" " " "	"
23989	" " " "	"
23990	" " " "	"
23991	" " " "	"
23992	" " " "	"
23993	" " " "	"
23994	" " " "	"
23993	" " " "	"
23994	Location of soil sample #65 Herminghouse Ranch	4-24-41
23995	" " " " #121	"
23996	" " " " #124	"
23997	" " " " #125	"
23998	" " " " #126	"
23999	" " " " #127	"
24000	" " " " #128	"



4/9 24001	San Dimas Exp. For. Bell Canyon #2 Debris Sta. Non-Edison Prop.	4-18-41
24002	" " " " Exp. Watersheds	"
24003	" " " " Forest " treatment of Highway fills	"
24004	Morris Reservoir	non - " "
24005	San Gabriel Dam #1	" " "
24006	San Dimas Experimental Forest Lysimeters & weighing device	" " "
24007	" " " " measuring Sta. above Big Dalton Res.	" " "
24008	" " " " Bell Con. #2 debris basin.	" " "
24009	Shell Oil Co. Watson Sub. No. 1	5-15-41
24010	" " " " No. 2	"
24011	" " " " No. 3	"
4/9 24012	" " " " No. 4	"
24013	" " " " No. 5	"
24014	" " " " meter rack	"
24015	" " " " No. 5	"
24014	" " " " meter rack	"
24015	" " " " meter rack	"
24016	Florence Lake Dam - Guniting operations on Arch #53	5-11-41
24017	Underside of Arch 58 walkway	"
24018	Florence Lake Dam - Looking directly upward under walkway repair Arch #1	"
24019	" " " " Asbestos over old asphalt emulsion torn by snowload #8	"
24020	Mts. Hooper & Hilgard from Kaiser Pass	5-10-41
24021	Florence Lake Dam - Arch 53, Looking down on sluice gate	"
24022	Mt. Ritter from Kaiser Pass	"
24023	Florence Lake Dam - Guniting Arch #53	5-11-41
24024	" " " " Pattern cracking on buttress at West End	"
24025	" " " " Arch 53, showing joint treatment	"
24026	" " " " Guniting Arch 53	"
24027	Typical sand pothole under tree near Badger Flats	5-12-41

7/25 24028	Redlands-Mill Creek 33KV, Cardiff-Redlands 33KV, Amer King Crayg Dam.	5-7-41
24029	" " " "	"
24030	" " " "	"
24031	" " " "	"
24032	" " " "	"
24033	" " " "	"
24034	" " " "	"
24035	" " " "	"
24036	m.c. - Yuccaipa 33 K.V. - Redlands-Yuccaipa 33 K.V.	5-7-41
24037	" " " "	"
24038	" " " "	"
24039	" " " "	"
24040	" " " "	"
24041	" " " "	"
24040	" " " "	"
24041	" " " "	"
24042	" " " "	"
24043	Long Beach St. Pl. #2 - Constr. joint between Units 8 & 9	7-1-41
24044	" " " " Typical crack in center of wall panel.	"
24045	" " " " Constr. joint, units #8 & #9, Outside, No. wall.	"
24046	" " " " #3 Shrinkage or settlement crack on top of door	"
24047	" " " " #2 Construction joint, Units #8 & #9, etc.	"
24048	" " " " #2 " " " "	"
24049	" " " " Constr. joint Condenser floor, N. side turbine room.	"
24050	Flo. Lake Tunnel - Typical hard rock section, etc.	M68
24051	Florence Lake Tunnel - Excavating in hard rock section fr. Ep. 61 (M 47)	"
24052	Illustrating Budget Items 1942 - Cardiff-Redlands 33 K.V. Lines.	6-18-41
24053	" " " "	"
24054	" " " "	"



218

For Small Films

24055	Illustrating Budget Items. 1942. Cardiff-Redlands 33 K.V. Lines	6-18-41
24056	" " " " " "	"
24057	" " " " " "	"
24058	" " " " " "	"
24059	" " " " " "	"
24060	" " " " " "	"
24061	" " " " " "	"
24062	" " " " " "	"
24063	" " " " " "	"
24064	" " " " " "	"
24065	Big Creek #1 Interior of penstock opening showing crack (Copy)	12-22-40
24066	Big Creek #1 Right hand nozzle Unit #2 showing crack (Copy)	Dec <sup>22</sup> 1940
24067	Big Creek No. 3 - Transfer Bus	8-24-41
24068	" " " " " " showing crack (Copy)	Dec <sup>22</sup> 1940
24067	Big Creek No. 3 - Transfer Bus	8-24-41
24068	" " " " " "	"
24069	" " " " " "	"
24070	" " " " " "	"
24071	" " " " " "	"
24072	" " " " " "	"
24073	New wire bus at P.H. #3 constructed in 1941	8-30-41
24074	" " " " " "	"
24075	" " " " " "	"
24076	" " " " " "	"
24077	" " " " " "	"
24078	" " " " " "	"
24079	Heading Bench Camp 62. Big Creek (M-48) (Copy)	No date
24080	Florence Lake Tunnel - crack in crown of Arch	7-16-41
24081	" " " " North wall - concrete crushing at Springline	"

For Small Films

219

24082	Florence Lake Dam, Second Tangent	7-16-41
24083	Shaver Dam - Preparation for crest repair	9-5-41
24084	" " " " " "	9-5-41
24085	Long Beach Steam Station - Bertram on D.W. #5	Jul. 1941
24086	" " " " " " Drilling O.W. #5	"
24087	" " " " " " Constr. joint #12, Conduit Tunnel.	8-15-41
24088	" " " " " " #11 " "	"
24089	" " " " " " Settlement around Well #4	8-22-41
24090	" " " " " " near #12-#13 intake tunnel	"
24091	" " " " " " Constr. joint #11, Conduit Tunnel.	Aug. 1941
24092	" " " " " " #12 " "	"
24093	Allen Sub.	Sept. 1941
24094	Alon Sub. Bldg.	"
24093	Allen Sub.	Sept. 1941
24094	Alon Sub. Bldg.	"
24095	" 11 KV Rack	"
24096	" 66 K.V. "	"
24097	" Transformers	"
24098	" Cottage	"
24099	Anita Substa.	"
24100	" " 16 K.V. rack	"





222

Reserved for Mrs. Almonstead (9-26-42)

24155	Florence Lake Dam - Extrados of Arch No. 18	5-5-42
24156	" " " " 19	
24157	" " " " 20	
24158	" " " " 21	
24159	" " " " 22	
24160	" " " " 23	
24161	" " " " 24	
24162	" " " " 25 Angle Buttress 25	
24163	" " " " 26	
24164	" " " " 27	
24165	" " " " 28	
24166	" " " " 29	
24167	" " " " 30	
24168	" " " " 29	
24167	" " " " 30	
24168	" " " " 31	
24169	" " " " 32	
24170	" " " " 33	
24171	" " " " 34	
24172	" " " " 35	
24173	" " " " 36	
24174	" View of upstream side of the Drungate Highway.	4-29-42
24175	" Extrados of Arch No. 37	4-29-42
24176	" " " " 38	
24177	" " " " 39	
24178	" " " " 40	
24179	" " " " 41	
24180	" " " " 42	
24181	" " " " 43	

223

Reserved for Mrs. Almonstead

24182	Florence Lake Dam - Extrados of Arch No. 44	4-29-42
24183	" " " " 45	
24184	" " " " 46	
24185	" " " " 47	
24186	" " " " 48	
24187	" " " " 49	
24188	" " Upstream face of Angle Buttress No. 49	5-5-42
24189	" " Extrados of Arch No. 50	
24190	" " " " " 51	
24191	" " " " " 52	
24192	" " " " " 53	
24193	" " " " " 54	
24194	" " " " " 55	
24193	" " " " " 54	
24194	" " " " " 55	
24195	" " " " " 56	
24196	" " " " " 57	
24197	" " " " " 58	
24198	" " " " " 13	5-8-42
24199	" " " Close up of groin bet. Arch 13 & 14, etc.	5-10-42
24200	" " " First normal ring of steel facing plates, etc.	5-14-42

224

Small Films

24201	Anita Sub. 66 K.V.	Sept. 1941
24202	" Cottage	"
24203	Artesia Sub.	"
24204	Ayusa City-Transformer Bank	"
24205	Baldwin Park Sub.	"
24206	Belmont Sub.	"
24207	Belvedere Sub.	"
24208	Bicknell Sub.	"
24209	Bixby Sub.	"
24210	Carmenita Cottage	"
24211	" Sub	"
24212	" 11 K.V. rack	"
24213	" 66 K.V. "	"
24212	" 11 K.V. rack	"
24213	" 66 K.V. "	"
24214	" Sub.	"
24215	Cherry Sub.	"
24216	City Terrace	"
24217	Claremont Sub.	"
24218	Clearwater Sub.	"
24219	Covina Sub. Bldg	"
24220	Covina 11 K.V.	"
24221	Dolores Sub.	"
24222	Downey Sub.	"
24223	Eagle Rock	"
24224	" " 4A Bank	"
24225	" " 220 K.V. rack	"
24226	" " Rear	"
24227	Cottage at Eagle Rock	"

225

Small Films

24228	Garages at Eagle Rock	Sept. 1941
24229	Eaton Sub.	"
24230	El Monte Sub.	"
24231	" " Cottage	"
24232	Ganesha Sub.	"
24233	" Cottage	"
24234	" 66 K.V. Rack	"
24235	Garfield Sub. " "	"
24236	" " 16 K.V. Rack	"
24237	Garfield Sub. Cottage	"
24238	Garvey Sub.	"
24239	Glendora Sub. ✓	"
24238	Harvey Sub.	"
24239	Glendora Sub. ✓	"
24240	Hathaway "	"
24241	" 11 K.V.	"
24242	Harbor Sub. Bldg.	"
24243	Harbor Sub.	"
24244	Hollydale Sub.	"
24245	Laguna Bell Cottages	"
24246	Laguna Bell Shop & Oil House	"
24247	Laguna Bell Warehouse	"
24248	" " Front of main Bldg.	"
24249	" " 220 K.V. Equip	"
24250	" " Transformers and rear of main Bldg.	"
24251	" " 8A Bank	"
24252	" " 66 K.V. Rack looking East	"
24253	La Verne Sub	"
24254	Linderoth Sub. 10-7-41	"



24255	Lighthipe Sub. - Transformer Bank 3C	Sept. 1941
24256	" " Looking West	"
24257	Lighthipe Cottage	"
24258	" Warehouse	"
24259	" West End of 66 K.V.	"
24260	" " " 220 K.V.	"
24261	" East End of 220 K.V.	"
24262	Linden Ave.	"
24263	Linden Ave. Sub.	"
24264	Locust Sub.	"
24265	Llano Sub.	"
24266	Los Cerritos Cottage	"
24267	Los Cerritos	"
24268	Monrovia 16 K.V. Equip.	"
24267	Los Cerritos	"
24268	Monrovia 16 K.V. Equip.	"
24269	Monrovia Cottage	"
24270	Naples Sub.	"
24271	Newmark Cottage	"
24272	" 66 K.V.	"
24273	Norwalk Sub.	"
24274	Perris Road	"
24275	Pico Sub.	"
24276	Pine Ave. Sub.	"
24277	Pomona Sub.	"
24278	Puente Sub.	"
24279	Puente Sub.	"
24280	Puente Cottage	"
24281	Ramona Sub.	"

24282	Receiving Sta. "C" - Edison transformers	Sept. 1941
24283	Ripple Sub.	"
24284	Ripple 66 K.V.	"
24285	San Gabriel Sub. 16 K.V. Rack	"
24286	San Gabriel Sub.	"
24287	San Gabriel Sub. Cottage	"
24288	San Marino Sub.	"
24289	Santa Fe Springs 11 K.V.	"
24290	Santa Fe Springs Bldg.	"
24291	" " 66 K.V.	"
24292	Santa Fe Springs Cottage	"
24293	Sierra Madre Sub.	"
24294	Signal Hill Sub.	"
24293	Sierra Madre Sub.	"
24294	Signal Hill Sub.	"
24295	Signal Hill 66 K.V.	"
24296	" 11 K.V.	"
24297	" Sub.	"
24298	Somerset 66 K.V.	"
24299	" 11 K.V.	"
24300	Somerset Cottage	"

Small Filices

24301	Somerset Sub.	Sept. 1941
24302	State St. Sub.	" "
24303	" " " 66 K.V.	" "
24304	State St. Cottages	" "
24305	State St. Sub.	" "
24306	Wabash 66 K.V.	" "
24307	Wabash Sub. Bldg.	" "
24308	" " 11 K.V.	" "
24309	Watson Cottage	" "
24310	Watson Sub.	" "
24311	Water St. Sub.	" "
24312	Watson Sub.	" "
24313	Whittier Sub.	" "
24314	H frames Chino Capistrano 115 K.V. line. <del>Mi. 21-1A Laguna Bell</del>	10/15/41
24315	" " " " " "	" "
24316	" " " " " "	" "
24317	" " " " " "	" "
24318	" " " " " "	" "
24319	"H" frame mi. 21-1A <del>Chino-Capistrano 115 KV Line</del> <del>Laguna Bell 220 KV line</del>	" "
24320	Long Beach Lighthouse Line - Cracks in 220 K.V. channel crossing tower f.dns.	Nov. 1941
24321	" " " " " " " " " "	" "
24322	" " " " " " " " " "	" "
24323	" " " " " " " " " "	" "
24324	" " " " " " " " " "	" "
24325	Shaver Lake Dam - Machine finishing surface of walkway.	9-17-41
24326	" " " - Placing dry concrete on walkway	" "
24327	" " " - Spaling on top of parapet	" "

Small Filices

24328	Spring Street & Third, taken in 1888 (Copy)	12-9-41
24329	Newmark Anita & Newmark Eaton 46 KV line - Rusty tower at Mile 3T5	12-14-41
24330	" " " " " " " "	"
24331	" " " " " " " "	"
24332	" " " " " " " "	"
24333	" " " " " " " "	"
24334	Re-arrangement of 220 KV. lines N/O Laguna Bell Sub.	1-13-42
24335	" " " " " " " "	"
24336	" " " " " " " "	"
24337	" " " " " " " "	"
24338	" " " " " " " "	"
24339	" " " " " " " "	"
24340	Lona Beach. Lt Pl #1	"
24339	" " " " " " " "	"
24340	Long Beach St. Pl. #1, Monitor windows over East firing aisle	2-3-42
24341	" " " " " Skylights & monitors over West firing aisle	"
24342	" " " " " " " machine shop & store room	"
24343	" " " " " South wall of turbine room showing large windows.	"
24344	" " " " " Interior view of turbine room looking East along So. wall	"
24345	" " " " " Large door at West End of turbine room	"
24346	" " " " " " & window at window no. of boiler room	"
24347	" " " " " East wall of boiler room showing windows	"
24348	" " " " " South wall of turbine room, showing large windows	"
24349	" " " " " East wall of transformer house showing windows	"
24350	" " " " " North wall of transformer house showing doors & windows	"
24351	Huntington Lake Dam #2, showing granite block disintegration.	10-26-41
24352	" " " " " 1 Yr. weathering granite block in parapet wall	"
24353	Shaver Walkway - Repair S. of recorder well	"
24354	Lorance Lake Dam - Amersote on Arch & Wall	"



24355	Florence Lake Dam - Paraffin on Arch #7 walkway	11-12-41
24356	" " Applying Paraffin to Arch #6	10-26-41
24357	" " Arch #2 before applying Amercote	"
24358	" " Applying Amercote Plastic to Arch #2 walkway	"
24359	Tunnel #3 outlet - Cores	6-2-41
24360	Huntington Lake Dam #1	6-23-41
24361	" " " "	"
24362	" " " Discharge of 4" weeper	"
24363	" " " " - Inspection	"
24364	" " " " Cores taken 1941 - wet	1941
24365	Project 4, Upstream at upper P.H. site	8-28-41
24366	Florence Lake - Downstream side of Arch #8	9-3-41
24367	Project 4, Upstream at upper P.H. site	8-28-41
24368	Florence Lake - Downstream side of Arch #8	9-3-41
24369	Florence Lake Dam - Arch #53	"
24370	" " " " 2.5. face granite coated Arch #2	"
24371	P.H. #2 Dam #1 West Abutment	9-4-41
24372	" " " " Showing leakage through granite	"
24373	" #6 W. Abut. granite	9-5-41
24374	Shaver Dam walkway	9-17-41
24375	Project #4, S. Abut. Site #7	9-19-41
24376	San Onofre Subsidence	10-5-41
24377	" " " "	"
24378	Old Subsidence north of recent example	"
24379	San Onofre Subsidence	"
24380	" " " "	"

24382	Project 4, Looking North across Site #5	11-15-41
24383	" " San Joaquin 900' below site #5	"
24384	" " Looking west across Site #7	"
24385	Dam site 1000' above N. Fork	"
24386	Project #4, Gully below site #7 on South bank	"
24387	" " Looking west up No. Fork	"
24388	" " " East along saddle E. of No. Fork junction	"
24389	" " Typical borrow pit area near site #7	"
24390	" " Looking upstream from below site #7	"
24391	" " Test hole B.P.1 near site #7 for Dam #7	11-27-41
24392	" " Looking upstream at lower rapids	11-28-41
24393	" " Test hole B.P.1 near site #7 for Dam #7	11-27-41
24394	" " Looking upstream at lower rapids	11-28-41
24395	" " Looking downstream at lower rapids	"
24396	" " Lower end of miners diversion near upper P.H. site	"
24397	" " Looking upstream from point 150' below section C-C	"
24398	" " Looking downstream from upper P.H. site	"
24399	Proposed road to tunnel portals - looking down No. Fk. from Pt. near saddle	12-5-41
24400	Project 4, No. Fork	12-4-41
	" " Proposed road P.H. 3 to site 5	"
	" " P. 6 & E. Wishon P.H. (#1) from road bridge	"

24401	Chino Substation	10-29-41
24402	"	"
24403	"	"
24404	"	"
24405	"	"
24406	"	"
24407	Saugus Substation	10-30-41
24408	"	"
24409	"	"
24410	"	"
24411	Rector Substation	"
24412	La Fresa Substation	10-28-41
24413	Rector Substation	"
24412	La Fresa Substation	10-28-41
24413	Barre Substation	10-29-41
24414	Magunden Substa.	"
24415	Saugus Substation	10-30-41
24416	2 <sup>nd</sup> Boulder-Chino Trans. Line - View of old & new Boulder Lines	11-3-41
24417	" " " Pulling out conductors at cross over	"
24418	Chino-Laguna Bell - Permanent Bridge on Patrol Road	"
24419	" " Erecting Vincent transposition Tower.	"
24420	" " Driving Wood piles for Tower Foundations	"
24421	" " Placing concrete for concrete pile Footings.	"
24422	" " Drilling Holes for concrete pile Footings	"
24423	2 <sup>nd</sup> Boulder-Chino Trans. Line - Clearing on 1 <sup>st</sup> & 2 <sup>nd</sup> Bo. Ch. Line	12-1-41
24424	" " " " Transposition at M216T3	"
24425	" " " " Get away of 2 <sup>nd</sup> Bo. Ch. Line	"
24426	Chino-Laguna Bell Trans. Line - Tensioning Conductor over M16T4	"
24427	" " " " " " " " " " " "	"

24428	Chino-Laguna Bell Trans. Line - Rolling Type Transposition.	12-1-41
24429	" " " " Erecting jumper stiffener Pipe, M23T1	"
24430	Photo not used - Chino-Laguna Bell - Road Drainage	"
24431	Chino-Laguna Bell Trans. Line - Raising 2 <sup>nd</sup> half of Bridge.	12-1-41
24432	Chino-Laguna Bell - M33T1 to M33T2 at Chino Substa.	12-3-41
24433	" " Erecting guard poles for stringing over 66KV line.	"
24434	" " Erecting jumpers on Eagle Bell anchor type tower	"
24435	" " Two towers M5-T2, M5-T3 & M5-T4	"
24436	Chino-Laguna Bell Trans. Line - Get away from Chino Rack	2-2-42
24437	" " " " Transposition Tower M10-T2	"
24438	" " " " Boulder Type Anchor Tower	"
24439	" " " " View of new line at M3-T1	"
24438	" " " " Boulder Type Anchor Tower	"
24439	" " " " View of new line at M3-T1	"
24440	" " " " Get away at Laguna Bell Sub.	"
24441	Williams Dam - Arizona - Taken by R. H. Spencer.	Feb. 1942
24442	" " " " " " " " " " " "	"
24443	Hydro Plant High Grove Substa. (Copy of old photo for Mr. Hayes)	"
24444	Air View of L.B. St. Pl. Looking S.E. ly.	1943
24445	" " " " (Taken by the Army in 1938)	1938
24446	B.C. #1 P.H. Unit 1 - Fabricated water wheel bucket (41)	3-1-44
24447	" " " " Upper or male die for the bowl of the bucket	"
24448	" " " " View of pressed bowl with two views of split pieces	"
24449	" " " " Positioning gig used for spot welding lugs	"
24450	" " " " Holding gig used to make full weld on lugs	"
24451	" " " " Rear view of bucket showing lugs & braces.	"
24452	" " " " Side & top view of bucket showing lugs	"
24453	" " " " Side view of bucket showing completed lug welds	"
24454	" " " " " " " " " " " "	"



234

8x10 films

24455	B.C. P.H. #1, Rocker positioner used to hold bucket for Bottom view of bucket showing lug welds welding in splitter. 3-1-44	
24456	" " " Inside or top view showing splitter welded in place. "	
24457	" " " Positioning gig used to locate holes in lugs "	
24458	" " " Template used to build up splitter piece "	
24459	" " " Underside view showing back of lip & splitter "	
24460	" " " Fabricated water wheel Bucket "	
24461	" " " View of various templates & flexible grinder. "	
24462	Proctor & Gamble Substa. (Taken by Long Beach Press Telegram) 1-28-45	
24463	Richfield Oil Corp. - Watson Refinery. " " " "	
24464	" " " " " " " "	
24465	3rd. Boulder Line, Looking West from M2 T1 Hayfield Highgroup. 9-25-45	
24466	" " " Guard Poles at Highway 70 - M51 T1. 9-24-45	
24467	" " " Lightning dampener at M51 T1 Highgroup. 9-25-45	
24466	" " " Guard Poles at Highway 70 - M51 T1. 9-24-45	
24467	" " " Lightning Dampener at M51 T1. 9-25-45	
24468	" " " Method of protecting conductors while on ground. 9-24-45	
24469	" " " (Ground wire unprotected). Conductor Reels M51 T1. 9-24-45	
24470	" " " " M52 T1 - Looking West. "	
24471	" " " Pulling in Sky Line at M52 T1 - " " "	
24472	" " " " bables at " - " " "	
24473	" " " " " " M51 T1 - " " "	
24474	" " " " " " " " " "	
24475	" " " " " " " " " "	
24476	" " " General View of Road from San Jimenes Canyon "	
24477	" " " Looking West to location of towers at M92 T1. "	
24478	" " " Looking down San Jimenes Canyon - West side of Canyon from M92 T1. "	
24479	" " " Excavation for M5 T2 West of Highgrove Looking South. "	
24479	(Cross Street) - Highgrove Substation. 9-26-45	
24480	" " " Highgrove Substation. "	
24481	" " " Road construction. Highgrove blins M5 T1. "	
24481	Not Used - to be used	

8x10 films

235

24482	3rd. Boulder Line. 1000 Palms Canyon. 9-24-45	
24483		
24484		
24485		
24486		
24487		
24488		
24489		
24490		
24491		
24492		
24493		
24494		
24495		
24496		
24497		
24498		
24499		
24500		

236

## Small Films

24501	Project 4, Proposed road to site 5	12-4-41
24502	Looking north from site 5 borrow pit	"
24503	Site 5 borrow pit looking East	"
24504	Project 4, Site 5 borrow pit from South	"
24505	Site 5 borrow pit looking East	"
24506	Site 7, Looking west across site 7	12-5-41
24507	Proposed road No. Fork - West from saddle	"
24508	Proposed road to site 5 - Looking dis. from below Italian bar bridge	"
24509	Looking South across saddle to Long ridge	"
24510	Project 4, Looking upstream from lower Powerhouse site	"
24511	" " " " " " " "	"
24512	Proposed road to site 5, Looking East up S. J. River	"
24513	Proposed road to site 5, Looking East up S. J. River	"
24512	Proposed road to site 5, Looking East up S. J. River	"
24513	Project 4, Bridge below Italian Bar	"
24514	" " Looking upstream from bridge below lower site	"
24515	Florence Lake Dam #1 Arch - west side	12-8-41
24516	Huntington Lake Dam #1, New spillway Looking down	12-9-41
24517	Huntington Lake Dam #1 Spillway Spalling on top of dividing wall 1937 constr.	"
24518	" " " " " " " "	"
24519	" " " " " W. Wall	"
24520	" " " " East dividing wall in spillway 1937 constr.	"
24521	Typical pattern cracked boulder at H.L. Dam	"
24522	Italian Bar, looking downstream	1-7-42
24523	Project 4, Italian Bar - South side	"
24524	" 4, Site #3 below Hallock Creek	"
24525	" 4, Gravel Bar at P.H. #3	"
24526	" 4 Italian Bar looking upstream	"
24527	Italian Bar looking upstream	"

237

## Small Films

24528	Project 4, Gravel bars above P.H. #3	1-7-42
24529	" " Proposed road P.H. 4 to Dam 7, site 5	1-8-42
24530	Looking downstream at Sites 4 & 5	1-23-42
24531	"Last Hope" Bar	"
24532	Site 5, South abutment	"
24533	Looking across N. Fork towards N. Portal of Longridge tunnel	"
24534	Looking W. across N. Fk. siphon	"
24535	Looking downstream at sites 4 and 5	"
24536	Old Placer mine across river from "Last Hope" bar	"
24537	Looking East across N. Fk. toward portal of short tunnel	"
24538	Bridge site below "Last Hope" bar	"
24539	Looking west across siphon site	"
24538	Bridge site below "Last Hope" bar	"
24539	Looking west across siphon site	"
24540	Looking up N. Fk. from siphon site	"
24541	Looking upstream at site 5	"
24542	South side of river from site #4	"
24543	South abutment Site #5 (Upper site)	"
24544	South abutment site 5	"
24545	North abutment Site #5	1-24-42
24546	North abutment 200' upstream from site 5	"
24547	North abutment just below Site 4	"
24548	North abutment upstream from site 5	"
24549	North abutment site 5	"
24550	North abutment Site 5	"
24551	Possible tunnel portals, site 5	"
24552	Ashfork Steel Dam - Arizona Taken by R. W. Spencer	Feb. 1942
24553	" " " " Downstream face	"
24554	" " " " " " " "	"



238

## Small Films

24555	Ashfork Steel Dam - Arizona. Downstream face, Taken by R.H. Spence	Feb. 1942
24556	Williams Dam - Arizona - Upstream face	" " "
24557	" " " " " " "	" " "
24558	" " " Spillway Channel	" " "
24559	Ashfork Dam, Steel - Arizona. West Abutment	" " "
24560	Huntington Lake Dam #1, Cracking and back seepage on un-reinf. gunite	4-3-42
24561	" " " Photo #1, Showing upstream face	" "
24562	" " " West end showing gunite band	" "
24563	" " " East end	" "
24564	" " " #1 Detail of pilaster and adjacent gunite repair	" "
24565	" " " Spillway showing Parker type of pattern cracking in 1937	" "
24566	" " " #2 Showing gunite repair on upstream face	" "
24565	" " " Spillway showing Parker type of pattern cracking in 1937	" "
24566	" " " #2 Showing gunite repair on upstream face	" "
24567	" " " Intake to Huntington-Shaver Cond.	" "
24568	" " " #3-A	" "
24569	" " " #3 Showing disintegration elev. 6915-22	" "
24570	" " " #3 Spalling since ice formed last fall.	" "
24571	Big Creek #4 - Looking down N. fork toward Project 4	3-13-42
24572	Dam #1, B.C. #3, Reservoir	3-15-42
24573	Kaiser Pass - Snow motor on Kaiser Pass	4-7-42
24574	" " " " " " " near " "	" "
24575	Florence Lake Dam Arch 51 - Detail of joint treatment	4-8-42
24576	" " " Chipping Arch #52	" "
24577	" " " Diversion Dam	" "
24578	" " " Dam Arch 13	" "
24579	" " " Disintegration of Amercole covered test block	" "
24580	" " " Arch #7 Insulmatic coated	" "
24581	" " " " 53	" "

## Small Films

239

24582	Florence Lake Dam River section	4-8-42
24583	" " " Paraffin treated gunite Arch 6	" "
24584	" " " Arch #8 Linseed oil waterproofing	" "
24585	" " " Asbestos coated Arch 8	" "
24586	Oil well derricks in vicinity of Long Beach, Steam Pl.	Jul. 1940
24587	" " " " " " "	" "
24588	" " " " " " "	" "
24589	" " " " " " "	" "
24590	" " " " " " "	" "
24591	" " " " " " "	" "
24592	" " " " " " "	" "
24593	" " " " " " "	" "
24594	" " " " " " "	" "
24593	" " " " " " "	" "
24594	" " " " " " "	" "
24595	" " " " " " "	" "
24596	" " " " " " "	" "
24597	" " " " " " "	" "
24598	" " " " " " "	" "
24599	" " " " " " "	" "
24600	" " " " " " "	" "

240

## Small Films

24601	Oil Well derricks in vicinity of Long Beach St. Plant	Jul. 1940
24602	" " " " " " " "	"
24603	" " " " " " " "	"
24604	" " " " " " " "	"
24605	" " " " " " " "	"
24606	" " " " " " " "	"
24607	Showing hole treated with creosote using pressure grease gun. Misc. Distr.	4-2-42
24608	" " " " " " " "	"
24609	" " " " " " " "	"
24610	" " " " " " " "	"
24611	" " " " " " " "	"
24612	" " " " " " " "	"
24611	" " " " " " " "	"
24612	" " " " " " " "	"
24613	" " " " " " " "	"
24614	" " " " " " " "	"
24615	Kern River #1 Spillway 1907 (Copy)	6-1942
24616	" " " " " " " "	"
24617	" " " " " " " "	"
24618	B.C. Project 4	3-8-42
24619	" " Looking up penstock line from Power House	3-13-42
24620	" " Looking down penstock line from top of penstock	"
24621	Shaver Lake Tunnel #5 intake trash rack	3-7-42
24622	Shaver Dam - Pattern cracking on upstream face.	"
24623	" " Typical pattern cracking on gunite parapet wall cap.	"
24624	" " Solution pits and disintegration at cracks on upstream face	"
24625	Shaver Reservoir, showing sunken logs	"
24626	Old rock filled dam at Shaver	"

241

## Small Films

24628	Shaver Reservoir - Showing old crib dam	3-7-42
24629	Florence Lake Dam - Arch #2 Gunite	4-8-42
24630	" " " " 13. Steel plate membrane	6-26-42
24631	" " " " #9 Coated with Carbozite	"
24632	" " " " 12 hot waterproofed	"
24633	" " " " 52 Coated with gunite May 1942	"
24634	" " " " 13 junction of steel plate face & walkway	"
24635	" " " " 13 Covered with welded steel plate	"
24636	" " " " #2 Coated with gunite in May 1940	"
24637	" " " " #8 Coated with Asbestite	"
24638	Tests - P.C.A. "farm" near Chicago	6-16-42
24639	" P.C.A. "farm" " "	"
24638	Tests - P.C.A. "farm" near Chicago	6-16-42
24639	" P.C.A. "farm" " "	"
24640	" P.C.A. "farm" near Chicago. Cover. placed in fall of 1941	"
24641	Distr. lines - Showing tree conditions on Ventura-Colonia Tel. line.	June 42
24642	" " " " " " " "	"
24643	" " " " " " " "	"
24644	" " " " " " " "	"
24645	Florence Lake Dam - River Section	5-21-42
24646	" " " Pattern cracking U.S. face Arch #55	"
24647	" " " Arch #54	"
24648	Long Beach St. Sta. - Replacement of glass, etc.	Aug. 1942
24649	" " 5 in. reinforced gunite slabs, etc.	"
24650	" " 10 in. " " " "	"
24651	" " 10 " " " " "	"
24652	" " " " " " "	"
24653	" " 10 in. thick by 12 in. high pre-cast conc. beams.	"



242

## Small Films

24655	L. B. Steam Sta. - 2 ft thick by 24 ft. wall.	Aug. 1942
24656	L. B. Steam Sta. - Pl. No. 3, windows and ventilator	Aug. 1942
24657	" " " " " 2 " doorway	"
24658	" " " " " 2, Looking east.	"
24659	" " " " " 2 So. Side, looking west	"
24660	" " " " " 2 No. " , west end	"
24661	" " " " " 2 Girl view, constr. in progress	"
24662	" " " " " 3 Interior view. Windows on North wall	"
24663	" " " " " 3 Skylight & monitor over boiler room	"
24664	" " " " " 3 Skylight over turbine room, East end	"
24665	" " " " " 3 Window at East end of boiler room	"
24666	Glorance Lake Dam - Placing Test slabs Arch 26	9-6-42
24665	" " " " " 3 Window at East end of boiler room	"
24666	Glorance Lake Dam - Placing Test slabs Arch 26	9-6-42
24667	" " " " " Making slump test, " "	9-16-42
24668	" " " " " Preparation for test slabs, Arch 34	"
24669	" " " " " Plant set up for test slabs	9-6-42
24670	" " " " " Preparation for test slabs, Arch 34	9-26-42
24671	Showing condition of County Road, Crossing K.R. #3 Penstocks	10-23-42
24672	" " " " " " " "	"
24673	" " " " " " " "	"
24674	" " " " " " " "	"
24675	" " " " " " " "	"
24676	" " " " " " " "	"
24677	" " " " " " " "	"
24678	" " " " " " " "	"
24679	" " " " " " " "	"
24680	" " " " " " " "	"

243

## Small Films

24682	Showing condition of County Road, Crossing K.R. #3 Penstocks	10-23-42
24683	Kern River No. 3, Showing condition of Generator #1	11-12-42
24684	" " " " " " " "	"
24685	" " " " " " " "	"
24686	" " " " " " " "	"
24687	" " " " " " " "	"
24688	" " " " " " " "	"
24689	Kern River #1, Undermined rack foundation	11-22-42
24690	" " " " " " " "	11-22-42
24691	" " " " " " " "	11-22-42
24692	Kern River #1 Method of placing concrete around intake	11-22-42
24693	" " " " " " " "	"
24692	Kern River #1 Method of placing concrete around intake	11-22-42
24693	" " " " " " " "	"
24694	Kern River #1 Intake showing reservoir above dam.	11-22-42
24695	" " " " " " " "	"
24696	Kern River #1 Upper trash rack foundation	11-22-42
24697	" " " " " " " "	"
24698	" " " " " " " "	"
24699	" " " " " " " "	"
24700	" " " " " " " "	"

244

Small films Reserved for Lang June 17, 1942

24701	Florence Lake Dam - Close up of 9" sealing plate.	5-17-42
24702	" " " " " " " "	"
24703	" " " One of the four 1 1/2" dia. drains	5-20-42
24704	" " " Arch 13 Close up of lower horizontal seal.	5-23-42
24705	" " " " " Progress picture.	"
24706	" " " " " " " "	5-31-41
24707	" " " " " Close up of side seals, Arch 13	6-1-42
24708	" " " " " Showing operation of bending 24" steel	"
24709	" " " " " Skylining 5' x 8' sheets from ground.	"
24710	" " " " " Placing steel sheets on Arch.	6-2-42
24711	" " " " " sheets on anchor bolts	"
24712	" " " " " Applying Ironhide primer.	6-3-42
24711	" " " " " sheets on anchor bolts	"
24712	" " " " " Applying Ironhide primer.	6-3-42
24713	" " " " " Showing top course of sheets	6-5-42
24714	" " " " " Guniting upper horizontal key	6-6-42
24715	" " " " " Welding face plates.	"
24716	" " " " " Final progress pictures	6-11-42
24717	" " " " " Cutting bottom key at base of Arch 54	3-28-42
24718	" " " " " Excavation bet. Arches 54	"
24719	" " " " " Progress picture	4-8-42
24720	" " " " " Completed extension of 8" fish pipe	4-10-42
24721	" " " " " Intake trash rack	"
24722	" " " " " First guniting on Arch 54	"
24723	" " " " " Placing first concrete in forms	4-15-42
24724	" " " " " Showing method of waterproofing	4-22-42
24725	" " " " " Forms for west sluice gate ext.	5-2-42
24726	" " " " " Gunite on Arch 52	"

245

Small films Reserved for Lang

24728	Florence Lake Dam - Progress picture, west sluice gate	5-9-42
24729	" " " Spraying raw linseed oil, Arch 53	5-13-42
24730	" " " Application of " " " "	"
24731	" " " Progress picture, first guniting Arch 52.	5-16-42
24732	" " " Guniting on Arch 52	5-19-42
24733	" " " Completed west sluice gate, Arch 53	"
24734	" " " Close up of guniting on Arch 52	5-22-42
24735	" " " Arches 52 & 53 after completion of work.	5-31-42
24736	" " " A portion of Arch 8.	6-1-42
24737	" " " Downstream side of Arch 53	6-10-42
24738	" " " " " " " 52	"
24739	" " " " " " " 52	"
24738	" " " " " " " 52	"
24739	" " " " " " " 52	"
24740		
24741		
24742		
24743		
24744		
24745		
24746		
24747	Florence Lake Dam -- Close up of Arch 8	3-31-43
24748	" " " " " " " Arch 54	3-29-43
24749	" " " Applying sonic test on bars	4-10-43
24750	Huntz-Pitman-Shaver Tunnel. Por. of concreted tunnel	9-18-41
24751	" " " " " " " "	"
24752	" " " " " " " "	"
24753	Big Creek P. H. #2, #1 Bucket, mfg. #89	6-21-42



246

Small Films

24755	Big Creek P.H. #2, #3 Bucket, R.H. Infq. #87	6-21-42
24756	" " " 4 " " #86	"
24757	" " " 5 " " #85	"
24758	" " " 6 " " #84	"
24759	" " " 7 " " #83	"
24760	" " " 8 " " #82	"
24761	" " " 9 " " #81	"
24762	" " " 10 " " #94	"
24763	" " " 11 " " #79	"
24764	" " " 12 " " #78	"
24765	" " " 13 " " #77	"
24766	" " " 14 " " #76	"
24767	" " " 15 " " (missing)	"
24768	" " " 14 " " #76	"
24767	" " " 15 " " (missing)	"
24768	" " " 16 " " #78	"
24769	" " " 17 " " #72	"
24770	" " " 18 " " #92	"
24771	" " " 19 " " #91	"
24772	" " " 20 " " #90	"
24773	" " " 21 " " #71	"
24774	" " " #1 " L.H. #61	"
24775	" " " #2 " " #62	"
24776	" " " #3 " " #63	"
24777	" " " 4 " " #53	"
24778	" " " 5 " " #65	"
24779	" " " 6 " " #60	"
24780	" " " 7 " " #74	"
24781	" " " 8 " " #93	"

Reserved for Lang. Small Films

247

24782	Big Creek P.H. 2, #9 Bucket, L.H. Infq. #68	6-21-42
24783	" " " 10 " " 67	"
24784	" " " 11 " " 66	"
24785	" " " 12 " " 70	"
24786	" " " 13 " " 51	"
24787	" " " 14 " " 52	"
24788	" " " 15 " " 54	"
24789	" " " 16 " " 56	"
24790	" " " 17 " " 57	"
24791	" " " 18 " " 58	"
24792	" " " 19 " " 59	"
24793	" " " 20 " " 60	"
24794	" " " 19 " " 59	"
24793	" " " 20 " " 60	"
24794	" " " 21 " " #95	"
24795	Kaweah No. 1 Flume - Looking upstream	9-14-41
24796	" " " " View of flume under full flow	"
24797	" " " " View of Old Flume under full flow.	9-12-41
24798	" " " " " New " " " "	9-14-41
24799	" " " " " Old " " " "	9-12-41
21800	" " " " " New " " " "	9-14-41

248

## Small items

24801	Htg. Lake Dam #2, Close up of damaged core	10-24-42
24802	" " " Entrance to gate house.	"
24803	" " " Gen. view of the 10' Intake gate house.	"
24804	" " " Interior " " " " " "	"
24805	Kaueah #2 Flume - Close up	10-7-42
24806	" " " Side view of flume	"
24807	" " " Close up of floor	"
24808	" " " View of relining.	"
24809	" " " Applying final spray coat of emulsion.	"
24810	" " " Compressor and pressure pot.	"
24811	Florence Lake Dam - Excavating along base of Arch No. 52	11-24-42
24812	" " " Hand tamping earth backfill	11-25-42
24811	Florence Lake Dam - Excavating along base of Arch No. 52	11-24-42
24812	" " " Hand tamping earth backfill	11-25-42
24813	" " " Excavating base of Arch #52	11-28-42
24814	" " " " in front of Stoney Gate	"
24815	" " " Progress picture, showing backfill	"
24816	" " " " Bryant Crew	"
24817	" " " Showing Sonic test bars.	12-3-42
24818	" " " " Backfilling in river channel.	"
24819	" " " " placement of concrete	12-10-42
24820	" " " Close-up showing application of 15# felt.	12-11-42
24821	" " " Showing application of waterproofing	"
24822	" " " " start of pour in box, etc.	12-12-42
24823	" " " Hand placing earth backfill etc.	12-13-42
24824	" " " Hauling material for rock surfacing	12-19-42
24825	" " " Close-up of gunite key at base of Arch 13	"
24826	" " " River section. Chipping on Arches 51 & 55	10-27-42
24827	" " " Arch #	"

249

24828	Florence Lake Dam - Experimental concrete walkway repair	9-5-42
24829	" " " " " " " "	"
24830	" " " " " " " "	"
24831	" " " " " " " "	9-24-42
24832	" " " " " " " "	"
24833	A+B " " Completed backfill.	1-1-43
24834	" " " " Arch No. 12	"
24835	" " " " Arches 50, 51 & 52	"
24836	" " " " " 54, 55 & 56	"
24837	" " " " " 57 & 58	"
24838	" " " " River section of Arches	"
24839	B.C.P.H. #8 - Showing amount of sand & rock bet. tailrace towers	1-17-43
24838	" " " " River section of Arches	"
24839	B.C.P.H. #8 - Showing amount of sand & rock bet. tailrace towers	1-17-43
24840	" " " " rock & sand accumulation	"
24841	" " " " accumulation of sand & rock	2-21-43
24842	" " " " " " " "	"
24843	" " " " erosion in concrete floor	"
24844	Big Creek No. 1 - Close up of Bucket No. 3	3-24-43
24845	" " " " " " " " No. 9	"
24846	" " " " " " " " No. 3	"
24847	" " " " " " " " #10, 22, 44, 46, 47, 48, 52 & 53	"
24848	" " " " " " " " No. 3	"
24849	" " " " General erection view	"
24850	Huntington Lake Dam No. 1 - Core taken from upstream face	4-23-43
24851	" " " " Cracking & back seepage	4-4-43
24852	" " " " Looking west from Sta. 7+75	"
24853	" " " " " " " " 6+25	4-19-43



250

Reserved for Mrs. Olinsted

24855	Htg. Lake Dam No. 1. View of siphon spillway	4-4-43
24856	" " " No. 2 Looking east toward intake	4-19-43
24857	" " " " " Showing intake to Huntington-Shaver Conduit	"
24858	" " " " " 3A View showing upstream face	"
24859	" " " " " No. 3 Upstream face showing disintegration	"
24860	" " " " " " " "	"
24861	Florence Lake Dam - Upstream face of Arches 1 & 2	4-10-43
24862	" " " " " " 4 to 10	"
24863	" " " " " " 11 to 25	"
24864	" " " " " " 26 to 36	"
24865	" " " " " " 37 to 49	"
24866	" " " " " " 50 to 58	"
24867	" " " " " " 37 to 49	"
24868	" " " " " " 50 to 58	"
24869	" " " " " " 37 to 49	"
24870	" " " " " " 50 to 58	"
24871	" " " " " " Erection of trash racks.	"
24872	July #4 Regulating Reservoir, shows reservoir after it was drained	4-26-43
24873	" " " " " from bottom of reservoir	4-29-43
24874	" " " " " before sluicing was stopped	"
24875	" " " " " " " "	"
24876	Florence Lake Dam - River Section Arches	5-6-43
24877	Florence Lake Dam - River section Arches	5-8-43
24878	" " " " " Vertical cracks in 1" Gunite	5-6-43
24879	" " " " " Arch #12	"
24880	" " " " " Test paints on Arch #12	5-8-43
24881	" " " " " Testing for leaks, Arch 13	5-8-43
24882	Florence Lake Dam - Waterproofing Arch 12	5-8-43
24883	" " " " " Intrados of Arch 13	7-17-43
24884	" " " " " " " "	"
24885	" " " " " " " "	"
24886	" " " " " " " "	"
24887	" " " " " " " "	"
24888	" " " " " " " "	"
24889	" " " " " " " "	"
24890	" " " " " " " "	"
24891	" " " " " " " "	"
24892	" " " " " " " "	"
24893	" " " " " " " "	"
24894	" " " " " " " "	"
24895	" " " " " " " "	"
24896	" " " " " " " "	"
24897	" " " " " " " "	"
24898	" " " " " " " "	"
24899	" " " " " " " "	"
24900	" " " " " " " "	"

Reserved for Mrs. Olinsted

251

24882	Florence Lake Dam - Intrados of Arch 52	7-17-43
24883	" " " " " " 53	"
24884	" " " " " " 54	"
24885	" " " " " " 55	"
24886	" " " " " " 56	"
24887	" " " " " " 57	"
24888	" " " " " " Cores taken from extrados of Arch 9	11-12-43
24889	" " " " " " " " 27, 9 & 12	"
24890	" " " " " " " " 15 & 16	"
24891	" " " " " " " " 16 & 17	"
24892	" " " " " " " " 14 & 15	"
24893	" " " " " " " " Drilling core from extrados of Arch 15	"
24894	" " " " " " " " 14 & 15	"
24895	" " " " " " " " Drilling core from extrados of Arch 15	"
24896	Florence Lake Dam - Gunite on Arch 17 & 18	11-18-43
24897	Big Creek No. 3 - Unit No. 1.	1-4-44
24898	Florence Lake Dam - Appearance of Test on Arch #12	12-1-43
24899	Florence Lake Dam - Asbestile covered Arches	12-1-43
24900	Florence Lake Dam - Asbestile Covered Arches	12-1-43
24901	" " " " " " Forms for concrete Box at 8" fish pipe	11-5-43
24902	" " " " " " Construction of new Intake for 8" fish pipe	"





24955	Alhambra - Open yard	1941
24956	" Salvage warehouse	
24957	" Crane runway	
24958	" Transf. oil storage house	
24959	" Open shed - <del>Beag.</del>	
24960	" Tank por. of Pole treating plant	
24961	" Genl. store platform	
24962	" Boiler House	
24963	" Creosote & fuel oil storage tanks	
24964	Bandini Sub.	
24965	" "	
24966	" "	
24967	" "	
24968	Beverly Hills Sub.	
24969	" " Transformers	
24970	" " - Oil Cooler	
24971	" " "	
24972	" " - Cottage	
24973	Baldwin Park Commercial Office	
24974	Carson Sub	
24975	" "	
24976	" "	
24977	Chancellor Canfield Midway Sub.	
24978	Compton Sub.	
24979	Columbia Steel Sub.	
24980	Compton Warehouse & Garage	
24981	Cudahy Sub.	

24982	Cudahy Sub.	1941
24983	" "	
24984	" "	
24985	Covina Warehouse	
24986	Covina Commercial Office	
24987	Culver City Sub.	
24988	" " "	
24989	" " "	
24990	Del Sur Sub.	
24991	El Porto Sub.	
24992	El Segundo Sub.	
24993	" " Sub.	
24994	" " " "	
24995	" " Sub.	
24996	" " "	
24997	" " "	
24998	" " "	
24999	Goodrich Rubber Co.	
25000	Lage Sub. - Bell Gardens	

256

## Small Films

25001	Gorman Sub. - On Ridge Route at K.R. #1	1941
25002	Garden Heights Sub.	"
25003	Gould Sub.	"
25004	Gould Sub.	"
25005	Gould Sub.	"
25006	Gould Sub.	"
25007	Graham Sub.	"
25008	Graham Sub.	"
25009	Granada Sub.	"
25010	" "	"
25011	" "	"
25012	Hawthorne Sub.	"
25011	" " " "	"
25012	Hawthorne Sub.	"
25013	Hawthorne Sub.	"
25014	Huntington Park Comm'l. Office	"
25015	Huntington Park Sub.	"
25016	Huntington Park Comm'l. Office	"
25017	Huntington Park Warehouse & garage	"
25018	" " " "	"
25019	Inglewood Commercial Office	"
25020	Inglewood Warehouse & garage	"
25021	" " " "	"
25022	Inglewood Sub.	"
25023	Inglewood Sub. - Rack	"
25024	Inglewood Sub. - Transformers	"
25025	Inglewood Sub. - Operators Cottage	"
25026	Lancaster Sub. Transformers	"
25027	" " " "	"

257

## Small Films

25028	Lancaster Sub. -
25029	" " Transformers
25030	" " Oil storage tanks
25031	Lancaster Comm'l. Office
25032	" Warehouse & garage
25033	Lancaster Warehouse & garage
25034	La Brea Sub.
25035	" " Hydro cooled condensers
25036	" "
25037	" " Condenser transformers
25038	" "
25039	" " Warehouse transformers
25038	" "
25039	" " Warehouse building
25040	" " Type "T" cottage
25041	Little Rock Sub.
25042	La Canada Sub.
25043	Lynwood Sub.
25044	Lennox Sub.
25045	Long Beach Commercial Office
25046	" " " "
25047	Long Beach Warehouse
25048	Long Beach Warehouse
25049	Long Beach Warehouse - garage
25050	L.A. #3 Sub. Alhambra & Moulton Ave.
25051	L.A. #3 Sub.
25052	" " " "
25053	Los Angeles Main Garage



258

## Small Films

- 25055 Los Angeles Main Garage  
 25056 Los Angeles Main Garage  
 25057 " " "  
 25058 Los Angeles Main Garage - Repair Shop  
 25059 Los Angeles Main Garage - Paint Shop  
 25060 Los Angeles Main Garage - Wash & grease rack  
 25061 Manhattan Sub. -  
 25062 Madrid Sub.  
 25063 Malibu Sub.  
 25064 Maywood Sub.  
 25065 Mozart Sub.  
 25066 Montebello Commercial Office  
 25065 Mozart Sub.  
 25066 Montebello Commercial Office  
 25067 " Sub.  
 25068 Montebello Warehouse -  
 25069 Montebello Warehouse - Loading platform.  
 25070 Marine Sub. - Santa Monica  
 25071 Marine Sub. - Operators cottage  
 25072 Marine Sub. - Transformers & rack  
 25073 Marine Sub. - "  
 25074 Mac Neal Sub. - Burbank  
 25075 Mac Neal Sub. - Rack  
 25076 Mac Neal Sub. - 16 K.V. Rack  
 25077 Mac Neal Sub. - Cooling tower  
 25078 Mac Neal Sub. - Cottages  
 25079 Moneta Sub. -  
 25080 Moneta Sub. - Transformers.

1941

259

## Small Films

- 25082 Pearl Sub. - Cottage  
 25083 Porter Sub. - San Fernando  
 25084 Porter Sub. - Transformers  
 25085 Perry Sub. - Torrance  
 25086 Pomona Warehouse & Garage  
 25087 Pomona Warehouse & Garage  
 25088 Ocean Park Sub. -  
 25089 Palos Verdes Sub.  
 25090 Randolph Sub. -  
 25091 Randolph Sub. - 16 K.V. Rack.  
 25092 Randolph Sub. - Transformers  
 25093 Randolph Sub. - Type T. Cottage.  
 25092 Randolph Sub. - Transformers  
 25093 Randolph Sub. - Type T Cottage  
 25094 Redondo Sub. -  
 25095 Redondo Sub. - Operator's Cottage  
 25096 Redman Sub. - Lancaster  
 25097 Redondo E.D.S. -  
 25098 Redondo Steam Plant  
 25099 Redondo Commercial Office  
 25100 Samson Sub. - (non-Edison Co. prop.)

260

## Small Films

25101	Southgate Sub. -	1941
25102	Santa Monica Commercial Office	"
25103	Santa Monica Warehouse & Garage	"
25104	San Vicente Sub. - Transformers	"
25105	San Vicente Sub. - Santa Monica	"
25106	San Vicente Sub. - Operator's Cottage	"
25107	San Fernando Sub.	"
25108	San Fernando Sub. - Operator's Cottage	"
25109	San Fernando Sub. -	"
25110	San Fernando Sub. - 4 Car garage	"
25111	Saugus Sub. -	"
25112	Saugus Sub. - Transformers	"
25111	Saugus Sub. -	"
25112	Saugus Sub. - Transformers	"
25113	Saugus Sub. - Rack	"
25114	Saugus Sub. - Rack	"
25115	Saugus Sub. - Kelman Oil Switches	"
25116	Saugus Sub. - 75 Ton crane	"
25117	Saugus Sub. - Water Tower	"
25118	Saugus Sub. - Water Cooling Tower	"
25119	Saugus Sub. - Type T Cottages	"
25120	Saugus Sub. - 12 car garage	"
25121	Saugus Sub. - 2 car garage	"
25122	Saugus Sub. -	"
25123	Sawtelle Warehouse & garage	"
25124	Santa Monica Sub. -	"
25125	Sawtelle Warehouse & garage	"
25126	Walteria Sub. - Lomita	"

261

## Small Films

25128	Walteria Sub. - Cottage, garage	"
25129	Whittier Commercial Office	"
25130	Torrance Sub. -	"
25131	Torrance Sub. - rack	"
25132	Torrance Sub. - rack	"
25133	Torrance Sub. - Operator's cottages	"
25134	Westflor Sub. -	"
25135	Westflor Sub. -	"
25136	Westflor Sub. -	"
25137	Westflor Sub. - Operator's Cottage	"
25138	Victoria Sub. - Redondo Beach	"
25139	Westflor Sub. - Operator's cottage	"
25138	Victoria Sub. - Redondo Beach	"
25139	Victoria Sub. - Rack	"
25140	Victoria Sub. - Rack	"
25141	Victoria Sub. - Type T. Cottage	"
25142	Long Beach Warehouse	1941
25143	Long Beach Warehouse	"
25144	Covina Warehouse	"
25145	Baldwin Park Commercial Office	"
25146	Transmission Dept. - Sadder truck. In Armistice Day Parade	11-11-42
25147	" " Distribution Truck. " " "	"
25148	" " Mobile Radio Sta. " " "	"
25149	Transmission Maintenance Crew - " " "	"
25150	Transm. Dept. Heavy Maintenance truck " " "	"
25151	Mill Creek #1 Bucket failure	5-14-39
25152	" " " " " "	"
25153	" " " " " "	"



262

Small Films

25155	Mill Creek #1 bucket failure	5-14-39
25156	" " " " "	"
25157	" " " " "	"
25158	" " " " "	"
25159	" " " " "	"
25160	" " " " "	"
25161	Long Beach St. Pl. - Removing Unit #8	1-18-43
25162	Long Beach S. P. Unit #7, Dual Driven exciter set	1-19-43
25163	" " " " " Evaporator & Evaporator Drip pump	"
25164	" " " " " 18 <sup>th</sup> stage Heater Drip Pump	"
25165	" " " " " Main Turbine & generator	"
25164	" " " " " 18 <sup>th</sup> stage Heater Drip Pump	"
25165	" " " " " Main Turbine & generator	"
25166	" " " " " Turbine end of main Unit	"
25167	Fontana Power Company Transf. Plant #24 Lytle Cr. wash nr. Power House	1-1-43
25168	" " " " #3 " " " "	"
25169	" " " " #1 " " " No. of Highland	"
25170	" " " " #13 " " " S.E. cor. Sec. 15	"
25171	" " " " #26 " " " At Devore Road	"
25172	" " " " #32 " " " Near Locust Ave.	"
25173	" " " " #28 " " " Power House	"
25174	" " " " #23 Baseline near Alder Ave.	"
25175	" " " " #31 " " " Citrus Ave.	"
25176	" " " " Haymill, Declez Cattle Assn. Slover Rd.	"
25177	" " " " Ranch Shop - Slover Ave.	"
25178	" " " " Hog Ranch General	"
25179	" " " " Hay mill, Declez Hog Ranch	"
25180	" " " " Hatchery Upland Ave. nr. Juniper	"

263

Small Films

25182	Fontana Power Co. Transf. #11 Booster #11 Juniper Ave. at Santa Fe Tracks	1-1-43
25183	" " " " 21 Oleander Ave. at Santa Fe Tracks	"
25184	" " " " Plant #17 Cherry Ave. at Santa Fe Tracks	"
25185	" " " " #30 Hemlock Ave. near Lookhill Blvd.	"
25186	" " " " #20 Manning Ave. near Cherry Ave.	"
25187	" " " " Walnut Drier - Slover Ave.	"
25188	" " " " Producers warehouse, Orange way near Sierra	"
25189	" " " " Citrus Basin. Mango at Pac. Elec. Tracks.	"
25190	" " " " Plant #28 Merrill Ave. near Locust Ave.	"
25191	Lytle Creek Intake - Looking toward sluice gates	1-28-43
25192	" " " " Showing damage to fence and grounds, downstream	"
25193	" " " " Looking upstream at sluice gates	"
25192	" " " " Showing damage to fence and grounds, downstream	"
25193	" " " " Looking upstream at sluice gates	"
25194	Sierra P.H. - Looking downstream from P.H. showing damaged tailrace	1-31-43
25195	Looking toward Sierra P.H. showing damage to Ontario #1	"
25196	Looking downstream at highway location about 200 yds. below Sierra P.H.	"
25197	Sierra Intake below Camp Baldy.	"
25198	" " " " Showing damage to fence, etc	"
25199	Borel P.H. - Removing 2 Obsolete generating units	4-15-43
25200	" " " " " " " "	"

264

## Small Films

25201	Borel P.H. Removing 2 obsolete generating units	4-15-43
25202	" " " " " "	"
25203	" " " " " "	"
25204	" " " " " "	"
25205	Long Beach S.P. - Progress dismantling #8	2-3-43
25206	" " " " " "	2-8-43
25207	" " Unit #8 Evaporator - inner and outer housing B	3-10-43
25208	" " Unit #8 Evaporator - inner baffle "A"	"
25209	" " " #8 " Outer baffle "A"	"
25210	" " " " " " " "	"
25211	" " " " " Inner baffle "A"	"
25212	" " Detail of support for balancing #8	3-14-43
25217	" " " " " Inner baffle "A"	"
25212	" " Detail of support for balancing #8	3-14-43
25213	" " Moving House Generator	3-15-43
25214	" " Progress dismantling #8	"
25215	" " Setup for balancing #8 rotor	3-14-43
25216	" " Detail of support for balancing #8	"
25217	" " Balancing #8 Rotor	3-15-43
25218	" " Reblading #8 turbine	2-16-43
25219	" " #7 Unit CO and water fire control system	1-19-43
25220	" " " " Aux. Gen. Air Cooler	"
25221	" " " " Smoke detector	"
25222	" " " " Cond. Rear & Oil Coolers	"
25223	" " " " Cond. rear & Atmospheric Relief valve	"
25224	" " " " Hytor Pumps	"
25225	" " " " Turbine gage board	"
25226	" " " " 7 Panel D.C. Exciter Switchboard	"
25227	" " " " " " " "	"

265

## Small Films

25228	Long Beach S.P. Unit #7 Aux. Generator	1-19-43
25229	" " " " Tanks, CO <sub>2</sub> Fire Control system	"
25230	" " " " " "Booster Pumps"	"
25231	" " " " " Condenser Hot Well & Condensate Pumps	"
25232	" " " " " Gland Steam Condenser & the jets	"
25233	" " " " " Main Generator Air Coolers	"
25234	" " " " " Top of Deaerator	1-20-43
25235	" " " " " Base of Deaerator	"
25236	" " " " " Pipe Gallery	"
25237	" " " " " 11 <sup>th</sup> Stage Heater	"
25238	" " " " " General View - Unit 8 removed	1-21-43
25239	" " " " " Condenser Front and Gage Board	"
25238	" " " " " General View - Unit 8 removed	1-21-43
25239	" " " " " Condenser Front and Gage Board	"
25240	" " " " " Water Level Alarm Control	"
25241	" " " " " Unit #8 - Dismantling progress	2-22-43
25242	" " " " " Removing tubes from #8 Gen Air Coolers Tubes & Tube sheets in good cond.	2-24-43
25243	" " " " " Unit #8 Air Ejectors - dismantled for cleaning & repair	"
25244	" " " " " Typical Crating of Unit 8 piping for shipment to Russia	"
25245	" " " " " Pitting on condensate pump suction	"
25246	" " " " " Corrosion on " " "	"
25247	" " " " " Typical skidding & protection for shipment, etc.	"
25248	" " " " " Progress dismantling Unit #8	3-2-43
25249	" " " " " " " "	3-9-43
25250	" " " " " Typical chunks of concrete removed from #8 foundation	3-10-43
25251	" " " " " Unit 8 - Low pressure housing - Typical marking	3-11-43
25252	Huntz Lake Dam #1 - Reinforcing steel East 42" sluice pipe	7-5-37
25253	" " " " " Forms, upper part of main envelope	"



266

## Small films

25255	Huntg. Lake Dam #1 - Pouring concrete in top sec. of 42" sluice pipe envelope.	7-7-37
25256	" " " " Progress picture - Backfill	7-11-37
25257	" " " " " " " "	"
25258	" " " " 2 <sup>nd</sup> view of dozing earth from fill	"
25259	" " " " Excavating for cut-off wall outlet end of 42" sluice valve ext.	"
25260	" " " " Initial backfill around concrete envelope " pipe "	"
25261	" " " " View of dozing earth from fill East side for backfill.	"
25262	" " " " " Backfilling operations 42" sluice pipe ext.	7-13-37
25263	" " " " " Excavating for cut-off wall, below 42" sluice valves	"
25264	" " " " View of backfilling around conc. envelope	"
25265	" " " " Excavating for cut-off wall 42" sluice valve extension	7-14-37
25266	" " " " Pouring lower part of cut-off wall 42" sluice valve "	7-15-37
25265	" " " " Excavating for cut-off wall 42" sluice valve extension	7-14-37
25266	" " " " Pouring lower part of cut-off wall 42" sluice valve "	7-15-37
25267	" " " " View of forms for concrete valve structure 42" valve ext.	7-17-37
25268	" " " " View of completed concrete structure " " "	7-20-37
25269	" " " " View of face of cut for Aux. spillway, etc.	7-21-37
25270	" " " " Excavating for upper butterfly valve house 84" flow line.	7-24-37
25271	" " " " " " " " " " " "	"
25272	" " " " Progress picture of Backfill	7-26-37
25273	" " " " " " " " " " " "	"
25274	" " " " " Dam #1 Backfill	"
25275	" " " " " of Backfill	8-1-37
25276	" " " " Backfill, barricade around 42" sluice valves	"
25277	" " " " Progress picture of backfill	"
25278	" " " " " " " " " " " "	8-3-37
25279	" " " " " " " " " " " "	8-13-37
25280	" " " " " " " " " " " Elev. of fill 6850, etc.	"

267

## Small films

25282	Huntg. Lake #1 Dam - Taking earth sample for density test.	8-15-37
25283	" " " " " " " " " " " "	"
25284	" " " " Progress picture of Backfill	"
25285	" " " " Backfill - west side of Dam	"
25286	" " " " Clearing along Aux. spillway, from So. End	"
25287	" " " " West section Aux. " " No. "	8-20-37
25288	" " " " East center Aux. spillway taken from No. End	"
25289	" " " " West center section Aux. Spillway " " "	"
25290	" " " " Progress picture of backfill. Above 6850	"
25291	" " " " East end Aux. Spillway, taken from North.	"
25292	" " " " Progress picture of excavation East end of Aux. spillway	"
25293	" " " " East end Aux. Spillway, taken from North.	"
25292	" " " " Progress picture of excavation East end of Aux. spillway	"
25293	" " " " Looking down on East siphon prior to clearing	8-23-37
25294	" " " " Backfill showing lift containing considerable rock.	8-30-37
25295	" " " " " Another view of lift showing rock imbedded in fill.	"
25296	" " " " Aux. spillway excavation Progress picture	9-1-37
25297	" " " " Backfill, from west end of Dam	9-8-37
25298	" " " " Aux. spillway. Drilling 10' lift in main channel.	"
25299	" " " " " View from South end.	"
25300	" " " " Excavating for siphon training	9-15-37

25301	Htg. Lake Dam #1 - Backfill, from East end, showing progress	9-16-37
25302	" " " " Progress picture, taken from West end	9-19-37
25303	" " " " Excavation for siphon training wall.	"
25304	" " " " Progress picture East side Aux spillway	9-22-37
25305	" " " " " West " " "	"
25306	" " " " Backfill - Progress picture	"
25307	" " " " Finished excavation for counterfort section of siphon.	"
25308	" " " " Cold weather concrete - Aux. spillway	10-1-37
25309	" " " " Forms for counterfort & cantilever sections	"
25310	" " " " Starting construction of spillway lip.	"
25311	" " " " Constr. progress, Aux. spillway forms & staging	11-1-37
25312	" " " " Pouring sections of concrete - Aux. spillway	"
25311	" " " " Constr. progress, Aux. spillway forms & staging	11-1-37
25312	" " " " Pouring sections of concrete - Aux. spillway	"
25313	" " " " Excavating East end of Aux. spillway	"
25314	" " " " Pouring a section of concrete Aux. spillway	"
25315	" " " " Progress picture - pouring a section of spillway	"
25316	" " " " Starting pour of concrete in section of Aux. spillway	"
25317	" " " " Finishing sections of concrete Aux. spillway	"
25318	" " " " Progress picture Aux. spillway, cut & staging	"
25319	" " " " Finishing top of a section of concrete Aux. spillway	"
25320	" " " " General construction view while building Aux. spillway	"
25321	" " " " Removing old construction trestle upstream face of dam	"
25322	" " " " Pouring first concrete	"
25323	" " " " Progress picture constr. Aux. spillway	"
25324	" " " " Aux. cut excavation.	"
25325	" " " " Progress picture - Constr. Aux. spillway	"
25326	" " " " Aux. spillway concrete	12-1-37

25328	Htg. Lake Dam #1 - Aux. spillway from downstream East end.	1-4-38
25329	" " " " Steam heated aggregate pile etc.	1-4-38
25330	" " " " Downstream side of Aux. spillway	1-11-38
25331	" " " #2 Reinf for duplex Gate House	8-20-37
25332	" " " " " " " " Pouring concrete	8-27-37
25333	" " " " " " " " Pouring concrete 10' dia. pipe encasement	"
25334	" " " " Reinf. Duplex Gate House	8-28-37
25335	" " " " " " " " Starting pour concrete	9-1-37
25336	" " " " " " " " Placing exterior forms	9-5-37
25337	" " " " " " " " Concrete floor slab	9-8-37
25338	" " " " " " " " Pouring walls & roof	9-13-37
25339	" " " " " " " " Repairing foot near	4-8-37
25338	" " " " " " " " Pouring walls & roof	9-13-37
25339	" " " " " " " " Pouring concrete	"
25340	" " " " " " " " Excavation at West end of Dam 2	Dec. 1937
25341	" " " " " " " " Reinforcing Duplex Gate House	9-14-37
25342	" " " " " " " " View of excavation West End of Dam 2	"
25343	" " " " " " " " " " " "	"
25344	" " " " " " " " Showing damage done to backfill	"
25345	" " " " " " " " View of backfill after heavy storm	"
25346	" " " " " " " " View of typical vertical crack	1-1-38
25347	" " " " " " " " Close view of Potrolastic repaired crack	1-11-38
25348	" " " #3 Hand excavation upstream toe of Dam North End.	Oct. 1937
25349	" " " " " " " " " " " "	"
25350	" " " " " " " " Maximum excavation upstream toe Dam 3	"
25351	" " " " " " " " Excavation below the 6880 level upstream toe	"
25352	" " " " " " " " Repairs to Upstream face. Grouting spalled Area.	Nov. 1937
25353	" " " " " " " " View taken while grouting Upstream toe	1-13-38



25355	1 <sup>4</sup> g. Lake Dam #3 - Taken while grouting hole upstream Tol.	1-13-38
25356	" " " Typical vertical Crack (Sta 1+95)	"
25357	Florence Lake Dam Arch #2 covered with gunite, linseed oil, etc	3-3-43
25358	" " " #1 P.H. 2	3-29-43
25359	Tunnel 3 Outlet plug B.C. 3, spalling on gallery wall	"
25360	" " " " gallery roof	"
25361	Huntington Lake Dam #3	3-30-43
+ 25362	Sno-Motor approaching Kaiser Pass	"
25363	Test bars on angle buttress #25 Florence Lake Dam	"
25364	Sno-motor at the foot of the "Ladder"	"
25365	Florence Lake Dam, Downstream face Arch 53	"
25366	" " Reservoir Experimental concrete fans	"
25365	Florence Lake Dam, Downstream face Arch 53	"
25366	" " Reservoir Experimental concrete fans	"
25367	" " Crib dam - Test bars on upstream face	"
25368	" " Dam - Typical scoring of Asbestide by snow loads	"
25369	" " " Arch 52, stalactites & icicles on downstream face	"
25370	" " " " " "	"
25371	" " " Arch haunch, etc	"
25372	" " " Arch #51, icicles on downstream face	"
25373	" " " Walkway at Arch #39, etc.	"
25374	West Side Project Mt. Ritter and the "west side"	4-1-43
25375	Mt. Hooper & Camp 61	"
25376	Long Beach St. Pl. - Unloading 8-R Condenser shell.	3-21-43
25377	" " " 1 <sup>st</sup> section of 8-R " "	"
25378	" " " " Moving House Generator	3-16-43
25379	Long Beach St. Pl. Moving House Generator	3-16-43
25380	" " " Unit #8 Stator created for shipment.	Apr. 1943

25382	Long Beach St. Pl. - Unit 8-R. Progress	3-31-43
25383	Long Beach St. Pl. Moving house generator	3-16-43
25384	" " Unloading 8-R Condenser shell.	3-21-43
25385	" " Balancing #8 Rotor	3-23-43
25386	Long Beach St. Pl. Unit #8 first stage wheel showing weights after balancing	3-23-43
25387	" " " " Welding 8-R Condenser	4-14-43
25388	" " " " Machine shroud bands #7 Turbo	4-15-43
25389	" " " " 8-R Condenser. Progress Constructing	4-14-43
25390	" " " " " Typical circumference weld.	"
25391	" " " " Machining shroud bands #7 Turbine	4-15-43
25392	" " " " " " " "	"
25393	Long Beach St. Pl. Forming shroud bands #8 Turbine	4-15-43
25392	" " " " " " " "	"
25393	Long Beach St. Pl. Forms & steel east footing 8-R	4-23-43
25394	Long Beach St. Pl. Unit 8-R Removal of Unit #7	4-27-43
25395	" " " " " Progress construction	4-27-43
25396	" " " " " Progress construction of Unit 8-R	5-23-43
25397	" " " " " " " "	5-11-43
25398	" " " " Removing coupling and 20 <sup>th</sup> stage wheel from #7 tur.	5-11-43
25399	" " " " Units 7 & 8 Removal -	5-14-43
25400	" " " " " " " "	"

272

25401	Long Beach S. Pl. Units 7 & 8 - Removal - Storage yard.	5-14-43
25402	" " " " " " "	"
25403	" " " " " " Storage area NW of Unit #10 Pl. #3	"
25404	" " " " " " " repair area	"
25405	" " " " " " " area	5-4-43
25406	" " " " " " Crating #7 in area N.W. of Unit 11	5-14-43
25407	" " " " " " Storage area S.W. of Unit #11	"
25408	" " " " " " Storage & cleaning area	"
25409	L.B. St. Pl. No 2 - Progress construction of 8-R	4-5-43
25410	" " " " " " " "	4-13-43
25411	" " " " " " " "	4-20-43
25412	" " " " " " Forms & steel East footing 8-R	4-23-43
25411	" " " " " " " "	4-20-43
25412	" " " " " " Forms & steel East footing 8-R	4-23-43
25413	" " " " " " " 8-R	"
25414	" " " " " " Progress Construction of Unit 8-R	5-17-43
25415	Vincent Transm. Line - Cummings Patrol Sta.	June 1932
25416	" " " " " " " "	"
25417	" " " " " " " "	"
25418	Long Beach St. Pl. - Holes cut in concrete to remove material sent to Russia	5-28-43
25419	" " " " " " Typical cement dust coating on Pl. #2 equip.	"
25420	" " " " " " Cracked flange on 11 <sup>th</sup> stage heater	"
25421	" " " " " " Cramped operating space around Unit 9	"
25422	" " " " " " Progress - construction 8-R	5-31-43
25423	" " " " " " Unit #7 foundation	5-28-43
25424	" " " " " " Placing levelling pads & sole plates for 8-R	6-2-43
25425	" " " " " " #7 Tube sheet, typical of worst corroded section.	6-3-43
25426	" " " " " " #7 Tube sheet showing point of maximum corrosion	"

Small Filtrus

273

25428	Long Beach S.P. Cleaning & repair area for Units #7 & #8	6-7
25429	" " " " " " Preparing foundation for #9 West circ. water pump	"
25430	" " " " " " Progress Construction of Unit 8-R	"
25431	" " " " " " Installing evaporator & condensate booster pumps for Unit 8-R	"
25432	" " " " " " 8-R Condenser shell & half of return water box	"
25433	K.R. #3 Dump - facing due East. Facing the old "drive-in" entrance & signs	6-7
25434	" " " " " " South Taken from higher ground	"
25435	" " " " " " Northwest. Back of signs is about center	"
25436	K.R. No. 3. Fish Hatchery fire	6-6-4
25437	" " " " " " " "	"
25438	" " " " " " " "	"
25439	" " " " " " " "	"
25438	" " " " " " " "	"
25439	" " " " " " " "	"
25440	" " " " " " " "	"
25441	Long Beach St. Pl. No. 2, Unit 8 R Condensate booster pumps 7-7	
25442	" " " " " " " " " "	"
25443	" " " " " " " " Hot well & condenser shell	"
25444	" " " " " " " " Assembly low pressure shell	"
25445	" " " " " " " " Generator sole plates & L.P. end of Turbine	"
25446	" " " " " " " " Progress construction	"
25447	" " " " " " " " " "	"
25448	" " " " " " " " { Placing return water box Unit 8 R Condenser, prior to rolling condenser shell into position	6-9-4
25449	" " " " " " " " { leveling pads for generator sole plates	"
25450	" " " " " " " " { Congestion in condenser floor aisle as a result of 8 R construction	7-10
25451	" " " " " " " " { Congestion around base of #7 as a result of removal of #7 & #8 and the construction of 8 R	"
25452	" " " " " " " " { Congestion around Unit #9 as a result of 8 R construction	"
25453	" " " " " " " " { Congestion around base of #7 as a result of removal of #7 & #8 and the construction of 8 R	"



74

## Small Films

25455	Long Beach S. P. Unit 8R	Typical conduit bends & supports	7-10-43
25456	" " " "	Trenches in floor under condensers	"
25457	" " " "	assembling high pressure end Unit 8R	"
25458	Poles damaged by woodpeckers (miscel. distr. lines)		5-20-43
25459	" " " "	"	"
25460	" " " "	"	"
25461	Caisson installations - Colton-Pedley & W. San Berdo Colton		1943
25462	" " " "	"	"
25463	" " " "	"	"
25464	" " " "	"	"
25465	" " " "	"	"
25464	" " " "	"	"
25465	" " " "	"	"
25466	" " " "	"	"
25467	" " " "	"	"
25468	" " Colton-Pedley & W. San Berdo-Riverside		1943
25469	" " " "	"	"
25470	" " " "	"	"
25471	" " " "	"	"
25472	" " E & W Colton-Cardiff 66 K.V. & E. Colton-San Berdo		"
25473	" " " "	"	"
25474	" " " "	"	"
25475	Big Creek #3 - Straightening shaft of Unit #3 Generator		Jan. 1930
25476	" " " "	"	"
25477	B.C. 2-2A P.H. Installing O.B. bushings, B.C. 2-2A line 220 K.V. oil cir. breaker.		4-23-43
25478	" " " "	"	"
25479	" " " "	"	"
25480	" " " "	"	"

275

## Small Films

25482	B.C. 2-2A P.H. Showing complete bushing handling rig.		4-23-43
25483	Long Beach S.P. - Unit 8-R Aux. Power transformers		7-10-43
25484	Kaweah, Mis. Franklin dam showing stone masonry upstream face		8-4-43
25485	" " " " No. end including spillway		"
25486	" " " " Spillway		"
25487	" " " " Detail of masonry joints		"
25488	" " " " Showing leakage at maximum section		"
25489	" " " " North end.		"
25490	" " Crystal Dam - from across Mineral King Canyon		"
25491	" " Eagle Lake		"
25492	" " Eagle Lake sluice gate stem.		"
25491	" " Eagle Lake		"
25492	" " Eagle Lake sluice gate stem.		"
25493	" " " " Dam & spillway		"
25494	" " Crystal Dam		8-5-43
25495	" " " " showing leakage		"
25496	" " Eagle Lake drainage from Crystal Lake trail.		"
25497	" " Mineral King, looking South		"
25498	" " Monarch Dam from lower Monarch Lake		"
25499	" " Lower Monarch Lake		"
25500	" " Monarch Lake		"

276

## Small Films

25501	Kaweah Miscel. - Monarch Dam, showing leakage	8-5-43
25502	" " Upper Monarch Dam	"
25503	K.R. #3 Public Dump - Same as photo #25433,	8-26-43
25504	" " " " Where fire originated in 1942.	"
25505	" " " " Looking East.	"
25506	Miscel. Non-Edison Prop. - L.A. Aqueduct, Showing condition of concrete	8-16-43
25507	" " " " " " Repair of concrete	"
25508	" " " " " " Cracking on concrete	"
25509	" " " " Grant Lake	8-17-43
25510	" " " " East Walker River Dam	"
25511	" " " " Siphon spillway	"
25512	" " " " Poole power house and penstock	"
25513	" " " " Tioga South Dam	"
25514	" " " " " " " " and penstock	"
25513	" " " " Tioga South Dam	"
25514	" " " " North Dam	"
25515	" " " " Saddlebag Dam & spillway	"
25516	" " " " " " reservoir	"
25517	" " " " " " Dam, looking South	"
25518	" " " " " " Detail of timber face	"
25519	" " " " Rhinedollar dam	"
25520	" " " " Lundy Reservoir	"
25521	" " " " Lundy Dam & spillway	"
25522	" " " " Downstream face of Grant Lake Dam	"
25523	" " " " Sierras from Lake Crowley	8-18-43
25524	" " " " " " (Long Valley)	"
25525	" " " " Long Valley Dam & No. Abutment	"
25526	" " " " " " Downstream face	"
25527	" " " " Rush Meadows Dam	"

277

## Small Films

25528	Miscel. Non-Edison Prop. - Rush Meadows Res. (Cough Lake)	8-18-43
25529	" " " " Detail - Rush Meadows Dam	"
25530	" " " " Spillway - Rush Meadows dam.	"
25531	" " " " Rush Meadows dam	"
25532	" " " " Gem Dam - downstream face	"
25533	" " " " " " Fresh asphalt emulsion on U.S. face	"
25534	" " " " " " downstream face	"
25535	" " " " " " Butress	"
25536	" " " " " " downstream face at Arch, near South end.	"
25537	" " " " " " Gem Lake	"
25538	" " " " " " Agnew Reservoir and dam	"
25539	" " " " " " Gem Dam - aggregate pit	"
25540	" " " " " " Agnew Dam. This season's repair completed.	"
25539	" " " " " " Gem Dam - aggregate pit	"
25540	" " " " " " Agnew Dam. This season's repair completed.	"
25541	" " " " " " South Lake (Hillside) dam on Bishop Creek.	8-19-43
25542	Florence Lake Dam - Wood float, finishing Arch 26 slabs.	9-6-43
25543	K.R. #3 Public Dump -	9-1-43
25544	" " " " " " Taken from higher ground	"
25545	S.A.R. #5 - Replacing upper 180 ft. section of 40" steel penstock	"
25546	" " " " " " " " " "	"
25547	" " " " " " " " " "	"
25548	" " " " " " " " " "	"
25549	K.R. #1 Dump	9-1-43
25550	Long Beach St. Pl. - Progress construction, Unit 8R	9-3-43
25551	" " " " " " 8-R Condenser - South End	"
25552	" " " " " " Condensate Cooler - Tube sheet sprayed with zinc.	"
25553	" " " " " " Entering 8R Generator field	"
25554	No title " Top view placing 8R Generator field	"







280

25601	Kern River #3 Canal - Special metering structure	5-1-43
25602	" " " " " " " " " " " "	"
25603	K.R. No. 3 Conduit - Salmon Cr. Inlake	"
25604	Kaweah Miscel. - Franklyn Dam & Lake	8-4-43
25605	" " " " " " " " " " " "	"
25606	" " " " " " " " " " " "	"
25607	" " " " " " " " " " " "	"
25608	" " " " " " " " " " " "	"
25609	" " " " " " " " " " " "	"
25610	" " " " " " " " " " " "	"
25611	" " " " " " " " " " " "	"
25612	" " " " " " " " " " " "	8-5-43
25613	" " " " " " " " " " " "	"
25612	" " " " " " " " " " " "	8-5-43
25613	" " " " " " " " " " " "	"
25614	" " " " " " " " " " " "	"
25615	" " " " " " " " " " " "	"
25616	" " " " " " " " " " " "	"
25617	" " " " " " " " " " " "	"
25618	" " " " " " " " " " " "	"
25619	" " " " " " " " " " " "	"
25620	" " " " " " " " " " " "	"
25621	K.R. #3 <del>Sandbox</del> <u>Corral Creek Flume</u> (Mr. Chas. L. ...)	8-24-43
25622	" " " " " " " " " " " "	"
25623	" " " " " " " " " " " "	"
25624	" " " " " " " " " " " "	"
25625	" " " " " " " " " " " "	8-24-43
25626	" " " " " " " " " " " "	"
25627	" " " " " " " " " " " "	"

281

25628	K.R. #3 <del>Sandbox</del> <u>Corral Creek flume</u> <del>Used in report on sand deposit</del> <u>Footings 2E</u>	8-24-43
25629	" " " " " " " " " " " "	"
25630	" " " " " " " " " " " "	"
25631	" " " " " " " " " " " "	"
25632	" " " " " " " " " " " "	"
25633	" " " " " " " " " " " "	"
25634	" " " " " " " " " " " "	"
25635	" " " " " " " " " " " "	"
25636	" " " " " " " " " " " "	"
25637	" " " " " " " " " " " "	"
25638	" " " " " " " " " " " "	"
25639	" " " " " " " " " " " "	"
25638	" " " " " " " " " " " "	"
25639	" " " " " " " " " " " "	"
25640	" " " " " " " " " " " "	"
25641	" " " " " " " " " " " "	"
25642	" " " " " " " " " " " "	"
25643	" " " " " " " " " " " "	"
25644	Big Creek #3-Unit #2 View of completed Class B winding,	11-25-43
25645	" " " " " " " " " " " "	"
25646	" " " " " " " " " " " "	"
25647	" " " " " " " " " " " "	"
25648	" " " " " " " " " " " "	"
25649	" " " " " " " " " " " "	"
25650	" " " " " " " " " " " "	"
25651	" " " " " " " " " " " "	"
25652	" " " " " " " " " " " "	"
25653	" " " " " " " " " " " "	"
25654	Miscel. Distribution - Malibu Falls	Jan 1943



25655	Miscel. Distribution - Malibu Fire	Nov. 1943
25656	" " "	"
25657	" " "	"
25658	" " "	"
25659	" " "	"
25660	" " "	"
25661	" " "	"
25662	L.B. 8R Condensers	12-9-43
25663	" " "	"
25664	" " "	"
25665	" " "	"
25666	" " "	"
25667	Long Beach S.P. Unit 8-R Platform around east circu. water valve	12-5-43
25668	" " "	"
25667	Long Beach S.P. Unit 8-R Platform around east circu. water valve	12-5-43
25668	" " " Completed except for painting	"
25669	Kern River #3 Penstock #1 View inside <sup>pipe at</sup> manhole about half way up	11-16-43
25670	Kern River #3 Carral Creek flume footing showing typical "Parkeritis"	11-16-43
25671	Kern River #3 " " " " " "	"
25672	L.B.S.P. #3 Boiler #52 superheater tubes after removal <sup>showing typical warping</sup> and overlapping of tubes	12-13-43
25673	" " " " after straightening	12-13-43
25674	" " " " superheater tubes after removal <sup>showing</sup> typical warping and overlapping of tubes	12-13-43
25675	" " View from N.E. corner showing warped superheater tubes and brick supporting wall shoved out of line by warping tubes	12-13-43
25676	" " View from N.E. corner showing warped superheater tubes and brick supporting wall	12-17-43
25677	" " Sagged superheater tubes looking East from near the center of the N. end of boiler	12-13-43
25678	" " View of N. end showing warped superheater tubes behind front boiler header	12-13-43
25679	Big Creek #3 - New Cole 220K.V. Discorn. switch	10-11-43
25680	" " Close up of transfer bus	"
25681	" " " " " "	"

25682	Big Creek #3 - New Cole 220K.V. Discorn. switches to Lower Bus	10-11-43
25683	" " 220K.V. Transfer Bus	"
25684	K.R. 3, Interior of Penstock #2	11-16-43
25685	Ward Tunnel Sta. 109+50 (Florence Lake)	12-15-43
25686	Florence Lake Dam River section	12-16-43
25687	Florence Lake - Old Crit diversion dam	"
25688	L.B.S.P. #3 - Boiler #52 - straightening separator tubes	12-13-43
25689	Big Creek general - Colby meadow Snow Course looking East	9-25-43
25690	" " " " " West	"
25691	" " " " " East from West	"
25692	" " Mc Clure Meadows Cabin	"
25693	" " " " Camp	"
25694	" " " " Cabin	"
25693	" " " " Camp	"
25694	" " " " Cabin	"
25695	" " Redinger fishing in Evolution Creek	"
25696	" " Mc Clure Meadows Creek	9-26-43
25697	" " " " Camp	"
25698	" " Close up of Crew	"
25699	" " " " Popeney, Mc Millan, Bush	"
25700	" " Evolution Meadow	"



284

25728	Huntington Shower Tunnel: Repairs, Start of Kuniting.	11-28-46
25729	" " " " - Kuniting/bicircular section.	12-20-44
25730	" " " " - Lement Ken & Miller.	12-20-44
25731	" " " " Newwin Camp 72 Adit.	11-28-44
25732	" " " " " of setup for drying sand.	12-8-44
25733	" " " " Adit at camp 72 & Outlet.	1-7-45
25734	Big Creek #3 - View of lathe Set-up	12-14-44
25735	Big Creek #3: Unit #3, Completion of lowering rotor on horizontal position.	12-14-44
25736	" " " " Starting to place rotor in horizontal position.	12-14-44
25737	" " " " Placing rotor after field poles removed.	12-14-44
25738	" " " " Horizontal view of rotor.	12-15-44
25739	" " " " View showing distortion of dovetail-- rotor.	12-15-44
25739	" " " " Horizontal view of rotor.	12-15-44
25739	" " " " View showing distortion of dovetail-- rotor.	12-15-44
25740	" " " " Distorted spider plate (Photograph 25739)	12-15-44
25741	" " " " View of rotor pole.	12-15-44
25742	" " " " View showing distortion of lamination.	12-15-44
25743	" " " " Close-up of rotor.	12-15-44
25744	" " " " of distorted field pole laminations.	1-16-45
25745	A B C " " " Two views method straightening laminations.	1-16-45 1-28-45
25746	A B " " " Two views milling machine set up P.H. #2.	1-16-45
25747	A B C " " " Three views Rotor set-up.	1-16-45
25748	A B C E F G H " " " Seven Views - Hydraulic Press.	1-28-45 2-4-45 2-12-45
25749	A B C " " " Three views Planer & Tool Assembly.	2-21-45
25750	" " " " Rigging for turning field pole after coil assembly.	3-4-45
25751	" " " " Re-assembled field pole & welded re-inforcement of dovetail.	3-4-45
25752	A B C " " " Beam used for balancing opposite poles on rotor.	3-4-45
25753	A B " " " Two views sig with field poles.	3-4-45
25754	" " " " " " " "	3-4-45



286

Reserved for Barker at Big Creek

(See index)  
Cards

25755	A	Big Creek #3: Unit #3, Rotor in Vertical Position	3-6-45
25756	"	" " " " Tool Mark in Lining of Pelton Valve	1-28-45
25757	"	Mono. Bear Diversion - Bear Cr. Reservoir Showing Sand Conditions	10-17-44
25758	"	" " " " Bear Tunnel Intake - Trash Rack After Cleaning	10-17-44
25759	"	" " " " Bear Dam - Condition of Sluice Gate Trash Rack	"
25760	"	Florence Lake Dam: View of Arch #9 after chipping, preparatory	3-25-44
25761	"	" " " " Repairs to Arch #8, May 1940	"
25762	"	" " " " Progress picture, applying waterproofing	4-6-44
25763	"	" " " " Removal of old granite Lower portion Arch No. 20	4-6-44
25764	"	" " " " Close-up of typical surface obtained by	4-18-44
25765	"	" " " " " " " " typical surface on sound areas	"
25766	"	" " " " View of chipped surface of Arch No. 19	"
25767	A	" " " " Repairs to Arch #54 + #52 (spot repairs)	5-4-44
25766	B	" " " " View of chipped surface of Arch No. 19	"
25767	A	" " " " Repairs to Arch #54 + #52 (spot repairs)	5-4-44
25768	B	" " " " Close-ups after chipping on Arch #28	5-11-44
25769	"	" " " " Progress picture. Chipping crew working	5-11-44
25770	"	" " " " Surface Arch #28 after smoothing with granite	5-13-44
25771	"	" " " " Spot repairs on Arches 52, 54 + #55	5-24-44
25772	"	" " " " Fourth Tangent, Arches #37 to #49, incl.	"
25773	"	" " " " Third " " #26 to #36	6-1-44
25774	"	" " " " Second " " #15 to #25	"
25775	"	" " " " Arches #1, #2 and West part of Arch #3, Waterproofing	"
25776	"	" " " " Arch #33 - present condition extrados surface	5-3-44
25777	A	" " " " Spillway concrete repair	9-10-44
25778	B	" " " " Progress picture. Application Matthews Cementine	"
25779	A	" " " " Two views - Spillway concrete repair	9-20-44
25780	B	" " " " Progress picture - " " "	9-24-44
25781	"	" " " " " Drops and Arches" after application	10-24-44
		Matthews Cementine reflecting Coat.	

287

Reserved for Barker at Big Creek (10-18-43)

(See index)  
Cards

25782	"	Florence Lake Dam: Spillway Concrete Repairs	11-16-44
25783	"	" " " " River section arches at close of 1944	"
25784	"	" " " " 3rd & 4th Tangent Arches after snowstorm	11-14-44
25785	"	Huntington-Shaver Tunnel: S & W repairs - Pressure grouting	10-13, 1944
25786	"	" " " " " " - Grouting set-up	1-7-45
25787	"	" " " " " " - Adit #1 North	1-19-45
25788	"	" " " " " " - Adit at Camp 72	1-18-45
25789	"	" " " " " " - Adit at Camp 72	1-18-45
25790	"	" " " " " " - Rocks in Floor N. of Adit At Camp 72	1-22-45
25791	"	Florence Lake Dam - Intrados of Arch #12 Taken During Inspection	7-28-44
25792	"	" " " " " " " " #54	7-28-44
25793	"	Big Creek Gen'l - Crater Creek Diversion - In Respect To Florence	4-14-44
25794	"	" " " " " " " " - Removing Snow From 12" Pipeline	5-11-44
25793	"	Big Creek Gen'l - Crater Creek Diversion - In Respect To Florence	4-14-44
25794	"	" " " " " " " " - Removing Snow From 12" Pipeline	5-11-44
25795	"	" " " " " " " " - Intake of Old Diversion	5-12-44
25796	"	" " " " " " " " - Solid Rock Ledge	5-14-44
25797	A	" " " " " " " " - Hand Drilling For Shooting	5-14-44
25798	B	" " " " " " " " - Progress Boulder Excavation	5-16-44
25799	A	" " " " " " " " - Excavation Along Ditch	5-17-44
25799	B	" " " " " " " " - Ditch After Spring Work	6-3-44
25800	"	" " " " " " " " - View of Crater Lake	6-4-44

288

For Small Films

25801	Big Creek General-Pavilion Dome	9-26-43
25802	Bar Co. High Lakes Muir Trail Cabin	"
25803	Big Co. General Sally Keyes Lake	9-27-43
25804	" " " " " "	"
25805	Bar Co. High Lakes Heart Lake Snow Course, looking North	"
25806	" " " " " " South	"
25807	" " " " " " N.E. ly.	"
25808	Big Co. General Blaney Meadow " N.W.	"
25809	" " " " " " S.E.	"
25810	" " Nellie Lake North-South Snow Course	9-27-43
25811	" " " " " "	"
25812	" " " " East-West " "	"
25813	" " " " " " " "	"
25812	" " " " East-West " "	"
25813	" " " " " " " "	"
25814	" " Shaver Lake showing early morning vapor	9-30-43
25815	" " Camp 73 Cabin	"
25816	Santa Ana Canyon Bridge bet. S.A.R. #3 & #2	12-7-43
25817	" " " " " "	"
25818	Kern River Tower on Ridge Route	12-14-43
25819	Long Beach St. Pl. Upper unit 8R Condenser tube sheet	1-11-44
25820	" " " NW <sup>4</sup> of Unit 8R " "	"
25821	" " " Lower SW <sup>4</sup> of Unit 8R " "	"
25822	" " " Upper SW <sup>4</sup> " " " "	"
25823	Long Beach St. Pl. No. 2 Unit 8R Condenser.	1-11-44
25824	" " " South end of Unit 8R Condenser	"
25825	" " " " Boiler No. 35.	"
25826	" " " " " " Re-bricked front wall.	"
25827	Big Creek Trans. lines. Storm damage	12-10-43

289

25828	Big Creek Trans. lines. Towers damaged in snow storm	12-10-43
25829	" " " " " "	"
25830	" " " " " "	"
25831	" " " " " "	"
25832	" " " " " "	"
25833	K.R. #3 Pl. Unit #1 Generator Shaft repair	Dec. 1943
25834	" " " " " "	"
25835	" " " " " "	"
25836	" " " " " "	"
25837	" " " " " "	"
25838	" " " " " "	"
25839	" " " " " "	"
25840	" " " " " "	"
25841	Borel Hydro P.N. Break in canal at Schoolhouse cut	12-21-43
25842	" " " " " "	"
25843	Kern-Saugus 66 K.V. H. frame storm damage.	12-10-43
25844	" " " Mile 53 towers - storm damage	"
25845	Magunden-Saugus 220 K.V. Mile 183 Tower 1, storm damage	"
25846	Kern-Saugus 66 K.V. Mile 53, Tower 7	"
25847	" " " " " " " "	"
25848	" " " " " " " 5	"
25849	" " " " " " " Line following storm of 12-10-43	"
25850	" " " " " " " "	"
25851	" " " " " " " "	"
25852	" " " " " " " "	"
25853	" " " " " " " "	"
25854	" " " " " " " "	"



25855	Sno Motor (Copy of print taken by outsiders) mounted	2-24-44
25856	S. J. River below Kerckhoff Gage Ht. 6.75	12-6-42
25857	" " " " " 6.75	"
25858	" " " " " Gage Ht. 6.75 showing low water control	"
25859	" " " " " Guy cables not yet installed	"
25860	" " " " " "	"
25861	" " " " " Showing boulder downstream	"
25862	Borel Canal Break in Canal Lining	3-6-44
25863	" " Cabin Below Break in Canal	"
25864	" " Back View of Cabin. No flood damage shown	3-6-44
25865	" " Close up of Break which occurred 3-5-44	3-6-44
25866	" " Cabin site, showing Flood Channel Cut.	"
25867	" " Close up of Break which occurred 3-5-44	3-6-44
25868	Borel - Showing Cabin Site, showing Flood Channel Cut.	"
25867	" " Close up of Break which occurred 3-5-44	3-6-44
25868	Borel - Showing R-5 Bulldozer & 30" Cat spreading dirt	3-8-44
25869	" " Showing break in Canal, etc.	"
25870	" " " " " "	"
25871	" " The "30" Cat about to make Track in Canal.	3-8-44
25872	" " Upstream view Thru Cut Below K.R. Flume.	"
25873	" " " " of Canal above Highway crossing	"
25874	" " " " " of Bad Section	"
25875	Borel - The small "22" Cat Bull-Dozing Sand, etc.	3-8-44
25876	" " Repairing Canal Berm	3-17-44
25877	" " Upstream view of repaired section	"
25878	Borel - Laying gunite Re-inforcing	3-17-44
25879	Borel - Reinforcing & Terracing Upper Bank	3-17-44
25880		
25881		

25882	Borel - Shows Excavation of mountainside for Berm Fill	3-17-44
25883	" " Upstream Close-up of Canal Break	3-8-44
25884	Borel - Jamming Downstream Berm	3-17-44
25885	" " Gunite gun & Concrete mixer	"
25886	" " Canal Cleared - Jamming Berm, etc.	"
25887	Borel - Guniting Rebuilt Section	3-17-44
25888	Borel Canal Break bet. Tunnel 1 & 2	3-6-44
25889	" " " " " " "	"
25890	Borel - Near Sta. 97+58.0 Looking West	3-11-44
25891	" " " " 525+95 near Tunnel #1	"
25892	Borel Canal - near Tilley Flume #3	3-11-44
25893	Borel Canal Break - near Tilley Flume #1	3-11-44
25894	" " " " Building up new Berm at Break	3-11-44
25893	Borel Canal Break - near Tilley Flume #1	3-11-44
25894	" " " " Building up new Berm at Break	"
25895	Borel Canal - near Sta. 234+50.5	3-11-44
25896	" " " " 238+33.9	"
25897	" " " " 290+07.5	"
25898	" " " " 593+84 near Tunnel #2	"
25899	Borel Canal - near Tilley Flume #2	3-11-44
25900	Big Creek 220 K.V. line - storm of 2-21-44	2-21-44



25901	Laguna Bell-Puente Trans.-Storm of 2-21-44	2-21-44
25902	Puente-Chino 66 K.V. line	"
25903	Big Creek 220 K.V. Lines	"
25904	Santa Clara River Crossing Saticoy-Colonia 66 K.V. line	"
25905	Big Creek 220 K.V. line, storm damage	"
25906	Big Creek Transm. Line	3-8-44
25907	Big Creek Transm. Line	"
25908	Storm Damage (Mr. Osborne) Saticoy Bridge	3-9-44
25909	" " " Santa Clara River Bed. (Storm 2-20)	"
25910	" " " Showing cut of S.P.R.R.	"
25911	" " " Highway Bridge No. of Saugus	"
25912	" " " So. Side of Soledad Bridge	"
25913	Big Creek 220 K.V. Lines, Storm damage	2-21-44
25914	" " " So. Side of Soledad Bridge	"
25913	Big Creek 220 K.V. Lines, Storm damage	2-21-44
25914	" " " " " "	"
25915	Santa Clara River Bridge - Storm of 2-21-44	"
25916	" " " near Saticoy - Storm	"
25917	" " " crossing near Saticoy	"
25918	" " " " " "	"
25919	Long Beach St. Pl. No. 2, Unit 8 R. S. H. Element with top & bottom legs off	2-8-44
25920	" " " S. H. Element coming out of descaling tank	"
25921	" " " " " as removed from boiler	"
25922	" " " " " When straightening is finished	2-8-44
25923	" " " " " Going into boiler	"
25924	" " " " " on forming jig	"
25925	" " " " " Straightening tool	"
25926	" " " " " S. H. Element as it is tested	"
25927	" " " " " going into Boiler	"

## Small films

25928	Long Beach St. Pl. #2 Unit 8 R - S. H. Element as legs welded on	2-9-44
25929	" " " " " " as straps are welded on	"
25930	Borel Canal Break - Completing concrete work.	3-11-44
25931	Borel Canal Break - Near sta. 458+95.5	3-11-44
25932	" " " " 488+82 Looking NW	"
25933	Borel Canal Break - Near Sta. 326+35.5	3-11-44
25934	" " " Reinforcing in place & guniting	"
25935	Borel - Tractor with Sheepfoot Roller Jamming	3-11-44
25936	San Joaquin River - New gaging station	3-11-43
25937	" " " " "	"
25938	" " " " "	"
25939	" " " " "	"
25940	L. B. St. Pl. Unit 8 R Condenser, South tube sheet	2-1-44
25939	" " " " "	"
25940	L. B. St. Pl. Unit 8 R Condenser, South tube sheet	3-13-44
25941	" " " " " West half upper quarter	"
25942	" " " " " East half lower quarter	3-14-44
25943	" " " " " Upper quarter	"
25944	" " " " " " "	"
25945	Htg. Pittman-Shaver-Pitman Cr. at Diversion Dam	3-19-43
25946	" " " " 68" Snow at Gage	"
25947	Big Creek Below Htg. Lake - Gage Height 1.17	"
25948	Florence Lake - Kaiser and Sno motor	3-21-44
25949	" " " Dam River Section showing snow drifts in Arches	3-22-44
25950	" " " " Butress #17	"
25951	" " " " Arch #53	3-23-44
25952	" " " " Haunch bet. Arches 12 & 13	"
25953	" " " " Arch 53,	"
25954	" " " " Chipping Arch #9 for Asbestos membrane	"







296

Small films

26001	B.C. 220KV. line - Damage caused by gas line failure	11-7-43
26002	" " " " " " " "	"
26003	" " " " " " " "	"
26004	" " " " " " " "	"
26005	" " " " " " " "	"
26006	Borel Flume. Looking downstream of canal section at site of proposed diversion outlet	5-10-44
26007	" " Looking upstream at the site of the proposed diversion outlet.	5-10-44
26008	" " Upstream side of Kern River flume showing location of proposed diversion gates and channel	5-10-44
26009	Transformer - Faulty 10KVA 3 $\phi$ Malony Transf. 12000-240/480 Visalia Dist.	5-18-44
26010	" " " " " " " "	"
26011	" " " " " " " "	"
26012	" " " " " " " "	"
26013	" " " " " " " "	"
26012	" " " " " " " "	"
26013	" " " " " " " "	"
26014	" " " " " " " "	"
26015	" " " " " " " "	"
26016	" " " " " " " "	"
26017	L.B.S.P. #2 Unit 8R Condenser. Upper N.E. 1/4 of tube sheet showing disintegration, Debecote and rusting of the tube sheet.	5-7-44
26018	L.B.S.P. #2 Unit 8R Condenser. Upper S.E. 1/4 of tube sheet.	5-7-44
26019	L.B.S.P. Unit 8R Condenser. Lower S.W. 1/4. Debecote on sheet and in tube ends. Typical blistering, rusting and pitting.	5-7-44
26020	L.B.S.P. #2 Unit 8R Condenser. Lower S.E. 1/4 showing small areas where both tubes and sheet are coated with Ferro-Prime B. and Amersote.	5-7-44
26021	Big Creek Gen. Lower end of Crater Creek diversion	5-17-44
26022	" " Lang and Bartholomew gaging Hooper Cr. at new recorder	Flow. 17.2 sec. ft. 5-19-44
26023	" " Hooper Creek at lower end of rock canyon about elev. 7450	5-18-44
26024	Bear Cr. main trail on south side of Bear ridge. Arnold shell, packer and gaging station supplies for upper Bear Creek stations.	5-20-44
26025	" " Arnold shell & pack train enroute to Hilgard Camp. Note crusty snow on trail	5-23-44
26026	" " Hilgard Camp at site of gaging station	5-24-44
26027	Big Cr. Gen. Packing recorder equipment into Hooper Creek.	5-18-44

297

26028	Big Creek Gen. Lunch on Crater Creek. Lang, Barber, Hansen.	5-17-44
26029	Bear Cr. Highlakes Looking down Hilgard and across Bear Creek from Elev. 9800	5-22-44
26030	" " Looking North on Bear Creek from near the Rose Marie gaging station	5-21-44
26031	" " Looking down Hilgard from El. 9900. Note easy road location	5-22-44
26032	Big Cr. Gen. Crater Creek diversion. Ledge rock near middle of the ditch	5-17-44
26033	" " Hooper Creek at about Elev. 7450	5-18-44
26034	" " Looking down Hooper Creek from about Elev. 7550	5-18-44
26035	" " Typical smooth rock and earth road location 1/4 mile below Kips	5-25-44
26036	" " Original Crater Creek diversion dam.	5-17-44
26037	" " " " " " " "	"
26038	" " Looking down Hooper Creek from about Elev. 7550	5-18-44
26039	Bear Cr. Highlakes Falls on Bear Creek 3 1/2 miles above Bear Dam. Tough road	location in this area 5-25-44
26040	" " Hilgard Cr. to Hooper Cr. from about elev. 9350	5-18-44
26039	Bear Cr. Highlakes Falls on Bear Creek 3 1/2 miles above Bear Dam. Tough road	location in this area 5-25-44
26040	" " Hilgard Creek El. 9800 Rough portion road location	5-22-44
26041	" " Looking down Hilgard from El. 10,000	5-22-44
26042	Big Cr. Gen. Upper End of Hooper Creek from about El. 7400	5-18-44
26043	Bear Cr. Upper rocky portion of Crater Creek diversion during snowstorm.	Flow about 6 sec. ft. 5-17-44
26044	Bear Cr. Highlakes Looking up the east fork of Bear Creek	5-21-44
26045	" " Looking up Hilgard Creek from near gaging station	5-24-44
26046	" " Mt. Hooper from near gaging station on Rose Marie Cr. at El. 10,000	5-21-44
26047	" " Upper Bear Creek and Seven Gables from the top of Bear Ridge on the Main Trail	5-20-44
26048	" " Seven Gables, from upper Bear Creek	5-21-44
26049	" " Mountain south of Hilgard Creek 1 mile above mouth	5-22-44
26050	" " Bear Creek 1 mile below Kips camp.	5-25-44
26051	Big Cr. Gen. Original 12" Crater Creek diversion pipe.	5-17-44
26052	" " Hooper Creek at confluence with lower fork	5-18-44
26053	" " Lower end of partially completed Crater Creek diversion channel. Flow about 6 sec. ft.	5-17-44
26054	Bear Cr. Highlakes Differential weathering of coarse crystals in a dyke on	



26055	Bear Cr. Highlakes	
26056	Big Creek Dam. Looking up Hilgard from El. 10,000.	5-22-44
26057	" " " Seven Tables from Rose-Marie gaging station.	5-21-44
26058	" " " Upper Hilgard from El. 10,100 ft. looking up road location to El. 10,600	5-22-44
26059	" " " Seven Tables from near Rose-Marie gaging station.	5-21-44
26060	Big Cr. Dam Excavating the upper end of Crater Creek diversion	5-26-44
26061	Vermilion Valley " Vermilion damsite - looking west along east leg	5-27-44
26062	" " " Excavating the middle portion of Crater Creek diversion.	5-26-44
26063	Big Creek Trans. Line. Caisson Installation at Mile 205 Tower 6 and Mile 206 Tower 1	
26064	" Castaic Creek. Pacific Crane & Rigging Co.	April & May 1944
26065	" " " "	"
26066	" " " "	"
26067	" " " "	"
26068	" " " "	"
26067	" " " "	"
26068	" " " "	"
26069	" " " "	"
26070	" " " "	"
26071	" " " "	"
26072	" " " "	"
26073	" " " "	"
26074	" " " "	"
26075	" " " "	"
26076	" " " "	"
26077	" " " "	"
26078	" " " "	"
26079	" " " "	"
26080	" " " "	"
26081	" " " "	"

26082	" " " "	"
26083	" " " "	"
26084	" " " "	"
26085	" " " "	"
26086	" " " "	"
26087	" " " "	"
26088	" " " "	"
26089	" " " "	"
26090	" " " "	"
26091	" " " "	"
26092	" " " "	"
26093	" " " "	"
26094	" " " "	"
26095	" " " "	"
26096	" " " "	"
26097	Bear Cr. Highlakes	5-27-44
26098	Big Creek Dam. Rose-Marie Creek & Mt. Hooper. View from site of gaging station El. 10,000 ft.	5-21-44
26099	" " " Looking across Bear Creek Canyon from Bear Ridge trail	5-21-44
26100	" " " East Fork at Bear Creek and spur of Seven Tables.	5-21-44
	" " " Seven Tables	5-21-44

300

26101	Bear Cr. Highlakes Big Creek Res.	Seven Tables	5-21-44
26102	"	Looking up Bear Creek Basin from Bear Ridge Elev. 9750' Hilgard Creek and Seven Tables, left center	5-20-44
26103	"	Looking up East Fork Bear Creek from Hill below Rose Marie Cr.	5-21-44
26104	"	Looking up East Fork of Bear Creek	5-21-44
26105	"	Kips Camp on Bear Creek - About 10 miles from Mono Dam.	5-22-44
26106	"	" " " " " " " " " "	"
26107	"	Seven Tables (R.H. Spencer in foreground)	5-21-44
26108	"	Pack train between Kips Camp and Hilgard Camp.	5-23-44
26109	"	" " " " on trail " " " " " " " " " "	5-23-44
26110	"	" " " " on switchbacks between Bear Ridge & Bear Cr.	5-20-44
26111	"	Arnold Shell, Packer, on trail between Kips Camp and Hilgard Creek gaging station.	5-23-44
26112	"	Kips camp on Bear Creek	5-21-44
26111	"	Arnold Shell, Packer, on trail between Kips Camp and Hilgard Creek gaging station.	5-23-44
26112	"	Kips camp on Bear Creek	5-21-44
26113	"	" " " " " " " " " "	"
26114	"	R.H. Spencer at site of Rose-Marie Gaging Sta. Elev. 10,000'	5-21-44
26115	"	H.A. Lang " " " " " " " " " "	"
26116	"	Tent Camp on Hilgard Creek near Gaging Sta.	5-24-44
26117	"	" " " " " " " " " "	"
26118	"	Mr. Houston on trail to Lake Italy.	8-14-44
26119	"	Big Creek Res. Rose-Marie Cr. gaging sta. on upper Bear Cr. Elev. 10,000'	5-28-44
26120	"	Merle Bartholomew, H.A. Lang, Martin Boss	5-29-44
26121	"	Gaging Sta. on Rose-Marie Cr. near Bear Cr. Elev. 10,000'	5-28-44
26122	"	Hilgard Cr. gaging sta. on upper Bear Cr. Elev. 9,500'	5-28-44
26123	"	" " " " " " " " " "	5-28-44
26124	"	" " " " " " " " " "	"
26125	Kern River No. 3.	Before churning tunnel mouth	6-11-44
26126	"	After " " " " " " " " " "	"
26127	"	Inspecting tunnel wall.	"